# FIRE DOOR SURVEY



# Lenton Business Centre, Lenton Boulevard, Nottingham NG7 2BZ

| ASSESSED BY<br>ASSESSED ON | David Shields<br>22/01/2025 |
|----------------------------|-----------------------------|
| APPROVED BY<br>APPROVED ON | Mark Clayton<br>05/02/2025  |
| ASSESSMENT REF.            | RB-U8LT5M                   |
| RECOMMENDED<br>REVIEW DATE | 22/01/2026                  |
| VERSION                    | 1                           |



Veteran Fire Safety Ltd Rawa House, Whitwick Road, Coalville, LE67 3FA 01530 588 189 • www.veteranfiresafety.co.uk

### **SUMMARY** 1

## Fire Door Survey

ASSESSMENT AND CERTIFICATE REFERENCE RB-U8LT5M

ASSESSED ON, BY 22/01/2025, David Shields

APPROVED / VALIDATED ON, BY 05/02/2025, Mark Clayton GIFireE MIFSM MIFPO

RECOMMENDED REVIEW DATE 22/01/2026

FINDINGS 440 Actions PRODUCED FOR THE RESPONSIBLE PERSON Veteran Fire Safety Ltd

SPECIFICATION CONFORMS TO Our own internal quality system.

ASSESSMENT SCOPE Assessment applies only to the building specified.

### **Assessed Property**

PROPERTY NAME Lenton Business Centre, Lenton Boulevard, Nottingham NG7 2BZ

PROPERTY REFERENCE **RB-EPKAUY** 

ASSESSING ORGANISATION Veteran Fire Safety Ltd Rawa House, Whitwick Road, Coalville, LE67 3FA 01530 588 189 — www.veteranfiresafety.co.uk

Veteran Fire

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 2 370



ADDRESS



### **Assessor Remarks**

#### Nottingham City Council.

Lenton Business Park Fire Door Inspection.

#### LBC1 BUILDING

#### Fire Door Certification:

A small number of doors were found to have BWF Certifire labels fixed to the top of the door leaves that gives some assurance regarding test evidence for the doors. Unfortunately these doors have been installed with just two hinges resulting in them being non compliant. These doors can have remedial works done to bring them into compliance and re-inspected to confirm. The balance of the doors show no evidence of certification. On circulation routes the door leaves are solid core so could be classed as notional fire doors, however they are showing deterioration from years of use and any rectification would be time consuming

and would need to be carried out by specialist contractors with BWF Certifire or BM Trada accreditation. Doors off circulation routes

were found to be hollow core non fire rated door leaves with no certification.

#### Intumescent & smoke seals:

Intumescent seals with no smoke seal are fitted in most locations, these have been over painted on a number of occasions and cannot be classed as functional. The intumescent strips have been incorrectly fitted and are broken by the hinge and lock case footprint.

#### Hinges:

The majority of the existing hinges are steel cranked butt hinges that do not comply with modern fire safety regulations being BS EN 1935 Class 7 rated, the requirement for fire doors is class 11 or 13.

#### Door controls:

Door closers are from a variety of manufacturing sources predating CE / UKCA marking and declaration of performance requirements. A large number are leaking hydraulic oil and should be replaced, the balance do not close in a controlled manor and should be adjusted. If adjustment fails they too should be replaced. Replacements door closer units should be compliant to BS EN1154 with adjustable power size 2 to 4.

On pairs of corridor doors the meeting stiles are rebated and are fitted with door selectors to ensure the doors close in the right sequence, only one door selector was found to be operational, the rest are damaged beyond repair and do not function correctly. Images are attached to the report demonstrating this issue. Rebated meeting stiles on pairs of fire doors are no longer the right solution as the rebate actually reduces the fire resisting material by 50% on the meeting stile. The best practice solution would be to replace these doors with new door sets with plain meeting stiles and intumescent and smoke seals fitted to the frame jabs and the leading edge of the active leaf.

#### Hold open units:

In some locations the doors are held open with battery powered sonic hold open units engaging at floor level. Releasing these doors on a daily basis is essential to maintain the valves and seals in the door closers and to prevent the door leaf from twisting due to the closer applying closing force at the top of the door and the holder stopping the door at the bottom. Best practice would be to disengage the hold open units at close of business hours every night.

#### Locking systems:

Generally these are old British standard locks with brass latch and deadbolts that predate the requirements of BS EN 12209 and are not supported by CE marking.

In some locations mechanical digital locks have been added to door leaves, these products have zinc alloy bodies and are not suitable for fire doors.

Magnetic locks have been added for access control purposes, the fixing bolt for the magnet armature plate pass through the door leaf, negating any fire certification that was available when the door leaves were manufactured.

#### Howard Building:

Ground floor office doors (Offices 1 to 4) are timber doors in aluminium frames and cannot be classed as fire doors.

In some areas door leaves have been replaced with 44mm door cores fitted into existing frames. These are non-compliant as the frames were made to suit 38mm thick door leaves. Examples of this can be seen on the first-floor reception atrium cleaners and CCTV rooms.

'V' prefix offices on the ground floor are original panelled doors that have been covered over with fibre board making them non fire rated and not certifiable. There are some replacement solid core doors in place that have no certification labels fitted into existing frames.



T prefix office units on the first floor are flush oak veneered in painted frames. Images on the report show that these doors were once electrically operated with some form of access control device. The doors are now mechanical locking and the wire ways for the previous system are still in place, the door surfaces have large lever handle back plates which probably cover the machining holes for the previous system. The door frames have been repaired with an aluminium fillet plate behind the lock strike to cover the holes. The angle of the fillet plate / lock strike prevents the latch bolt from engaging and doors not closing correctly. Suite V18 on the second floor is the best example where the power loop in the frame has been totally removed and leaving the cable way in the door leaf exposed.

#### Additional suggestions:

#### Acoustic enhancement (Building Regulations Document E)

In some business units there are confidential matters being discussed, if the existing doors are being replaced with new fire doors , these could be enhanced for acoustic performance and provide the users with assurances on privacy and confidentiality.

#### **Equality Act**

If doors are replaced other considerations other than fire safety are relevant, such as Building Regulations Document M and BS8300. Clear zones of vision between 500 to 1500 from ffl should be adopted for vision panels plus issues such as ironmongery compliance, clear opening widths, door opening forces and door contrasts / light reflective values.





# **2** FIRE DOORS

| IMAGE      | ID          |       | LOCATION                               | FIRE RATING | ACTIONS   |
|------------|-------------|-------|--|-------------|-----------|
| See. 1     | RB-2F       | S1UN  | Basement. Chemical store               | FD30        | 1 Action  |
|            | 2<br>RB-KT  | SC4U  | Basement. Corridor near<br>to unit BM5 | FD30        | 1 Action  |
|            | 3<br>RB-PJ  | GGE7  | Basement. Escape lobby<br>door         | FD30        | 6 Actions |
| 100 I.I.I. | 4<br>RB-MI  | UGB2W | Basement. Lift machinery               | FD30        | 1 Action  |
|            | s<br>RB-M   | 1P5E6 | Basement. Meter room                   | FD30        | 1 Action  |
|            | 6<br>RB-L5  | NNXW  | Basement. Rear workshop<br># 2         | FD30        | 6 Actions |
|            | 7<br>RB-FK  | F33E  | Basement. Rear workshop                | FD30        | 1 Action  |
|            | 8<br>RB-CF  | M2DV  | Basement. Restricted<br>access door #2 | FD30        | 1 Action  |
| 5.m        | 9<br>RB-D\  | /9HIX | Basement. Restricted<br>access door #3 | FD30        | 1 Action  |
|            | 10<br>RB-68 | TD97  | Basement. Restricted<br>access door    | FD30        | 1 Action  |



|    | RB-GL2VRK | Basement. Store next to female wc | FD30      | 1 Action   |
|----|-----------|-----------------------------------|-----------|------------|
|    | RB-NYCKVW | Basement. Store next to male wc   | FD30      | 1 Action   |
| 13 | RB-9ZN8AS | Basement. Unit 7                  | FD30      | 1 Action   |
| 14 | RB-J4UUYW | Basement. Unit 8                  | FD30      | 1 Action   |
| 15 | RB-SY5BVL | Basement. Unit 9A                 | FD30      | 1 Action   |
| 16 | RB-3367EB | Basement. Unit 9B                 | FD30      | 1 Action   |
| 17 | RB-7VBAHW | Basement. Unit BM5                | FD30      | 1 Action   |
| 18 | RB-DRT368 | GF. 57 Suite                      | FD30      | No Actions |
| 19 | RB-78MCHD | GF. Basement stair lobby          | FD30      | 1 Action   |
| 20 | RB-SJWVTA | GF. Cleaners cupboard             | FD30      | 1 Action   |
| 21 | RB-4CRAI4 | GF. Comms Room                    | Not Rated | 1 Action   |



| 222 | RB-AR48PJ | GF. Corridor                           | FD30 | 1 Action  |
|-----|-----------|--|------|-----------|
| 23  | RB-A57JCK | GF. Corridor / stair lobby             | FD30 | 6 Actions |
| 24  | RB-7BQ6P4 | GF. Corridor lobby                     | FD30 | 1 Action  |
| 25  | RB-53DQQM | GF. Corridor lobby                     | FD30 | 1 Action  |
| 26  | RB-JRZGWA | GF. Corridor lobby                     | FD30 | 7 Actions |
| 27  | RB-SC1QF3 | GF. Corridor lobby next to<br>unit 27a | FD30 | 2 Actions |
| 28  | RB-4Y6J1S | GF. Corridor near to unit<br>48        | FD30 | 6 Actions |
| 29  | RB-PCXWMV | GF. Corridor next to unit<br>15        | FD30 | 7 Actions |
| 30  | RB-CZY9S1 | GF. Corridor next to unit<br>18        | FD30 | 7 Actions |
| 31  | RB-9NGMW8 | GF. Corridor next to unit<br>19        | FD30 | 7 Actions |
| 32  | RB-3JXMUG | GF. Corridor next to unit<br>23        | FD30 | 8 Actions |



| 33      | RB-TYV5EP | GF. Corridor next to unit<br>47 | FD30      | 6 Actions |
|---------|-----------|---------------------------------|-----------|-----------|
| 34      | RB-DFYUN4 | GF. Corridor to goods lift      | FD30      | 1 Action  |
| 35      | RB-WTG24P | GF. Electrical panel            | Not Rated | 1 Action  |
| 36      | RB-DY4BED | GF. Electric cupboard           | FD30      | 1 Action  |
| 37<br>A | RB-4FAFCU | GF. Exit lobby doors            | Not Rated | 7 Actions |
| . 38    | RB-L3UT9D | GF. Female WC                   | FD30      | 6 Actions |
| 39      | RB-BBUKQ6 | GF. Goods lift lobby            | FD30      | 1 Action  |
|         | RB-2PHDZC | GF. Howard Building             | Not Rated | 1 Action  |
| 41      | RB-3QAK7I | GF. Howard Building             | FD30      | 1 Action  |
| 42      | RB-4WCGQ6 | GF. Howard Building             |           | 1 Action  |
| 43      | RB-5MWD9X | Gf. Howard Building             | FD30      | 1 Action  |



| 44 | RB-8V34BM | GF. Howard Building | FD30      | 5 Actions  |
|----|-----------|---------------------|-----------|------------|
| 45 | RB-9CJ52S | GF. Howard Building |           | 1 Action   |
| 46 | RB-9DKYW5 | GF. Howard Building | Not Rated | 1 Action   |
| 47 | RB-9VKZCK | GF. Howard Building |           | 1 Action   |
| 48 | RB-72EBBR | GF. Howard Building | Not Rated | 1 Action   |
| 49 | RB-72SMJ6 | GF. Howard Building | FD30      | 2 Actions  |
| 50 | RB-ABA3NQ | GF. Howard Building | FD30      | 7 Actions  |
| 51 | RB-AP5BJW | GF. Howard Building | FD30      | 5 Actions  |
| 52 | RB-BX49NR | GF. Howard Building | FD30      | No Actions |
| 53 | RB-ESVT97 | GF. Howard Building | FD30      | 6 Actions  |
| 54 | RB-FQ56JD | GF. Howard Building | FD30      | 6 Actions  |



| 55           | RB-GK57N1 | GF. Howard Building | FD30      | 1 Action   |
|--------------|-----------|---------------------|-----------|------------|
| 56           | RB-H2YEU2 | GF. Howard Building |           | 1 Action   |
| 57           | RB-HVHKZH | GF. Howard Building | FD30      | 7 Actions  |
| 58           | RB-INVS8R | GF. Howard Building |           | No Actions |
| 59           | RB-J6RSA7 | GF. Howard Building |           | 1 Action   |
| 60           | RB-JNY8RK | GF. Howard Building | Not Rated | 1 Action   |
| 61<br>4<br>4 | RB-JPS8JW | GF. Howard Building | FD30      | 1 Action   |
| 62           | RB-KRNXIE | GF. Howard Building | FD30      | 1 Action   |
| 63           | RB-KXKXR4 | GF. Howard Building |           | 1 Action   |
| 64           | RB-L4XTPK | GF. Howard Building |           | 2 Actions  |
| 65           | RB-MYTV28 | GF. Howard Building |           | 1 Action   |



| 66        | RB-NEPL5S | GF. Howard Building | FD30      | 1 Action  |
|-----------|-----------|---------------------|-----------|-----------|
| 67        | RB-NL5VST | GF. Howard Building | FD30      | 6 Actions |
| 68        | RB-P3GWYN | GF. Howard Building | FD30      | 1 Action  |
| 69        | RB-PFNULF | GF. Howard Building |           | 1 Action  |
| * 70<br>* | RB-QWSMXS | GF. Howard Building | FD30      | 3 Actions |
| 71        | RB-RCZR6Q | GF. Howard Building | FD30      | 1 Action  |
| 72        | RB-SQWDQ7 | GF. Howard Building | FD30      | 5 Actions |
| 73        | RB-UDMK9Q | GF. Howard Building | FD30      | 1 Action  |
| 74        | RB-VMJ3MB | GF. Howard Building | FD30      | 6 Actions |
| 75        | RB-WKRB86 | GF. Howard Building | FD30      | 1 Action  |
| 76        | RB-XWDYWQ | GF. Howard Building | Not Rated | 1 Action  |



| 77       | RB-Y18LFE | GF. Howard Building      |           | 1 Action   |
|----------|-----------|--------------------------|-----------|------------|
| 78       | RB-Y66BKF | GF. Howard Building      | Not Rated | 1 Action   |
| 79<br>89 | RB-Z932V9 | GF. Howard Building      | FD30      | 1 Action   |
| 80       | RB-9KTZBJ | GF. Kitchen              | FD30      | 6 Actions  |
| 81       | RB-DB1BKP | GF. Kitchen              | Not Rated | 1 Action   |
| 82       | RB-37DAH3 | GF. Male WC              | FD30      | 5 Actions  |
| 83       | RB-YQU55W | GF. Meeting Room 1       | FD30      | No Actions |
| 84       | RB-DTZVLV | GF. Patra                | FD30      | No Actions |
| 85       | RB-Q2XDJJ | GF. Patra Corridor Lobby | FD30      | 6 Actions  |
| 86       | RB-PE7PS4 | GF. Patra ITSuite        | FD30      | No Actions |
| 87       | RB-G8Z1TF | GF. Patra interview      | Not Rated | 1 Action   |



| 88        | RB-HEUGL8 | GF. Stair lobby #14       | FD30      | 1 Action   |
|-----------|-----------|---------------------------|-----------|------------|
| 89        | RB-SNGHXD | GF. Stair lobby           | FD30      | 1 Action   |
| 90        | RB-4RX459 | GF. Store / Void          | FD30      | 1 Action   |
| 91        | RB-Q8B2LD | GF. Store next to unit 38 | Not Rated | 1 Action   |
| 92        | RB-ZHJ6V9 | GF. Unit 1                | Not Rated | 2 Actions  |
| 93        | RB-BG3AZG | GF. Unit 2                | Not Rated | 1 Action   |
| <b>94</b> | RB-KIZXVC | GF. Unit 3                | Not Rated | 1 Action   |
| 95        | RB-9KNZZH | GF. Unit 4                | Not Rated | 1 Action   |
| 96        | RB-KK2AQB | GF. Unit 5                | Not Rated | 1 Action   |
| 97        | RB-QXEAJ1 | GF. Unit 6                | Not Rated | 2 Actions  |
| 98        | RB-V1W9BS | GF. Unit 10               | FD30      | No Actions |



| 99         | RB-MYHIJL | GF. Unit 11 | FD30      | No Actions |
|------------|-----------|-------------|-----------|------------|
| 100        | RB-Z5VIT9 | GF. Unit 12 | FD30      | No Actions |
| 101        | RB-6STZGB | GF. Unit 13 | Not Rated | 1 Action   |
| <b>102</b> | RB-T8HW6R | GF. Unit 14 | FD30      | No Actions |
| 103        | RB-ALV967 | GF. Unit 15 | Not Rated | 1 Action   |
| 104        | RB-U5UZU4 | GF. Unit 16 | Not Rated | 2 Actions  |
| 105        | RB-DEUWJF | GF. Unit 17 | Not Rated | 2 Actions  |
| 106        | RB-DLBK91 | GF. Unit 18 | Not Rated | 2 Actions  |
| 107        | RB-5ARPDA | GF. Unit 19 | Not Rated | 2 Actions  |
| 108        | RB-NY5RCM | GF. Unit 20 | Not Rated | 2 Actions  |
| 109        | RB-TX18J6 | GF. Unit 21 | Not Rated | 1 Action   |



| 110 | RB-19H8ZU | GF. Unit 22  | Not Rated | 1 Action   |
|-----|-----------|--------------|-----------|------------|
| 111 | RB-AZI9NN | GF. Unit 23  | Not Rated | 2 Actions  |
| 112 | RB-JPZS5D | GF. Unit 24  | Not Rated | 2 Actions  |
| 113 | RB-TT1BSB | GF. Unit 25  | Not Rated | 2 Actions  |
| 114 | RB-HHN85J | GF. Unit 26  | Not Rated | 2 Actions  |
| 115 | RB-NSW7IE | GF. Unit 27  | Not Rated | 1 Action   |
| 116 | RB-VUZ8YP | GF. Unit 27a | Not Rated | 1 Action   |
|     | RB-IKQKHD | GF. Unit 29  | Not Rated | 1 Action   |
| 118 | RB-26HCY2 | GF. Unit 30  | FD30      | 2 Actions  |
| 119 | RB-UXZU7D | GF. Unit 31  | FD30      | 2 Actions  |
| 120 | RB-JNAPUI | GF. Unit 32  | FD30      | No Actions |



| 121 | RB-ZF8X6P | GF. Unit 33      | FD30      | 1 Action |
|-----|-----------|------------------|-----------|----------|
| 122 | RB-ETVB2I | GF. Unit 34      | FD30      | 1 Action |
| 123 | RB-I7QXFQ | GF. Unit 35 / 01 | Not Rated | 1 Action |
| 124 | RB-CW536F | GF. Unit 35      | Not Rated | 1 Action |
| 125 | RB-IQM8RF | GF. Unit 36      | Not Rated | 1 Action |
| 126 | RB-ZNZVWR | GF. Unit 37      | Not Rated | 1 Action |
| 127 | RB-YL926L | GF. Unit 38      | Not Rated | 1 Action |
| 128 | RB-V35D7F | GF. Unit 40      | Not Rated | 1 Action |
| 129 | RB-RFPMJH | GF. Unit 41      | Not Rated | 1 Action |
| 130 | RB-8GS9EM | GF. Unit 42      | Not Rated | 1 Action |
| 131 | RB-YCEKDM | GF. Unit 43      | Not Rated | 1 Action |





| 132 | RB-FLC2UR | GF. Unit 44 | Not Rated | 1 Action  |
|-----|-----------|-------------|-----------|-----------|
| 133 | RB-FJ8R7A | GF. Unit 45 | Not Rated | 1 Action  |
| 134 | RB-1LTJVG | GF. Unit 46 | Not Rated | 1 Action  |
| 135 | RB-C5Z7QX | GF. Unit 47 | Not Rated | 1 Action  |
| 136 | RB-6M1EDY | GF. Unit 48 | Not Rated | 1 Action  |
| 137 | RB-NNI1DK | GF. Unit 50 | Not Rated | 1 Action  |
| 138 | RB-Z6QVYC | GF. Unit 50 | Not Rated | 1 Action  |
| 139 | RB-RA4KPH | GF. Unit 51 | Not Rated | 1 Action  |
| 140 | RB-TB6HD7 | GF. Unit 52 | FD30      | 2 Actions |
| 141 | RB-QDQ9R3 | GF. Unit 53 | FD30      | 6 Actions |
| 142 | RB-MNQKSS | GF. Unit 54 | FD30      | 4 Actions |



| 143 | RB-59QWP5 | GF. Unit 55                     | FD30      | 1 Action  |
|-----|-----------|---------------------------------|-----------|-----------|
| 144 | RB-E6EE7R | GF. Unit 56                     | FD30      | 4 Actions |
| 145 | RB-IS5WZ5 | GF. Void door - Patra           | Not Rated | 1 Action  |
| 146 | RB-3E3PHK | Ground. Howard Building         | FD30      | 5 Actions |
| 147 | RB-CZACXD | Ground. Howard Building         | FD30      | 5 Actions |
| 148 | RB-EXID89 | Ground. Howard Building         | FD30      | 5 Actions |
| 149 | RB-G366XR | Ground. Howard Building         | FD30      | 1 Action  |
| 150 | RB-RVRETR | Ground. Howard Building         | FD30      | 6 Actions |
| 151 | RB-SSU5VQ | Ground. Howard Building         | FD30      | 7 Actions |
| 152 | RB-TKJLLH | Ground. Howard Building         | FD30      | 5 Actions |
| 153 | RB-2H5NBL | First floor. Howard<br>Building | FD30      | 7 Actions |



| 154 | RB-2VNJ9V | First floor. Howard<br>Building | FD30 | 1 Action  |
|-----|-----------|---------------------------------|------|-----------|
| 155 | RB-3BT7KS | First floor. Howard<br>Building | FD30 | 1 Action  |
| 156 | RB-4FU1H8 | First floor. Howard<br>Building | FD30 | 1 Action  |
| 157 | RB-7CY73Z | First floor. Howard<br>Building | FD30 | 1 Action  |
| 158 | RB-8IKCET | First floor. Howard<br>Building | FD30 | 1 Action  |
| 159 | RB-9EN3B8 | First floor. Howard<br>Building | FD30 | 5 Actions |
| 160 | RB-9SR5PD | First floor. Howard<br>Building | FD30 | 1 Action  |
| 161 | RB-9ZUWI7 | First floor. Howard<br>Building | FD30 | 6 Actions |
| 162 | RB-468GQH | First floor. Howard<br>Building | FD30 | 6 Actions |
| 163 | RB-BAI8Z6 | First floor. Howard<br>Building | FD30 | 7 Actions |
| 164 | RB-D7CUPT | First floor. Howard<br>Building | FD30 | 8 Actions |





| 165 | RB-DGAH7G | First floor. Howard<br>Building | FD30 | 1 Action  |
|-----|-----------|---------------------------------|------|-----------|
| 166 | RB-DP9XRM | First floor. Howard<br>Building | FD30 | 1 Action  |
| 167 | RB-DVCJM6 | First floor. Howard<br>Building | FD30 | 4 Actions |
| 168 | RB-EKGWZ6 | First. Howard Building          | FD30 | 6 Actions |
|     | RB-FTZ3EB | First floor. Howard<br>Building | FD30 | 6 Actions |
| 170 | RB-L84BB4 | First floor. Howard<br>Building | FD30 | 1 Action  |
| 171 | RB-LRRGE8 | First floor. Howard<br>Building | FD30 | 1 Action  |
| 172 | RB-LVG171 | First floor. Howard<br>Building | FD30 | 1 Action  |
| 173 | RB-MBQMJK | First. Howard Building          | FD30 | 1 Action  |
| 174 | RB-NCC6RL | First floor. Howard<br>Building | FD30 | 1 Action  |
| 175 | RB-Q99RL7 | First floor. Howard<br>Building | FD30 | 7 Actions |



| 176 | RB-WSTDT3 | First floor. Howard<br>Building  | FD30 | 5 Actions |
|-----|-----------|----------------------------------|------|-----------|
| 177 | RB-XDG12G | First floor. Howard<br>Building  | FD30 | 1 Action  |
| 178 | RB-XSJL8M | First floor. Howard<br>Building  | FD30 | 6 Actions |
| 179 | RB-Y4ZDXA | First. Howard Building           | FD30 | 1 Action  |
| 180 | RB-MYQB29 | Second floor. Howard<br>Building | FD30 | 7 Actions |
| 181 | RB-PZSHGC | Second floor. Howard<br>Building | FD30 | 7 Actions |
| 182 | RB-UR51QI | Second floor. Howard<br>Building | FD30 | 7 Actions |
| 183 | RB-X6Y1YG | Second floor. Howard<br>Building | FD30 | 8 Actions |



## Fire Door RB-2FS1UN 🛛 🕫 FD30



Floor / Location Basement / Chemical store

**1** Action



**Fire Resistance** 

FD30

ltem

Fire Door

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish


Frame Finish Paint Finish

Leaf Vision Panels No

Gaps Head 6mm Hinge 1 Meeting Hinge 2 4mm 7mm 3mm Threshold 13mm

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



| Inspection Type   | LIMITED, OCCUPANT DID NOT<br>Answer |
|---|-------------------------------------|
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door survey. | NO TIMESCALE                        |
| REFERENCE RB-DHEHYL DUE No Due Date   | NO SEVERITY                         |







Item Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No



Floor / Location Basement / Corridor near to unit BM5

Intumescent & Smoke Seals Intumescent Only


Self-Closing Devices Overhead

**1** Action

**Electrical Hold Open Device** Yes

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



FULL ACCESS **Inspection Type Fire Door Condition** X The leaf and frame are adequately specified Replace door with FD30s rated fire door. **NO TIMESCALE** The door is not fit for purpose - 38mm hollow. REFERENCE RB-U96ZMD DUE No Due Date **NO SEVERITY** 







Floor / Location

6 Actions

ltem Fire Door


**Fire Resistance** FD30

Certification None

Leaf Finish Metal Finish

Frame Finish Paint Finish

Leaf Vision Panels No




Intumescent & Smoke Seals Intumescent Only

Basement / Escape lobby door

Self-Closing Devices Overhead

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



| Inspection Type   | FULL ACCESS         |
|---|---------------------|
| <ul> <li>Fire Door Condition</li> <li>The leaf and frame are adequately specified</li> <li>There is no damage significant enough to affect the fire integrity of the leaf or frame</li> <li>Gaps around the frame are within tolerance (and/or manufacturers guidelines)</li> <li>Seals are undamaged and well fitted / continuous around the whole leaf or frame</li> <li>Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws pre</li> <li>An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)</li> <li>When closed, the leaf sits against a securely installed stop without distortion</li> <li>Fire door signage correctly identifies door operation and is securely attached</li> </ul> | sent                |
| Replace hinges with BS EN standard fire door hinges.  | TIMESCALE           |
| All fire doors are required to have 3 hinges, which must be fire certified.   | SHORT TERM          |
| REFERENCE RB-STMDKA DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Replace door with FD30s rated fire door.  | TIMESCALE           |
| The door is not fit for purpose steel clad timber door core, no certification.  | SHORT TERM          |
| REFERENCE RB-AYY4JL DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |



| Reduce gaps between the door and the door frame.              | TIMESCALE           |
|---|---------------------|
| To ensure heat and smoke cannot pass through to escape route. | SHORT TERM          |
| REFERENCE <b>RB-3F66Z9</b> DUE 22/04/2025                     | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.                      | TIMESCALE           |
| Seals are damaged or missing in sections of the frame.        | SHORT TERM          |
| REFERENCE RB-1RQ5JF DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Adjust door alignment.  | TIMESCALE           |
| Door gaps exceed safe guidelines.                             | SHORT TERM          |
| REFERENCE RB-33CBDF DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Multiple lock mortices left exposed.<br>Certification.        | NO TIMESCALE        |
| REFERENCE RB-J81Q5K DUE No Due Date                           | NO SEVERITY         |
| 184   |                     |



### Fire Door RB-MUGB2W 🔮 FD30

FD30 1 Action

**ltem** Fire Door

> Fire Resistance FD30

Certification None

Leaf Configuration Double Leaf - Single Acting


Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No

#### Floor / Location Basement / Lift machinery





Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



#### A Additional Photos



#### **Inspection Type**

#### **Fire Door Condition**

X The leaf and frame are adequately specified

#### Replace door with FD30s rated fire door.

The door is not fit for purpose - hollow core, see image.

REFERENCE RB-234A8U DUE No Due Date

LIMITED, OCCUPANT DID NOT ANSWER

NO TIMESCALE

**NO SEVERITY** 



### Fire Door RB-M1P5E6



**Item** Fire Door

Fire Resistance

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance Floor / Location Basement / Meter room




Gaps Head 6mm Hinge 4mm Closing 10mm

Self-Closing Devices Overhead

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



Inspection Type

Have the door fully inspected by a competent person. The assessor had limited access to the door during the routine door survey.

REFERENCE RB-23S1ZN DUE 22/04/2025 CATEGORY Building: Doors LIMITED, OCCUPANT DID NOT ANSWER

> TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION





**Item** Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance



#### A Additional Photos



#### Inspection Type

#### **Fire Door Condition**

- X The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- X Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- $\checkmark$  When closed, the leaf sits against a securely installed stop without distortion
- $\checkmark$  Fire door signage correctly identifies door operation and is securely attached

Floor / Location Basement / Rear workshop # 2

**6** Actions




Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



#### FULL ACCESS

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 28 370

🛛 🔽 Risk Base

| Replace hinges with BS EN standard fire door hinges.                        | TIMESCALE           |
|---|---------------------|
| All fire doors are required to have 3 hinges, which must be fire certified. | SHORT TERM          |
| REFERENCE RB-I7X21V DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Replace door with FD30s rated fire door.                                    | TIMESCALE           |
| The door is not fit for purpose.  | SHORT TERM          |
| REFERENCE RB-7EX3WF DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.                            | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.               | SHORT TERM          |
| REFERENCE RB-SMT2ST DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.                                    | TIMESCALE           |
| Seals are damaged or missing in sections of the frame.                      | <b>SHORT TERM</b>   |
| REFERENCE RB-IRVNN9 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Confirm glazing meets BS EN fire regulations.                               | TIMESCALE           |
| Ensure the integrity of the fire door.                                      | <b>SHORT TERM</b>   |
| REFERENCE RB-MZ2K7B DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust door alignment.  | TIMESCALE           |
| Door gaps exceed safe guidelines.   | SHORT TERM          |
| REFERENCE RB-BA7NNN DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |



### Fire Door RB-FKF33E 🛛 🕫 FD30



Item Fire Door

Fire Resistance FD30

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance

Floor / Location Basement / Rear workshop

**1** Action

Gaps Head 8mm Closing Hinge 2mm 4mm Threshold 12mm

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



**Inspection Type** 

#### **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door.

The door is not fit for purpose - panelled door not solid core.

REFERENCE RB-B1QPJX DUE No Due Date

FULL ACCESS

**NO TIMESCALE NO SEVERITY** 



### Fire Door RB-CFM2DV



Floor / Location

Basement / Restricted access door #2



Fire Resistance FD30

Item

Fire Door

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Gaps Head 6mm Hinge 4mm Closing 7mm

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



Inspection TypeLIMITED, OCCUPANT DID NOT<br/>ANSWERHave the door fully inspected by a competent person.<br/>The assessor had limited access to the door during the routine door survey.TIMESCALE<br/>SHORT TERMREFERENCE RB-YLFPIZ<br/>CATEGORY Building: DoorsSEVERITY<br/>PROPERTY PROTECTION





### Fire Door RB-DV9HIX 🕏 FD30



Floor / Location

**1** Action

Basement / Restricted access door #3



**Risk**Base

**Fire Resistance** FD30

Item

Fire Door

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No


Gaps Head 6mm Hinge Closing 4mm 7mm Threshold 13mm

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



LIMITED, OCCUPANT DID NOT Inspection Type **ANSWER** Have the door fully inspected by a competent person. TIMESCALE SHORT TERM The assessor had limited access to the door during the routine door survey. REFERENCE RB-NHJIAV DUE 22/04/2025 SEVERITY PROPERTY PROTECTION CATEGORY Building: Doors



### Fire Door RB-68TD97 🕏 FD30



Item Fire Door

**Fire Resistance** FD30

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Floor / Location

**1** Action

Basement / Restricted access door



Gaps Head 6mm Hinge 1 Meeting Hinge 2 4mm 7mm 3mm Threshold 13mm

Last Limited Inspection 22/01/2025



LIMITED, OCCUPANT DID NOT Inspection Type **ANSWER** Have the door fully inspected by a competent person. TIMESCALE SHORT TERM The assessor had limited access to the door during the routine door survey. REFERENCE RB-VFUYH7 DUE 22/04/2025 SEVERITY PROPERTY PROTECTION CATEGORY Building: Doors





### Fire Door RB-GL2VRK 🔮 FD30



Item Fire Door

**Fire Resistance** 

FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance



#### A Additional Photos



#### Inspection Type

#### **Fire Door Condition** × The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose panelled/ louvered door, no certification.

REFERENCE RB-EITCSJ DUE No Due Date

Basement / Store next to female wc

Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

**1** Action

Floor / Location

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection





## **NO TIMESCALE**

LIMITED, OCCUPANT DID NOT

ANSWER

**NO SEVERITY** 



### Fire Door RB-NYCKVW 🛛 🕫 FD30



Floor / Location

Basement / Store next to male wc

Item

Fire Door

**Fire Resistance** FD30

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance Gaps Head 10mm Hinge Closing 5mm 4mm Threshold 10mm

Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead



#### **Inspection Type**

#### **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm hollow.

REFERENCE RB-U8KBKX DUE No Due Date

LIMITED ACCESS

**NO TIMESCALE** 

**NO SEVERITY** 



### Fire Door RB-9ZN8AS 🛛 🗢 FD30



Floor / Location Basement / Unit 7



**Fire Resistance** FD30

Item

Fire Door

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Gaps Head 6mm Hinge 1 Meeting Hinge 2 4mm 7mm 3mm Threshold 13mm

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



### LIMITED, OCCUPANT DID NOT Inspection Type **ANSWER** Have the door fully inspected by a competent person. The assessor had limited access to the door during the routine door survey.

REFERENCE RB-KYG32J DUE 22/04/2025 CATEGORY Building: Doors

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION



### Fire Door RB-J4UUYW



**Item** Fire Door

Fire Resistance FD30

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No


Floor / Location Basement / Unit 8



Gaps Head 6mm Hinge 1 Meeting 4mm 7mm Hinge 2 3mm Threshold 13mm

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



Inspection TypeLIMITED, OCCUPANT DID NOT<br/>ANSWERHave the door fully inspected by a competent person.<br/>The assessor had limited access to the door during the routine door survey.TIMESCALE<br/>SHORT TERMREFERENCE RB-496N9R DUE 22/04/2025<br/>CATEGORY Building: DoorsSEVERITY<br/>PROPERTY PROTECTION







### Fire Door RB-SY5BVL 🛛 🕫 FD30



Item Fire Door

Fire Resistance FD30

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Gaps Head 6mm Hinge 2 **3mm** Hinge 1 **4mm** Meeting 7mm Threshold 13mm

Last Limited Inspection 22/01/2025

**1** Action

Floor / Location

Basement / Unit 9A

Last Inspection Type Limited Access Inspection



LIMITED, OCCUPANT DID NOT Inspection Type **ANSWER** Have the door fully inspected by a competent person. TIMESCALE SHORT TERM The assessor had limited access to the door during the routine door survey. REFERENCE RB-WCPRZR DUE 22/04/2025 SEVERITY **PROPERTY PROTECTION** CATEGORY Building: Doors

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



## Fire Door RB-3367EB 🛛 🕫 FD30



Item Fire Door

**Fire Resistance** FD30

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish


Frame Finish Paint Finish

Leaf Vision Panels No

Floor / Location Basement / Unit 9B

**1** Action





Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



### Inspection Type

Have the door fully inspected by a competent person. The assessor had limited access to the door during the routine door survey.

REFERENCE RB-U7ZETU DUE 22/04/2025 CATEGORY Building: Doors

**ANSWER** TIMESCALE SHORT TERM

LIMITED, OCCUPANT DID NOT

SEVERITY PROPERTY PROTECTION

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



## Fire Door RB-7VBAHW



**Item** Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance



Basement / Unit BM5

Floor / Location


Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection





Inspection Type

### **Fire Door Condition**

X The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - louvered/ panelled door, no certification.

REFERENCE RB-ISGDME DUE No Due Date

LIMITED, OCCUPANT DID NOT ANSWER

NO TIMESCALE

**NO SEVERITY** 

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 4







ltem Fire Door

**Fire Resistance** FD30

Floor / Location GF / 57 Suite



Last Limited Inspection

22/01/2025

Last Inspection Type Limited Access Inspection



LIMITED, OCCUPANT DID NOT ANSWER

Inspection Type



## Fire Door RB-78MCHD



**Item** Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

### Frame Finish

Paint Finish



# .....

GF / Basement stair lobby

**1** Action

Floor / Location

Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





### A Additional Photos



### Inspection Type

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- × An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- imes When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ

42 370 **Risk**Base

### Replace fire door with FD30s fire rated door.

The fire door is damaged beyond repair.


REFERENCE RB-44AY9M DUE 22/04/2025 CATEGORY Building: Doors TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 43 3



## Fire Door RB-SJWVTA 🛛 🕏 FD30



**Item** Fire Door

Fire Resistance FD30

Certification None

Leaf Configuration Single Leaf - Single Acting Floor / Location GF / Cleaners cupboard



**Leaf Finish** Paint Finish

Frame Finish Paint Finish



**Inspection Type** 

### **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm hollow.

REFERENCE RB-D1IT1W DUE 22/04/2025 CATEGORY Building: Doors LIMITED ACCESS

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



### Fire Door RB-4CRAI4 🛛 🕏 Not Rated

Item

Fire Door

**Fire Resistance** 

Not Rated

Certification

Leaf Finish

Paint Finish

Frame Finish

Paint Finish

Gaps

Leaf Configuration

Single Leaf - Single Acting

Head **7mm** 

Threshold 15mm

Closing

12mm

None



**1** Action

Floor / Location GF / Comms Room

Intumescent & Smoke Seals None

Self-Closing Devices Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



21

#### A Additional Photos

Hinge 4mm



### Inspection Type

#### **Fire Door Condition**

- X The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- ✓ When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



### Replace fire door with FD30s fire rated door.

The fire door is damaged beyond repair.

REFERENCE RB-ABY3CE DUE 22/04/2025

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 46



### Fire Door RB-AR48PJ



**Item** Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish



Floor / Location GF / Corridor

**1** Action

Intumescent & Smoke Seals None

Self-Closing Devices Overhead

Electrical Hold Open Device Yes

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





### Inspection Type

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached

### Replace fire door with FD30s fire rated door.

The fire door is damaged beyond repair.

REFERENCE RB-VF6SRV DUE 22/04/2025 CATEGORY Building: Doors

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



#### FULL ACCESS

SHORT TERM

SEVERITY PROPERTY PROTECTION

### Fire Door RB-A57JCK 🛛 🕏 FD30



Item Fire Door

**Fire Resistance** FD30


Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance



### A Additional Photos



### **Inspection Type**

#### **Fire Door Condition**

- X The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)

Floor / Location GF / Corridor / stair lobby

**6** Actions

Intumescent & Smoke Seals Intumescent Only


Self-Closing Devices Overhead

**Electrical Hold Open Device** Yes

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 





**FULL ACCESS** 

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 48 370

**Risk**Base

| Adjust door alignment.  | TIMESCALE           |
|---|---------------------|
| Door gaps exceed safe guidelines.                             | SHORT TERM          |
| REFERENCE RB-EZNF7E DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Confirm glazing meets BS EN fire regulations.                 | TIMESCALE           |
| Ensure the integrity of the fire door.                        | SHORT TERM          |
| REFERENCE RB-NZYG6A DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.                      | TIMESCALE           |
| Seals are damaged or missing in sections of the frame.        | SHORT TERM          |
| REFERENCE RB-M35MAY DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.              | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route. | SHORT TERM          |
| REFERENCE <b>RB-WYVA13</b> DUE 22/04/2025                     | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Replace door with FD30s rated fire door.                      | TIMESCALE           |
| The door is not fit for purpose.                              | SHORT TERM          |
| REFERENCE RB-SSBRCP DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Door selector not functional.                                 | TIMESCALE           |
| Certification.  | SHORT TERM          |
| REFERENCE RB-MIA9HJ DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |



### Fire Door RB-7BQ6P4



**Item** Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish



### Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

**1** Action

Floor / Location

GF / Corridor lobby

Electrical Hold Open Device Yes

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





### A Additional Photos



### Inspection Type

#### **Fire Door Condition**

- X The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- × When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



### Replace fire door with FD30s fire rated door.

The fire door is damaged beyond repair.

REFERENCE RB-RT2GK7 DUE 22/04/2025 CATEGORY Building: Doors TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 51 370



# Fire Door RB-53DQQM 🔮 FD30

**Item** Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish



# GF / Corridor lobby

Floor / Location

**1** Action

Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

Electrical Hold Open Device Yes

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



25

### A Additional Photos



### Inspection Type

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



### Replace fire door with FD30s fire rated door.

The fire door is damaged beyond repair.

REFERENCE RB-9JKHAB DUE 22/04/2025 CATEGORY Building: Doors TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 53 370



### Fire Door RB-JRZGWA

Item

FD30

None

Fire Door

**Fire Resistance** 

Certification

Leaf Finish

Paint Finish

Frame Finish

Paint Finish

Leaf Configuration

Double Leaf - Single Acting



Floor / Location GF / Corridor lobby

7 Actions

Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead


Electrical Hold Open Device Yes

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection

<page-header>

# Gaps



Head 5mm

### A Additional Photos



### Inspection Type

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- × When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



| Replace hinges with BS EN standard fire door hinges.                        | TIMESCALE           |
|---|---------------------|
| All fire doors are required to have 3 hinges, which must be fire certified. | SHORT TERM          |
| REFERENCE RB-KUWXD7 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust door alignment.  | TIMESCALE           |
| Door gaps exceed safe guidelines.   | SHORT TERM          |
| REFERENCE RB-F7EKU8 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust the closer to ensure the door sits flush with the rebate.            | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.               | SHORT TERM          |
| REFERENCE RB-KJL3TI DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Confirm glazing meets BS EN fire regulations.                               | TIMESCALE           |
| Ensure the integrity of the fire door.                                      | SHORT TERM          |
| REFERENCE RB-PGJEGU DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust door alignment.  | TIMESCALE           |
| Doors do not close in-line if released from an open position.               | SHORT TERM          |
| REFERENCE RB-HCNPNL DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.                                    | TIMESCALE           |
| Seals are damaged or missing in sections of the frame.                      | SHORT TERM          |
| REFERENCE RB-S9W411 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.                            | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.               | SHORT TERM          |
| REFERENCE RB-7ATGK8 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 55 370 V Risk Base



### Fire Door RB-SC1QF3 👽 FD30



2 Actions

Intumescent & Smoke Seals

Self-Closing Devices

Last Full Inspection

Last Inspection Type

**Full Access Inspection** 

None

Overhead

22/01/2025

Item Fire Door

**Fire Resistance** FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

### Frame Finish

Paint Finish




### A Additional Photos



### Inspection Type

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached








**FULL ACCESS** 

**Risk**Base



| Replace hinges with BS EN standard fire door hinges.                           | TIMESCALE           |
|--|---------------------|
| All fire doors are required to have 3 hinges, which must be fire certified.    | SHORT TERM          |
| REFERENCE RB-6FHA17 DUE 22/04/2025   | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
|  |                     |
| Door leaf split at top due to closer hitting masonry reveal.<br>Certification. | <b>NO TIMESCALE</b> |







Item Fire Door

**Fire Resistance** FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No



#### **Electrical Hold Open Device** Yes

Last Full Inspection 22/01/2025

Floor / Location

Intumescent Only

Overhead

Self-Closing Devices

GF / Corridor near to unit 48

Intumescent & Smoke Seals

Last Inspection Type **Full Access Inspection** 





#### A Additional Photos



### **Inspection Type**

#### **Fire Door Condition**

- X The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- Fire door signage correctly identifies door operation and is securely attached

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



| Replace hinges with BS EN standard fire door hinges.                        | TIMESCALE           |
|---|---------------------|
| All fire doors are required to have 3 hinges, which must be fire certified. | SHORT TERM          |
| REFERENCE RB-4CRF5W DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Replace fire door with FD30s fire rated door.                               | TIMESCALE           |
| The fire door is damaged beyond repair.                                     | SHORT TERM          |
| REFERENCE <b>RB-2LSWAK</b> DUE <b>22/04/2025</b>                            | SEVERITY            |
| CATEGORY <b>Building: Doors</b>   | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.                            | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.               | SHORT TERM          |
| REFERENCE RB-RUXJGS DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.                                    | TIMESCALE           |
| Seals are damaged or missing in sections of the frame.                      | SHORT TERM          |
| REFERENCE RB-AXPNQ5 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust the door closer.   | TIMESCALE           |
| The door does not close-in-line if released from an open position.          | SHORT TERM          |
| REFERENCE <b>RB-B85JN3</b> DUE 22/04/2025                                   | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust door alignment.  | TIMESCALE           |
| Door gaps exceed safe guidelines.   | SHORT TERM          |
| REFERENCE RB-U2B93E DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |



### Fire Door RB-PCXWMV

**FD30** 7 Actions

> Floor / Location GF / Corridor next to unit 15

Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

**Electrical Hold Open Device** Yes

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 

29



Double Leaf - Single Acting

Leaf Configuration

ltem

FD30

None

Fire Door


**Fire Resistance** 

Certification

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance



### A Additional Photos



### Inspection Type

### **Fire Door Condition**


- X The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- ✓ Fire door signage correctly identifies door operation and is securely attached

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



| Replace hinges with BS EN standard fire door hinges.                                   | TIMESCALE                   |
|--|-----------------------------|
| All fire doors are required to have 3 hinges, which must be fire certified.            | SHORT TERM                  |
| REFERENCE RB-DQM7NJ DUE 22/04/2025   | SEVERITY                    |
| CATEGORY Building: Doors   | PROPERTY PROTECTION         |
| Replace fire door with FD30s fire rated door.  | TIMESCALE                   |
| The fire door is damaged beyond repair.  | SHORT TERM                  |
| REFERENCE RB-512EJ3 DUE 22/04/2025   | SEVERITY                    |
| CATEGORY Building: Doors   | PROPERTY PROTECTION         |
| Reduce gaps between the door and the door frame.                                       | TIMESCALE                   |
| To ensure heat and smoke cannot pass through to escape route.                          | NO TIMESCALE                |
| REFERENCE RB-H4GIX7 DUE No Due Date  | SEVERITY                    |
| CATEGORY Building: Doors   | PROPERTY PROTECTION         |
| Fit intumescent seals to the door frame.   | TIMESCALE                   |
| Seals are damaged or missing in sections of the frame.                                 | SHORT TERM                  |
| REFERENCE RB-XFXG5T DUE 22/04/2025   | SEVERITY                    |
| CATEGORY Building: Doors   | PROPERTY PROTECTION         |
| Confirm glazing meets BS EN fire regulations.  | TIMESCALE                   |
| Ensure the integrity of the fire door.   | SHORT TERM                  |
| REFERENCE RB-NGGH83 DUE 22/04/2025   | SEVERITY                    |
| CATEGORY Building: Doors   | PROPERTY PROTECTION         |
| Adjust door alignment.   | TIMESCALE                   |
| Door gaps exceed safe guidelines.  | SHORT TERM                  |
| REFERENCE RB-TZ79YB DUE 22/04/2025   | SEVERITY                    |
| CATEGORY Building: Doors   | PROPERTY PROTECTION         |
| Door selector not functional.<br>Certification.<br>REFERENCE RB-3LKMDM DUE No Due Date | NO TIMESCALE<br>NO SEVERITY |







ltem Fire Door

**Fire Resistance** FD30


Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance



### A Additional Photos



### Inspection Type

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- ✓ Fire door signage correctly identifies door operation and is securely attached

Floor / Location GF / Corridor next to unit 18

Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

**Electrical Hold Open Device** Yes

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



**FULL ACCESS** 

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



7 Actions

| Replace hinges with BS EN standard fire door hinges.                        | TIMESCALE           |
|---|---------------------|
| All fire doors are required to have 3 hinges, which must be fire certified. | SHORT TERM          |
| REFERENCE RB-EKL5CL DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Replace fire door with FD30s fire rated door.                               | TIMESCALE           |
| The fire door is damaged beyond repair.                                     | SHORT TERM          |
| REFERENCE RB-DBG9TK DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.                            | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.               | SHORT TERM          |
| REFERENCE RB-94CGLU DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Confirm glazing meets BS EN fire regulations.                               | TIMESCALE           |
| Ensure the integrity of the fire door.                                      | SHORT TERM          |
| REFERENCE RB-QG3F8J DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust the closer to ensure the door sits flush with the rebate.            | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.               | SHORT TERM          |
| REFERENCE RB-XB943Z DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust door alignment.  | TIMESCALE           |
| Door gaps exceed safe guidelines.   | SHORT TERM          |
| REFERENCE RB-M4AGLG DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust door alignment.  | TIMESCALE           |
| Door gaps exceed safe guidelines.   | SHORT TERM          |
| REFERENCE RB-7SG4Z5 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |



### Fire Door RB-9NGMW8

**FD30** 

**Item** Fire Door

Fire Resistance


Certification None

Leaf Configuration Double Leaf - Single Acting


Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance



### A Additional Photos



### **Inspection Type**

#### **Fire Door Condition**

- X The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- × When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

Floor / Location GF / Corridor next to unit 19

7 Actions

Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

Electrical Hold Open Device Yes

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection











| Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-VSKX3W DUE 22/04/2025<br>CATEGORY Building: Doors | TIMESCALE<br>SHORT TERM         |
|---|---------------------------------|
|   | SEVERITY<br>PROPERTY PROTECTION |
| Confirm glazing meets BS EN fire regulations.   | TIMESCALE                       |
| Ensure the integrity of the fire door.  | SHORT TERM                      |
| REFERENCE RB-5PITEN DUE 22/04/2025  | SEVERITY                        |
| CATEGORY Building: Doors  | PROPERTY PROTECTION             |
| Fit intumescent seals to the door frame.  | TIMESCALE                       |
| Seals are damaged or missing in sections of the frame.  | SHORT TERM                      |
| REFERENCE RB-U4CY2Y DUE 22/04/2025  | SEVERITY                        |
| CATEGORY Building: Doors  | PROPERTY PROTECTION             |
| Reduce gaps between the door and the door frame.  | TIMESCALE                       |
| To ensure heat and smoke cannot pass through to escape route.   | SHORT TERM                      |
| REFERENCE RB-R82X1Z DUE 22/04/2025  | SEVERITY                        |
| CATEGORY Building: Doors  | PROPERTY PROTECTION             |
| Replace door with FD30s rated fire door.  | timescale                       |
| The door is not fit for purpose.  | <b>SHORT TERM</b>               |
| REFERENCE <b>RB-5EYETA</b> DUE <b>22/04/2025</b>  | SEVERITY                        |
| CATEGORY Building: Doors  | PROPERTY PROTECTION             |
| Replace hinges with BS EN standard fire door hinges.  | TIMESCALE                       |
| All fire doors are required to have 3 hinges, which must be fire certified.   | SHORT TERM                      |
| REFERENCE <b>RB-3IPRGN</b> DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors  | PROPERTY PROTECTION             |
| Door selector not functional.   | TIMESCALE                       |
| Certification.  | SHORT TERM                      |
| REFERENCE RB-X3QD9D DUE 22/04/2025  | SEVERITY                        |
| CATEGORY Building: Doors  | PROPERTY PROTECTION             |



### Fire Door RB-3JXMUG



**Item** Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance



### A Additional Photos



### **Inspection Type**

#### **Fire Door Condition**

- X The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- × When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

Floor / Location GF / Corridor next to unit 23

Intumescent & Smoke Seals Intumescent Only


Self-Closing Devices Overhead

Electrical Hold Open Device Yes

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





FULL ACCESS

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



### esistance

| Replace hinges with BS EN standard fire door hinges.                        | TIMESCALE           |
|---|---------------------|
| All fire doors are required to have 3 hinges, which must be fire certified. | NO TIMESCALE        |
| REFERENCE RB-JMQQU3 DUE No Due Date   | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Replace fire door with FD30s fire rated door.                               | TIMESCALE           |
| The fire door is damaged beyond repair.                                     | NO TIMESCALE        |
| REFERENCE RB-2IHSVA DUE No Due Date   | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.                            | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.               | SHORT TERM          |
| REFERENCE RB-QFDN2T DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.                                    | TIMESCALE           |
| Seals are damaged or missing in sections of the frame.                      | SHORT TERM          |
| REFERENCE RB-HUSEK5 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Confirm glazing meets BS EN fire regulations.                               | TIMESCALE           |
| Ensure the integrity of the fire door.                                      | SHORT TERM          |
| REFERENCE RB-G5D9WJ DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust the closer to ensure the door sits flush with the rebate.            | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.               | SHORT TERM          |
| REFERENCE RB-5U7EI2 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust door alignment.  | TIMESCALE           |
| Door gaps exceed safe guidelines.   | SHORT TERM          |
| REFERENCE RB-3AYNN8 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Door selector not functional.   | TIMESCALE           |
| Certification.  | SHORT TERM          |
| REFERENCE <b>RB-7I2VE1</b> DUE 22/04/2025                                   | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |







# **6** Actions

Item Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No



### A Additional Photos



### **Inspection Type**

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

Floor / Location GF / Corridor next to unit 47

Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices Overhead

**Electrical Hold Open Device** Yes

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



FULL ACCESS

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



33

| Replace hinges with BS EN standard fire door hinges.  | TIMESCALE           |
|---|---------------------|
| All fire doors are required to have 3 hinges, which must be fire certified.   | SHORT TERM          |
| REFERENCE RB-TQ1L5F DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Replace fire door with FD30s fire rated door.   | TIMESCALE           |
| The fire door is damaged beyond repair. Morticed 3 times holes exposed or cover with face plates.                           | SHORT TERM          |
| REFERENCE RB-WWRQ6G DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.  | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.   | SHORT TERM          |
| REFERENCE RB-KTCDPA DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.  | TIMESCALE           |
| Seals are damaged or missing in sections of the frame.  | SHORT TERM          |
| REFERENCE RB-1WRP9X DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust the door closer. Currently slamming violently.<br>The door does not close-in-line if released from an open position. | NO TIMESCALE        |
| REFERENCE RB-JDLTUF DUE No Due Date   | NO SEVERITY         |
| Adjust door alignment.  | TIMESCALE           |
| Doors do not close in-line if released from an open position.   | SHORT TERM          |
| REFERENCE RB-74VQT9 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |



### Fire Door RB-DFYUN4



**Item** Fire Door


Fire Resistance FD30

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish



# .....

GF / Corridor to goods lift

**1** Action

Floor / Location

Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

Electrical Hold Open Device Yes

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





### A Additional Photos



### Inspection Type

FULL ACCESS

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- × An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- imes When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 7



### Replace fire door with FD30s fire rated door.

The fire door is damaged beyond repair.

REFERENCE RB-AXNPSC DUE 22/04/2025 CATEGORY Building: Doors TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 71 370



### Fire Door RB-WTG24P 🛛 🕏 Not Rated

Item Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Floor / Location


GF / Electrical panel

Last Full Inspection 22/01/2025

1 Action

Last Inspection Type **Full Access Inspection** 





A Additional Photos



### Inspection Type

### **Fire Door Condition**

X The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose.

REFERENCE RB-2J7NAC DUE 22/04/2025 CATEGORY Building: Doors

FULL ACCESS



SEVERITY **PROPERTY PROTECTION** 



RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ





ltem Fire Door

**Fire Resistance** FD30

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish Frame Finish

Floor / Location

**1** Action

GF / Electric cupboard

Paint Finish

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection





A Additional Photos



| Inspection Type   | LIMITED, OCCUPANT DID NOT<br>Answer |
|---|-------------------------------------|
| Door appears to be sealed shut - confirm usage. No hinges visible from outside.<br>Certification. | NO TIMESCALE                        |
| REFERENCE RB-2ZCSVI DUE No Due Date   | NO SEVERITY                         |

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



## Fire Door RB-4FAFCU 🛛 Not Rated



7 Actions

Floor / Location GF / Exit lobby doors



**Fire Resistance** Not Rated

Item

Fire Door

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance

#### Gaps Head 9mm Hinge 1 Meeting Hinge 2 6mm 8mm 4mm Threshold 7mm

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



### A Additional Photos



#### Inspection Type

**FULL ACCESS** 

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present X
- Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides ×
- An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line) X
- When closed, the leaf sits against a securely installed stop without distortion X
- Fire door signage correctly identifies door operation and is securely attached  $\checkmark$

Replace hinges with BS EN standard fire door hinges.

All fire doors are required to have 3 hinges, which must be fire certified.

REFERENCE RB-FE9K6Y DUE 22/04/2025 CATEGORY Building: Doors

SHORT TERM

SEVERITY PROPERTY PROTECTION





| Replace fire door with FD30s fire rated door.                      | TIMESCALE           |
|--|---------------------|
| The fire door is damaged beyond repair.                            | SHORT TERM          |
| REFERENCE RB-4BTSRF DUE 22/04/2025                                 | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.                   | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.      | SHORT TERM          |
| REFERENCE <b>RB-2PCGBG</b> DUE 22/04/2025                          | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.                           | TIMESCALE           |
| Seals are damaged or missing in sections of the frame.             | SHORT TERM          |
| REFERENCE <b>RB-2C3DEG</b> DUE 22/04/2025                          | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
| Adjust the door closer.  | TIMESCALE           |
| The door does not close-in-line if released from an open position. | SHORT TERM          |
| REFERENCE RB-88JJU4 DUE 22/04/2025                                 | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
| Adjust door alignment.   | TIMESCALE           |
| Doors do not close in-line if released from an open position.      | SHORT TERM          |
| REFERENCE <b>RB-5EIRYA</b> DUE 22/04/2025                          | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
| Door selector not functional.<br>Certification.                    | NO TIMESCALE        |
| REFERENCE RB-VH8F71 DUE No Due Date                                | NO SEVERITY         |



# Fire Door RB-L3UT9D 🛛 🕏 FD30



Item Fire Door


**Fire Resistance** FD30

Certification **BWF** Certifire

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish



## A Additional Photos



### Inspection Type

### **Fire Door Condition**

- The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

Floor / Location GF / Female WC

**6** Actions

Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 





**FULL ACCESS** 


**Risk**Base

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 76 370

| Replace hinges with BS EN standard fire door hinges.  | TIMESCALE                       |
|---|---------------------------------|
| All fire doors are required to have 3 hinges, which must be fire certified.                                 | SHORT TERM                      |
| REFERENCE RB-G1NKJ8 DUE 22/04/2025  | SEVERITY                        |
| CATEGORY Building: Doors  | PROPERTY PROTECTION             |
| Adjust door alignment.  | TIMESCALE                       |
| Door gaps exceed safe guidelines.   | SHORT TERM                      |
| REFERENCE RB-XD1FSB DUE 22/04/2025  | SEVERITY                        |
| CATEGORY Building: Doors  | PROPERTY PROTECTION             |
| Adjust the door closer for the door to latch closed.  | TIMESCALE                       |
| The door does not close in-line if released from an open position.  | SHORT TERM                      |
| REFERENCE <b>RB-WWDDYB</b> DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors  | PROPERTY PROTECTION             |
| Fit intumescent seals to the door frame.  | TIMESCALE                       |
| Seals are damaged or missing in sections of the frame.  | SHORT TERM                      |
| REFERENCE <b>RB-IDGP62</b> DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors  | PROPERTY PROTECTION             |
| Make good missing lock case hole.   | TIMESCALE                       |
| Certification.  | NO TIMESCALE                    |
| REFERENCE <b>RB-73GCCF</b> DUE <b>No Due Date</b><br>LOCATION Door leaf.<br>CATEGORY <b>Building: Doors</b> | SEVERITY<br>PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.  | TIMESCALE                       |
| To ensure heat and smoke cannot pass through to escape route.   | SHORT TERM                      |
| REFERENCE <b>RB-KWNYDC</b> DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors  | PROPERTY PROTECTION             |



# Fire Door RB-BBUKQ6



Floor / Location GF / Goods lift lobby

Fire Door

Item

Fire Resistance FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

### Frame Finish

Paint Finish




## Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





### A Additional Photos



### Inspection Type

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

FULL ACCESS

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 7



## Replace fire door with FD30s fire rated door.

The fire door is damaged beyond repair.

REFERENCE RB-W5PCHD DUE 22/04/2025

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 79 37







**1** Action

Item Fire Door

> **Fire Resistance** Not Rated

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Metal Finish

GF / Howard Building

Floor / Location

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





Bar cellar

Inspection Type

**Fire Door Condition** × The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - timber door in an aluminium frame.

REFERENCE RB-TCXBI7 DUE 22/04/2025 CATEGORY Building: Doors

FULL ACCESS

SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 80 370



# Fire Door RB-3QAK7I 🛛 🕫 FD30



Item Fire Door

**Fire Resistance** FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish



GF / Howard Building

**1** Action

Floor / Location

Intumescent & Smoke Seals None

Self-Closing Devices None

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



41

Office V16

**Inspection Type** 

FULL ACCESS

**Fire Door Condition** 


× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose. Panelled door has been refaced.

REFERENCE RB-HUSV1K DUE No Due Date

**NO TIMESCALE** 

**NO SEVERITY** 






# Fire Door RB-4WCGQ6 1Action

**Item** Fire Door

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish



Floor / Location GF / Howard Building

Intumescent & Smoke Seals None

Self-Closing Devices None

Electrical Hold Open Device No

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





Office 13

#### A Additional Photos



Inspection Type

### **Fire Door Condition**

× The leaf and frame are adequately specified

### FULL ACCESS

Replace door with FD30s rated fire door. The door is not fit for purpose, frame cut away at lock area, only two inadequate hinges fitted. Door closer disconnected missing arm. Door located in panelled partition.

TIMESCALE SHORT TERM SEVERITY PROPERTY PROTECTION

REFERENCE RB-5FD6IR DUE 22/04/2025 CATEGORY Building: Doors

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 82 370



# Fire Door RB-5MWD9X 👽 FD305


Item Fire Door

**Fire Resistance** FD30

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish



Floor / Location Gf / Howard Building



Intumescent & Smoke Seals Intumescent & Smoke

**1** Action

Self-Closing Devices Overhead

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



**FULL ACCESS** 

**NO TIMESCALE** 

**NO SEVERITY** 

Conference / escape lobby

### **Inspection Type**

### **Fire Door Condition**

X The leaf and frame are adequately specified

### Replace door with FD30s rated fire door.

The door is not fit for purpose; code lock fitted not suitable for fire, also contravenes fire safety in terms of free egress by having code lock fitted on an escape route. Hinges fitted upside-down also.

#### REFERENCE RB-YXMCCW DUE No Due Date



RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



# Fire Door RB-8V34BM 🛛 🗢 FD30



**Item** Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish



.....

Floor / Location GF / Howard Building

Intumescent & Smoke Seals None

Self-Closing Devices Overhead

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





Footbath

## Inspection Type

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- × When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

### Replace hinges with BS EN standard fire door hinges.

All fire doors are required to have 3 hinges, which must be fire certified.

REFERENCE RB-JEFUDI DUE 22/04/2025 CATEGORY Building: Doors FULL ACCESS


TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION



| Replace door with FD30s rated fire door.                      | TIMESCALE           |
|---|---------------------|
| The door is not fit for purpose.                              | SHORT TERM          |
| REFERENCE RB-CXK8IQ DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.              | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route. | SHORT TERM          |
| REFERENCE RB-9DNS8I DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.                      | TIMESCALE           |
| Seals are damaged or missing in sections of the frame.        | SHORT TERM          |
| REFERENCE RB-E2JDMR DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Adjust door alignment.  | TIMESCALE           |
| Door gaps exceed safe guidelines.                             | SHORT TERM          |
| REFERENCE RB-18UU2R DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |





**Item** Fire Door Floor / Location GF / Howard Building



Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



Office 4

Inspection Type

Fire Door ConditionX The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - timber door in an aluminium frame.

REFERENCE RB-4Q4TLH DUE 22/04/2025 CATEGORY Building: Doors FULL ACCESS

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 86 370



# Fire Door RB-9DKYW5 🛛 🕏 Not Rated



Floor / Location GF / Howard Building

1 Action

ltem Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Female WC

### A Additional Photos



## **Inspection Type**

### **Fire Door Condition**


× The leaf and frame are adequately specified

| Replace door with FD30s rated fire door.<br>The door is not fit for purpose. Door badly damaged and does not close in frame, located in | NO TIMESCALE |
|---|--------------|
| panelled partition.<br>REFERENCE <b>RB-I3KETE</b> DUE <b>No Due Date</b>  | NO SEVERITY  |

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 87 370



FULL ACCESS



**ltem** Fire Door

l ....f.C....finunction

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish Floor / Location GF / Howard Building



Frame Finish Paint Finish



LIMITED ACCESS

**Risk**Base

Office V4

Inspection Type

Fire Door Condition

× The leaf and frame are adequately specified

| Replace door with FD30s rated fire door.   | TIMESCALE           |
|--|---------------------|
| The door is not fit for purpose - door located in panelled partition. Original panelled door has been refaced. | SHORT TERM          |
| REFERENCE RB-Z4TTE3 DUE 22/04/2025   | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
|  |                     |



## Fire Door RB-72EBBR 🛛 Not Rated



1 Action

Floor / Location GF / Howard Building

Intumescent & Smoke Seals None

Self-Closing Devices None

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



48

Leaf Finish Wood Finish

Leaf Configuration Single Leaf - Single Acting

ltem

Fire Door

**Fire Resistance** 


Not Rated

Certification

None

Frame Finish Wood Finish

Leaf Vision Panels No



Kitchen

### A Additional Photos



Inspection Type

FULL ACCESS

**Fire Door Condition** X The leaf and frame are adequately specified

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



### Replace door with FD30s rated fire door.

The door is not fit for purpose - traditional panelled door, leaf split at top corner on the closing edge.


NO TIMESCALE

REFERENCE RB-XZU6NC DUE No Due Date

**NO SEVERITY** 

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 90







2 Actions

Floor / Location GF / Howard Building

Intumescent & Smoke Seals Intumescent & Smoke


Self-Closing Devices Floor Sprung / Pivot

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 





Frame Finish Paint Finish

Leaf Finish

Paint Finish

Item

FD30

None

Fire Door


**Fire Resistance** 

Certification

Leaf Configuration

Double Leaf - Double Acting

Leaf Vision Panels Yes - Unknown Fire Resistance



### Double action corridor

**Inspection Type** 

#### **FULL ACCESS**

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- Seals are undamaged and well fitted / continuous around the whole leaf or frame
- Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- ✓ When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

## Replace door with FD30s rated fire door. SHORT TERM The door is not fit for purpose, floor spring has full shoe at bottom, this is not certified. REFERENCE RB-B9KY6S DUE 22/04/2025 **PROPERTY PROTECTION** CATEGORY Building: Doors



RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ

Reduce gaps between the door and the door frame. To ensure heat and smoke cannot pass through to escape route.

REFERENCE RB-JTRSGR DUE 22/04/2025 CATEGORY Building: Doors TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 92 37



# Fire Door RB-ABA3NQ 🛛 🗢 FD30

Item Fire Door

**Fire Resistance** FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish



Intumescent & Smoke Seals

7 Actions

GF / Howard Building

Floor / Location

None

Self-Closing Devices None

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 





Office V12 FULL ACCESS Inspection Type

### **Fire Door Condition**

- × The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- X Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × When closed, the leaf sits against a securely installed stop without distortion

| Replace hinges with BS EN standard fire door hinges.                        | TIMESCALE           |
|---|---------------------|
| All fire doors are required to have 3 hinges, which must be fire certified. | SHORT TERM          |
| REFERENCE RB-ML4CC9 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Replace fire door with FD30s fire rated door.                               | TIMESCALE           |
| The fire door is damaged beyond repair.                                     | SHORT TERM          |
| REFERENCE RB-GYSAVD DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |





| Reduce gaps between the door and the door frame.   | TIMESCALE                   |
|--|-----------------------------|
| To ensure heat and smoke cannot pass through to escape route.                                      | SHORT TERM                  |
| REFERENCE RB-ELBLFJ DUE 22/04/2025   | SEVERITY                    |
| CATEGORY Building: Doors   | PROPERTY PROTECTION         |
| Fit intumescent seals to the door frame.   | TIMESCALE                   |
| Seals are damaged or missing in sections of the frame.   | SHORT TERM                  |
| REFERENCE RB-GBZNMV DUE 22/04/2025   | SEVERITY                    |
| CATEGORY Building: Doors   | PROPERTY PROTECTION         |
| Install a door closer compliant to BS EN1154   | TIMESCALE                   |
| To ensure heat and smoke cannot pass through to escape route.                                      | SHORT TERM                  |
| REFERENCE RB-KR1A2X DUE 22/04/2025   | SEVERITY                    |
| CATEGORY Building: Doors   | PROPERTY PROTECTION         |
| Adjust door alignment.   | TIMESCALE                   |
| Door gaps exceed safe guidelines.  | SHORT TERM                  |
| REFERENCE RB-PYPJYZ DUE 22/04/2025   | SEVERITY                    |
| CATEGORY Building: Doors   | PROPERTY PROTECTION         |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-JUHQG5 DUE No Due Date | NO TIMESCALE<br>NO SEVERITY |
|  |                             |



# Fire Door RB-AP5BJW



**Item** Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Double Leaf - Double Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance



.....

**5** Actions

Floor / Location

GF / Howard Building

Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices Floor Sprung / Pivot

Electrical Hold Open Device No

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





Double action corridor

### Inspection Type

#### FULL ACCESS

**Fire Door Condition** 

- ✓ The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

| Adjust door alignment.             | TIMESCALE           |
|------------------------------------|---------------------|
| Door gaps exceed safe guidelines.  | SHORT TERM          |
| REFERENCE RB-X1N4VJ DUE 22/04/2025 | SEVERITY            |
| CATEGORY Building: Doors           | PROPERTY PROTECTION |
|                                    | ACTION CONTINUES    |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



### ..ACTION CONTINUED



| Replace fire door with FD30s fire rated door.  | TIMESCALE           |
|--|---------------------|
| The fire door is damaged beyond repair. Top of RH leaf missing at top centre location. | SHORT TERM          |
| REFERENCE RB-YDEGNK DUE 22/04/2025   | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
|  |                     |
| Adjust the closer to ensure the door sits flush with the rebate.                       | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.                          | SHORT TERM          |
| REFERENCE RB-GCHG3S DUE 22/04/2025   | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
| Adjust the door closer.  | TIMESCALE           |
| The door does not close-in-line if released from an open position.                     | SHORT TERM          |
| REFERENCE RB-PJK6TK DUE 22/04/2025   | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
| Confirm glazing meets BS EN fire regulations.  | TIMESCALE           |
| Ensure the integrity of the fire door.   | SHORT TERM          |
| REFERENCE RB-GSHC7Z DUE 22/04/2025   | SEVERITY            |







ltem Fire Door

**Fire Resistance** FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish



Floor / Location GF / Howard Building

Intumescent & Smoke Seals None

Self-Closing Devices None

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection





Office V8

Inspection Type

LIMITED, OCCUPANT DID NOT ANSWER



## Fire Door RB-ESVT97 🛛 🔊 FD305



Item Fire Door

**Fire Resistance** FD30

Certification None


Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

#### Leaf Vision Panels

Yes - Unknown Fire Resistance



Intumescent & Smoke Seals

**6** Actions

GF / Howard Building

Floor / Location

Intumescent & Smoke Self-Closing Devices

Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Double action corridor

### **Inspection Type**

FULL ACCESS

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- When closed, the leaf sits against a securely installed stop without distortion  $\checkmark$
- Fire door signage correctly identifies door operation and is securely attached



RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



| Adjust door alignment.  | TIMESCALE           |
|---|---------------------|
| Door gaps exceed safe guidelines.                             | SHORT TERM          |
| REFERENCE RB-PU8DN2 DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Confirm glazing meets BS EN fire regulations.                 | TIMESCALE           |
| Ensure the integrity of the fire door.                        | SHORT TERM          |
| REFERENCE RB-LUYRRY DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.                      | TIMESCALE           |
| Seals are damaged or missing in sections of the frame.        | SHORT TERM          |
| REFERENCE RB-X8X746 DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.              | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route. | SHORT TERM          |
| REFERENCE RB-DV5CLQ DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Replace fire door with FD30s fire rated door.                 | TIMESCALE           |
| The fire door is damaged beyond repair.                       | SHORT TERM          |
| REFERENCE RB-TRDG22 DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |



# Fire Door RB-FQ56JD 🛛 🕏 FD305



**Fire Resistance** FD30

Item

Fire Door

Certification **BWF** Certifire

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Fire Rated

Gaps Head 4mm Hinge 1 Meeting Hinge 2 8mm 7mm 4mm Threshold 7mm

Intumescent & Smoke Seals Intumescent & Smoke


6 Actions

GF / Howard Building

Floor / Location

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



Reception

### A Additional Photos



RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 100 370



#### Inspection Type

### **Fire Door Condition**

- ✓ The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- ✓ Fire door signage correctly identifies door operation and is securely attached

| Adjust door alignment.   | TIMESCALE                       |
|--|---------------------------------|
| Door gaps exceed safe guidelines.  | SHORT TERM                      |
| REFERENCE RB-ZHDHEI DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-DA465E DUE 22/04/2025  | TIMESCALE<br>SHORT TERM         |
| CATEGORY Building: Doors   | SEVERITY<br>PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame. Seals are broken where hinges are located,<br>seals do not butt together. |                                 |
| REFERENCE RB-YC64LX DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |
| Re fix hinges correctly, not fitted flush.   | TIMESCALE                       |
| Hinges badly fitted.   | SHORT TERM                      |
| REFERENCE RB-1GFPHB DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |
|  |                                 |
| Correct frame fixings.<br>Frame fixings left exposed, should be capped or filled. Five fixings to LHleaf, only 3 fixings to RH<br>leaf.                                      | TIMESCALE<br>SHORT TERM         |
| REFERENCE RB-48G971 DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |
| Panic bolt fouling on RH leaf.   | TIMESCALE                       |
| Stops door closing - see images.   | SHORT TERM                      |
| REFERENCE RB-LATACU DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 101 3



# Fire Door RB-GK57N1

Item

Fire Door




Floor / Location GF / Howard Building



**Fire Resistance** 55 Gaps Head 4mm FD30 Certification Hinge Closing -V6-None 4mm 4mm Leaf Configuration Single Leaf - Single Acting Threshold 8mm Leaf Finish Intumescent & Smoke Seals Paint Finish None Frame Finish Self-Closing Devices Paint Finish None Office V6 Inspection Type LIMITED ACCESS **Fire Door Condition** × The leaf and frame are adequately specified Replace door with FD30s rated fire door. **NO TIMESCALE** The door is not fit for purpose panelled door has been resurfaced. REFERENCE RB-245ZZQ DUE No Due Date **NO SEVERITY** 





ltem Fire Door

Floor / Location GF / Howard Building



Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



Office 1

Inspection Type

**Fire Door Condition** × The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - timber door in an aluminium frame.

REFERENCE RB-GA7WKM DUE No Due Date

FULL ACCESS

**NO TIMESCALE** 

**NO SEVERITY** 

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 103 370



# Fire Door RB-HVHKZH 🛛 🕫 FD30



Floor / Location GF / Howard Building



Fire Resistance FD30

Item

Fire Door


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish



Intumescent & Smoke Seals None

Self-Closing Devices None

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



Office V11

### Inspection Type

### **Fire Door Condition**

- × The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- X Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached

| Replace hinges with BS EN standard fire door hinges.                        | TIMESCALE           |
|---|---------------------|
| All fire doors are required to have 3 hinges, which must be fire certified. | SHORT TERM          |
| REFERENCE RB-4QHFE8 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Replace door with FD30s rated fire door.                                    | TIMESCALE           |
| The door is not fit for purpose.  | SHORT TERM          |
| REFERENCE <b>RB-2D5ZNV</b> DUE 22/04/2025                                   | SEVERITY            |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 1



FULL ACCESS

| Reduce gaps between the door and the door frame.   | TIMESCALE  |
|--|--|
| To ensure heat and smoke cannot pass through to escape route.  | SHORT TERM   |
| REFERENCE RB-1CNKCK DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Fit intumescent seals to the door frame.   | TIMESCALE  |
| Seals are damaged or missing in sections of the frame.   | SHORT TERM   |
| REFERENCE RB-83BZMQ DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Fit a fire door keep locked shut sign.<br>REFERENCE RB-4ZW47L DUE 22/04/2025<br>CATEGORY Building: Doors   | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |
| Adjust door alignment.   | TIMESCALE  |
| Door gaps exceed safe guidelines.  | SHORT TERM   |
| REFERENCE RB-4949V7 DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Install a door closer compliant to BS EN 1154.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-W3EU89 DUE No Due Date | NO TIMESCALE<br>NO SEVERITY                                |



# Fire Door RB-INVS8R

**Item** Fire Door

Leaf Configuration Single Leaf - Single Acting


**Leaf Finish** Paint Finish

Frame Finish Paint Finish Floor / Location GF / Howard Building



Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



Office V17

Inspection Type

LIMITED, OCCUPANT DID NOT ANSWER

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 106 370






ltem Fire Door

Floor / Location GF / Howard Building





Office 2

Inspection Type

### **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - timber door in an aluminium frame.

REFERENCE RB-GGSMBV DUE 22/04/2025 CATEGORY Building: Doors



LIMITED ACCESS

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 107 370



## Fire Door RB-JNY8RK 🛛 🔊 Not Rated



**1** Action

Floor / Location GF / Howard Building



**Fire Resistance** Not Rated

Item

Fire Door

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Metal Finish

Leaf Vision Panels Yes - Fire Rated

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



**Reception corridor** 

Inspection Type

**Fire Door Condition** × The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - timber door in an aluminium frame.

REFERENCE RB-V9XW1W DUE No Due Date CATEGORY Building: Doors

**FULL ACCESS** 

SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 108 370



# Fire Door RB-JPS8JW 🛛 🕫 FD30



Floor / Location GF / Howard Building

1 Action



**Fire Resistance** FD30

ltem

Fire Door


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish




Intumescent & Smoke Seals None

Self-Closing Devices None

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Office V10

A Additional Photos



Inspection Type

FULL ACCESS

**Risk**Base

**Fire Door Condition** × The leaf and frame are adequately specified



# Replace door with FD30s rated fire door. TIMESCALE The door is not fit for purpose. SHORT TERM REFERENCE RB-Z1VNCZ DUE 22/04/2025 SEVERITY LOCATION Panelled door has been resurfaced. CATEGORY Building: Doors 252



# Fire Door RB-KRNXIE 🛛 🕫 FD30



Floor / Location GF / Howard Building



Fire Resistance FD30

Item

Fire Door

Certification None

Leaf Configuration Single Leaf - Single Acting

**Leaf Finish** Paint Finish

Frame Finish Paint Finish



Intumescent & Smoke Seals None

Self-Closing Devices None



Office V14

Inspection Type

Fire Door ConditionX The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose. Panelled door has been refaced.


REFERENCE RB-8YXX8T DUE 22/04/2025 CATEGORY Building: Doors LIMITED ACCESS

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 111 370





**Item** Fire Door

Leaf Configuration Single Leaf - Single Acting

**Leaf Finish** Paint Finish Floor / Location GF / Howard Building



Frame Finish Paint Finish



LIMITED ACCESS

.....

Office V5

Inspection Type

Fire Door Condition

The leaf and frame are adequately specified


 Replace door with FD30s rated fire door.
 TIMESCALE

 The door is not fit for purpose. Panelled door fitted in a panelled partition, door has been resurfaced.
 SEVENTY

 REFERENCE RB-QBD9L5 DUE 22/04/2025
 SEVENTY

 CATEGORY Building: Doors
 253





Item Fire Door

Last Full Inspection 22/01/2025

GF / Howard Building

Floor / Location

Last Inspection Type **Full Access Inspection** 



FULL ACCESS

**Risk**Base

Office 3

# Inspection Type

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- V When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached

### Replace door with FD30s rated fire door. TIMESCALE SHORT TERM The door is not fit for purpose timber door in an aluminium. REFERENCE RB-JX6XF6 DUE 22/04/2025 SEVERIT **PROPERTY PROTECTION** CATEGORY Building: Doors Fit intumescent seals to the door frame. **NO TIMESCALE** Seals are damaged or missing in sections of the frame. REFERENCE RB-3P5C3M DUE No Due Date **NO SEVERITY** ACTION CONTINUES..








RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 114 370 V Risk Base





**Item** Fire Door

Leaf Configuration Single Leaf - Single Acting

**Leaf Finish** Paint Finish Floor / Location GF / Howard Building



Frame Finish Paint Finish



.....

Office V3

Inspection Type

Fire Door ConditionX The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose door located in panelled partition. Original panelled door has been refaced. TIMESCALE SHORT TERM

LIMITED ACCESS

SEVERITY PROPERTY PROTECTION

REFERENCE RB-HRFSMD DUE 22/04/2025 CATEGORY Building: Doors

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 115 370







Item Fire Door

**Fire Resistance** FD30


Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

### Leaf Vision Panels Yes - Fire Rated



GF / Howard Building

**1** Action

Floor / Location


Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices Overhead

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 





Business opportunity centre

### A Additional Photos



Inspection Type

FULL ACCESS

**Fire Door Condition** 

X The leaf and frame are adequately specified

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 116 370



### Replace door with FD30s rated fire door.

The door is not fit for purpose - stop section of frame has been cut away to allow mag lock installation, head room reduced below 2m clear.

TIMESCALE SHORT TERM

REFERENCE RB-4BD3BC DUE 22/04/2025 CATEGORY Building: Doors SEVERITY PROPERTY PROTECTION



# Fire Door RB-NL5VST 🛛 🕏 FD30



Floor / Location GF / Howard Building

**6** Actions

**Fire Resistance** FD30

Item

Fire Door


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish



Intumescent & Smoke Seals None

Self-Closing Devices None

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Office V7

# Inspection Type

# **Fire Door Condition**

- × The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- X When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached

| Replace fire door with FD30s fire rated door.                  | TIMESCALE           |
|--|---------------------|
| The fire door is damaged beyond repair.                        | SHORT TERM          |
| REFERENCE RB-21KJED DUE 22/04/2025<br>CATEGORY Building: Doors | PROPERTY PROTECTION |
| Adjust door alignment.   | TIMESCALE           |
| Door gaps exceed safe guidelines.                              | SHORT TERM          |
| REFERENCE RB-ZXPXGH DUE 22/04/2025<br>CATEGORY Building: Doors | PROPERTY PROTECTION |

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



FULL ACCESS

| Fit a fire door keep locked shut sign.<br>REFERENCE RB-G8WPE5 DUE 22/04/2025<br>CATEGORY Building: Doors | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |
|--|--|
| Fit intumescent seals to the door frame.   | TIMESCALE  |
| Seals are damaged or missing in sections of the frame.   | SHORT TERM   |
| REFERENCE RB-AZ3U42 DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Reduce gaps between the door and the door frame.   | TIMESCALE  |
| To ensure heat and smoke cannot pass through to escape route.  | SHORT TERM   |
| REFERENCE RB-B242KE DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Replace hinges with BS EN standard fire door hinges.   | TIMESCALE  |
| All fire doors are required to have 3 hinges, which must be fire certified.                              | SHORT TERM   |
| REFERENCE RB-QEKMI4 DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |



# Fire Door RB-P3GWYN 👽 FD30

Item Fire Door

**Fire Resistance** FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish



Floor / Location GF / Howard Building

**1** Action

Intumescent & Smoke Seals None

Self-Closing Devices None

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection





Office V15

# Inspection Type

## **Fire Door Condition**

× The leaf and frame are adequately specified

# Replace door with FD30s rated fire door.

The door is not fit for purpose. Panelled door has been refaced.

### REFERENCE RB-6VQXKD DUE No Due Date

LIMITED, OCCUPANT DID NOT ANSWER

**NO TIMESCALE** 

**NO SEVERITY** 







**Item** Fire Door

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish Floor / Location GF / Howard Building



Frame Finish Paint Finish



LIMITED ACCESS

Office V1

# Inspection Type

**Fire Door Condition** 

× The leaf and frame are adequately specified

| Replace door with FD30s rated fire door.   | TIMESCALE           |
|--|---------------------|
| The door is not fit for purpose - located in a panelled partition - original panelled door has been refaced. | SHORT TERM          |
| REFERENCE RB-89HAND DUE 22/04/2025   | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
|  |                     |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 121 370

RiskBase

# Fire Door RB-QWSMXS 🔮 FD30

**Item** Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish





**3 Actions** 

Floor / Location

GF / Howard Building

None

Self-Closing Devices None

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





Meter room

.....

# Inspection Type

# **Fire Door Condition**

- × The leaf and frame are adequately specified
- ✓ There is no damage significant enough to affect the fire integrity of the leaf or frame
- ✓ Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present

| Fit intumescent seals to the door frame.               | TIMESCALE           |
|--|---------------------|
| Seals are damaged or missing in sections of the frame. | SHORT TERM          |
| REFERENCE RB-VH3Z15 DUE 22/04/2025                     | SEVERITY            |
| CATEGORY Building: Doors                               | PROPERTY PROTECTION |
| Replace door with FD30s rated fire door.               | TIMESCALE           |
| The door is not fit for purpose.                       | SHORT TERM          |
| REFERENCE RB-BXRMFX DUE 22/04/2025                     | SEVERITY            |
| CATEGORY Building: Doors                               | PROPERTY PROTECTION |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 122 370



FULL ACCESS

Replace hinges with BS EN standard fire door hinges. All fire doors are required to have 3 hinges, which must be fire certified.

REFERENCE RB-DK1LLF DUE 22/04/2025 CATEGORY Building: Doors

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 123 370 V Risk Base



# Fire Door RB-RCZR6Q 🛛 🕫 FD30



Item Fire Door

**Fire Resistance** 

FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish



Intumescent & Smoke Seals

None

**1** Action

GF / Howard Building

Floor / Location

Self-Closing Devices Overhead

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



71



V9 Kitchen

FULL ACCESS

# **Inspection Type**

# **Fire Door Condition**

× The leaf and frame are adequately specified

### Replace door with FD30s rated fire door. The door is not fit for purpose. Panelled door has been refaced.

REFERENCE RB-BRLAUN DUE 22/04/2025

# CATEGORY Building: Doors

259

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 124 370



# Fire Door RB-SQWDQ7



**Item** Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

### Leaf Vision Panels Yes - Fire Rated



Threshold 13mm

Intumescent & Smoke Seals None

Self-Closing Devices Overhead

Floor / Location

GF / Howard Building

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





Business opportunity centre

### **Inspection Type**

### FULL ACCESS

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- V When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached





| Fit intumescent seals to the door frame.  | TIMESCALE           |
|---|---------------------|
| Seals are damaged or missing in sections of the frame.  | SHORT TERM          |
| REFERENCE RB-D65AZ2 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.  | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.   | SHORT TERM          |
| REFERENCE RB-VJS9MM DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| <b>Replace door with FD30s rated fire door.</b><br>The door is not fit for purpose - leading edges are radius edge suggesting this door set was | NO TIMESCALE        |
| originally double action.<br>REFERENCE <b>RB-VZMV3A</b> DUE <b>No Due Date</b>  | NO SEVERITY         |
|   |                     |
| Replace hinges with BS EN standard fire door hinges.  | TIMESCALE           |
| All fire doors are required to have 3 hinges, which must be fire certified.   | SHORT TERM          |
| REFERENCE RB-5RD73H DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |



# Fire Door RB-UDMK9Q 🔮 FD30

ltem

Fire Door

Fire Resistance FD30

Certification None

Leaf Configuration Single Leaf - Single Acting


**Leaf Finish** Paint Finish

Frame Finish Paint Finish



**1** Action





Intumescent & Smoke Seals None

Self-Closing Devices Overhead



**Cleaners Store** 

Inspection Type

Fire Door ConditionX The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose. Panelled door, no test evidence.

REFERENCE RB-I722ER DUE 22/04/2025 CATEGORY Building: Doors LIMITED ACCESS

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 127 370



# Fire Door RB-VMJ3MB 🛛 🕏 FD30

Item

Fire Door

**Fire Resistance** FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish



**6** Actions

Floor / Location GF / Howard Building


Intumescent & Smoke Seals None

Self-Closing Devices None

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 





V13 inner treatment room

# Inspection Type

# **Fire Door Condition**

- × The leaf and frame are adequately specified
- There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- × When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached

### Replace hinges with BS EN standard fire door hinges.

All fire doors are required to have 3 hinges, which must be fire certified.


REFERENCE RB-KB961K DUE 22/04/2025 CATEGORY Building: Doors

FULL ACCESS

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

**Risk**Base 128 370



| Replace door with FD30s rated fire door.   | TIMESCALE  |
|--|--|
| The door is not fit for purpose.   | SHORT TERM   |
| REFERENCE RB-WZEF7A DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Reduce gaps between the door and the door frame.   | TIMESCALE  |
| To ensure heat and smoke cannot pass through to escape route.  | SHORT TERM   |
| REFERENCE RB-WUEBN1 DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Fit intumescent seals to the door frame.   | TIMESCALE  |
| Seals are damaged or missing in sections of the frame.   | SHORT TERM   |
| REFERENCE RB-73Z4VQ DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Fit a fire door keep locked shut sign.<br>REFERENCE RB-7CN911 DUE 22/04/2025<br>CATEGORY Building: Doors | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |
| Adjust door alignment.   | TIMESCALE  |
| Door gaps exceed safe guidelines.  | SHORT TERM   |
| REFERENCE RB-51RCZN DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| 262  |  |



# Fire Door RB-WKRB86



**Item** Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish



.....

Floor / Location

GF / Howard Building

Intumescent & Smoke Seals None

Self-Closing Devices None

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection





Boardroom

Inspection Type

# **Fire Door Condition**

× The leaf and frame are adequately specified

# Replace door with FD30s rated fire door.

The door is not fit for purpose. Original panelled door.

REFERENCE RB-VMA461 DUE No Due Date

LIMITED, OCCUPANT DID NOT ANSWER

NO TIMESCALE

**NO SEVERITY** 

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 130 370



# Fire Door RB-XWDYWQ 🛛 🕏 Not Rated



Item Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting


Leaf Finish Wood Finish Floor / Location GF / Howard Building

**1** Action



Frame Finish Metal Finish

Leaf Vision Panels Yes - Fire Rated



Reception corridor # 2

Inspection Type

**Fire Door Condition** × The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - timber door fitted in an aluminium frame.

REFERENCE RB-AF31X3 DUE 22/04/2025 CATEGORY Building: Doors


LIMITED ACCESS

SHORT TERM

SEVERITY PROPERTY PROTECTION

**Risk**Base

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 131 370



**Item** Fire Door

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish Floor / Location GF / Howard Building



Frame Finish Paint Finish



LIMITED ACCESS

Office V2

Inspection Type

# **Fire Door Condition**

 The leaf and frame are adequately specified
 Replace door with FD30s rated fire door. The door is not fit for purpose - fitted in a panelled partition. Original door has been re- faced.
 REFERENCE RB-DFT3MT\_DUE 22/04/2025 CATEGORY Building: Doors
 Severity PROPERTY PROTECTION





# Fire Door RB-Y66BKF 🛛 🕏 Not Rated



**1** Action

Floor / Location GF / Howard Building



**Fire Resistance** Not Rated

Item

Fire Door

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Male WC

# A Additional Photos



# **Inspection Type**

### **Fire Door Condition**

× The leaf and frame are adequately specified Replace door with FD30s rated fire door. **NO TIMESCALE** The door is not fit for purpose, uncertified, badly damaged and fitted in a panelled partition. REFERENCE RB-M2RQXA DUE No Due Date **NO SEVERITY** 

FULL ACCESS

**Risk**Base RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 133 370

# Fire Door RB-Z932V9 🛛 🔊 FD30



Item Fire Door

**Fire Resistance** FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish

Paint Finish



GF / Howard Building

**1** Action

Floor / Location


Intumescent & Smoke Seals None

Self-Closing Devices None

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 





Server room

# **Fire Door Condition**

**Inspection Type** 

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose 38mm hollow.

REFERENCE RB-QNI3M4 DUE 22/04/2025 CATEGORY Building: Doors

FULL ACCESS

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 134 370



# Fire Door RB-9KTZBJ 🛛 🕏 FD30



Floor / Location

Intumescent Only

Self-Closing Devices

Last Full Inspection

Last Inspection Type

**Full Access Inspection** 

Overhead

22/01/2025

Yes

Intumescent & Smoke Seals

**Electrical Hold Open Device** 

GF / Kitchen

**Item** Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No



### A Additional Photos



# Inspection Type

# Fire Door Condition

- × The leaf and frame are adequately specified
- There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- × When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached



FULL ACCESS

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 1



80

| Replace hinges with BS EN standard fire door hinges.                        | TIMESCALE           |
|---|---------------------|
| All fire doors are required to have 3 hinges, which must be fire certified. | SHORT TERM          |
| REFERENCE RB-U66UXR DUE 22/04/2025<br>CATEGORY Building: Doors              | PROPERTY PROTECTION |
| Adjust door alignment.  | TIMESCALE           |
| Door gaps exceed safe guidelines.   | SHORT TERM          |
| REFERENCE RB-9KP9TR DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.                                    | TIMESCALE           |
| Seals are damaged or missing in sections of the frame.                      | SHORT TERM          |
| REFERENCE RB-58HGP2 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.                            | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.               | SHORT TERM          |
| REFERENCE RB-LEIPIC DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust the door closer.   | TIMESCALE           |
| The door does not close-in-line if released from an open position.          | SHORT TERM          |
| REFERENCE RB-RUYTEC DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust the door closer for the door to latch closed.                        | TIMESCALE           |
| The door does not close in-line if released from an open position.          | SHORT TERM          |
| REFERENCE RB-1832TT DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |



# Fire Door RB-DB1BKP 🛛 🕏 Not Rated

**Item** Fire Door

Fire Resistance

Certification None


Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Side & Overhead Panels No



**1** Action

Floor / Location

GF / Kitchen

Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

Electrical Hold Open Device Yes





### **Fire Door Condition**

- × The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

**Replace fire door with FD30s fire rated door.** The fire door is damaged beyond repair.

REFERENCE RB-3ILLWJ DUE 22/04/2025 CATEGORY Building: Doors TIMESCALE SHORT TERM SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 13



# Fire Door RB-37DAH3 🛛 🕫 FD30



**Item** Fire Door


Fire Resistance FD30

Certification BWF Certifire

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish



Floor / Location GF / Male WC

Intumescent & Smoke Seals Intumescent Only


Self-Closing Devices Overhead

Electrical Hold Open Device No

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection






| Inspection Type   | FULL ACCESS         |
|---|---------------------|
| <ul> <li>Fire Door Condition</li> <li>The leaf and frame are adequately specified</li> <li>There is no damage significant enough to affect the fire integrity of the leaf or frame</li> <li>Gaps around the frame are within tolerance (and/or manufacturers guidelines)</li> <li>Seals are undamaged and well fitted / continuous around the whole leaf or frame</li> <li>Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws pre</li> <li>An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)</li> <li>When closed, the leaf sits against a securely installed stop without distortion</li> <li>Fire door signage correctly identifies door operation and is securely attached</li> </ul> | sent                |
| Adjust door alignment.  | TIMESCALE           |
| Door gaps exceed safe guidelines.   | SHORT TERM          |
| REFERENCE RB-ZJ3NGT DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust the door closer for the door to latch closed.  | TIMESCALE           |
| The door does not close in-line if released from an open position.  | SHORT TERM          |
| REFERENCE RB-VJUA8M DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 138 370



| Fit intumescent seals to the door frame.                                    | TIMESCALE           |
|---|---------------------|
| Seals are damaged or missing in sections of the frame.                      | SHORT TERM          |
| REFERENCE RB-ZPZQZN DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.                            | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.               | SHORT TERM          |
| REFERENCE RB-Q41Q9S DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Replace hinges with BS EN standard fire door hinges.                        | TIMESCALE           |
| All fire doors are required to have 3 hinges, which must be fire certified. | SHORT TERM          |
| REFERENCE RB-DRCY3G DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |





ltem

Fire Door

**Fire Resistance** FD30

Floor / Location GF / Meeting Room 1



Last Limited Inspection 22/01/2025


Last Inspection Type Limited Access Inspection



Inspection Type

LIMITED, OCCUPANT DID NOT ANSWER





**ltem** Fire Door

Fire Resistance

FD30

Certification None Floor / Location GF / Patra



GF / Patra

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection




.....

Inspection Type

LIMITED, OCCUPANT DID NOT ANSWER

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 141 370





ltem

FD30

None

Fire Door

**Fire Resistance** 

Certification

Leaf Finish Paint Finish

Frame Finish

Paint Finish

Leaf Configuration Single Leaf - Single Acting



**6** Actions

Floor / Location GF / Patra Corridor Lobby

Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025


Last Inspection Type **Full Access Inspection** 




85

Leaf Vision Panels

Yes - Fire Rated



# A Additional Photos



**Inspection Type** 

FULL ACCESS




# **Fire Door Condition**

- × The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- ✓ Seals are undamaged and well fitted / continuous around the whole leaf or frame
- ✓ Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- ✓ Fire door signage correctly identifies door operation and is securely attached

| Adjust door alignment.  | TIMESCALE           |
|---|---------------------|
| Door gaps exceed safe guidelines.   | SHORT TERM          |
| REFERENCE RB-21 AVW8 DUE 22/04/2025   | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust the closer to ensure the door sits flush with the rebate.  | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.   | SHORT TERM          |
| REFERENCE RB-HQQRLE DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| <b>Confirm glazing meets BS EN fire regulations.</b>  | TIMESCALE           |
| Ensure the integrity of the fire door.  | SHORT TERM          |
| REFERENCE RB-C4P96K DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.  | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.   | SHORT TERM          |
| REFERENCE <b>RB-SE2J82</b> DUE 22/04/2025   | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Address morticing of frame jambs both sides.<br>Certification.  | NO TIMESCALE        |
| REFERENCE RB-6R9Z1W DUE No Due Date   | NO SEVERITY         |
| Mag lock negates fire certification.<br>Door doesn't close against jamb, headroom of 2.0m not achieved. | NO TIMESCALE        |
| REFERENCE RB-83JRFP DUE No Due Date   | NO SEVERITY         |





ltem

Fire Door


**Fire Resistance** FD30

Floor / Location GF / Patra ITSuite



Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



Inspection Type

LIMITED, OCCUPANT DID NOT ANSWER

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 144 370



### Fire Door RB-G8Z1TF 🛛 🕏 Not Rated



Floor / Location

GF / Patra interview

**1** Action

Fire Resistance Not Rated

Item

Fire Door


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels No




Intumescent & Smoke Seals None

Self-Closing Devices None

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



### **Inspection Type**

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- When closed, the leaf sits against a securely installed stop without distortion  $\checkmark$
- × Fire door signage correctly identifies door operation and is securely attached

### Replace door with FD30s rated fire door. The door is not fit for purpose.

REFERENCE RB-PTKCBM DUE 22/04/2025 CATEGORY Building: Doors

**PROPERTY PROTECTION** 

SHORT TERM

FULL ACCESS



### Fire Door RB-HEUGL8



Floor / Location GF / Stair lobby #14



Fire Resistance FD30

Item

Fire Door

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish Gaps Head 11mm Hinge 4mm Closing 9mm Threshold 11mm

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



### Inspection Type

FULL ACCESS

#### **Fire Door Condition**

- X The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- imes Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- × An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

Replace fire door with FD30s fire rated door.<br/>The fire door is damaged beyond repair.TIMESCALE<br/>SHORT TERMREFERENCE RB-JSMFKU DUE 22/04/2025<br/>CATEGORY Building: DoorsSEVERITY<br/>PROPERTY PROTECTION



### Fire Door RB-SNGHXD



**Item** Fire Door

Fire Resistance


FD30

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Vision Panels Yes - Fire Rated

Side & Overhead Panels Yes - Glazed



Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

Floor / Location

GF / Stair lobby

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





#### Inspection Type

#### **Fire Door Condition**

- X The leaf and frame are adequately specified
- There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- × When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

Replace door with FD30s rated fire door. The door is not fit for purpose.

REFERENCE RB-DDHLKN DUE 22/04/2025

CATEGORY Building: Doors

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 147 370

FULL ACCESS



SEVERITY PROPERTY PROTECTION







**Fire Resistance** FD30

Certification None

GF / Store / Void


Floor / Location

1 Action



Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



| Inspection Type   | LIMITED, OCCUPANT DID NOT<br>Answer |
|---|-------------------------------------|
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door survey. | NO TIMESCALE                        |
| REFERENCE RB-1AD7JM DUE No Due Date   | NO SEVERITY                         |







**1** Action

GF / Store next to unit 38

ltem Fire Door

**Fire Resistance** Not Rated

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Floor / Location

Leaf Vision Panels Yes - Non Fire Rated

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection





| Inspection Type   | LIMITED, OCCUPANT DID NOT<br>Answer |
|---|-------------------------------------|
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door survey. | NO TIMESCALE                        |
| REFERENCE RB-CIETZ1 DUE No Due Date   | NO SEVERITY                         |







2 Actions



Item Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Non Fire Rated

Floor / Location

GF / Unit 1

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



### **Inspection Type**

Have the door fully inspected by a competent person. The assessor had limited access to the door during the routine door survey.

REFERENCE RB-1Y2KHN DUE 22/04/2025 CATEGORY Building: Doors

### **Fire Door Condition**

X The leaf and frame are adequately specified

The door is not fit for purpose - panelled door, 2 x GG type.

Replace door with FD30s rated fire door.

REFERENCE RB-7IVEQX DUE 22/04/2025

CATEGORY Building: Doors

**ANSWER** SHORT TERM

LIMITED, OCCUPANT DID NOT

SEVERITY PROPERTY PROTECTION

TIMESCALE SHORT TERM

SEVERITY **PROPERTY PROTECTION** 





**1** Action

Floor / Location

GF / Unit 2

ltem Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish Frame Finish

Paint Finish

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



93

Inspection Type

**Fire Door Condition** 

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm hollow.

REFERENCE RB-R78YT2 DUE No Due Date

FULL ACCESS

**NO TIMESCALE** 

**NO SEVERITY** 







**Fire Resistance** Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Floor / Location

GF / Unit 3

Last Full Inspection 22/01/2025

**1** Action

Last Inspection Type **Full Access Inspection** 





Inspection Type

### **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm hollow.


REFERENCE RB-3E1C36 DUE No Due Date

FULL ACCESS

**NO TIMESCALE** 

**NO SEVERITY** 





Not Rated



Fire Resistance Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish Frame Finish Paint Finish

Floor / Location

GF / Unit 4

Last Full Inspection 22/01/2025

**1** Action

Last Inspection Type Full Access Inspection





### Inspection Type

### **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm hollow.

REFERENCE RB-Z8JMN2 DUE No Due Date

FULL ACCESS

NO TIMESCALE

**NO SEVERITY** 







**Fire Resistance** Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish


Floor / Location

GF / Unit 5

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 





Inspection Type

### **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose 38mm hollow.

REFERENCE RB-M8JC7U DUE No Due Date

FULL ACCESS

**NO TIMESCALE** 

**NO SEVERITY** 







2 Actions

Floor / Location

GF / Unit 6

ltem Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



| Inspection Type  | FULL ACCESS  |
|--|--|
| Fire Door Condition  X The leaf and frame are adequately specified   |  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.<br>REFERENCE RB-N2ADED DUE 22/04/2025<br>CATEGORY Building: Doors | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |
| Door is domestic 38mm nfr leaf.<br>Certification.  | NO TIMESCALE   |
| REFERENCE RB-SK8NYF DUE No Due Date  | NO SEVERITY  |

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ

**Risk**Base 155 370



Fire Resistance FD30 Floor / Location GF / Unit 10



Last Limited Inspection

22/01/2025

Last Inspection Type Limited Access Inspection



.....

Inspection Type

LIMITED, OCCUPANT DID NOT ANSWER







**Fire Resistance** 

FD30

Floor / Location GF / Unit 11



Last Limited Inspection 22/01/2025


Last Inspection Type Limited Access Inspection



Inspection Type

LIMITED, OCCUPANT DID NOT ANSWER





**Fire Resistance** FD30

Floor / Location GF / Unit 12



Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



Inspection Type

LIMITED, OCCUPANT DID NOT ANSWER







Floor / Location

**1** Action



Item Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish Frame Finish Paint Finish

GF / Unit 13

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



### Inspection Type

### **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose.

REFERENCE RB-5CDU9P DUE 22/04/2025 CATEGORY Building: Doors

FULL ACCESS

TIMESCALE SHORT TERM SEVERITY **PROPERTY PROTECTION** 





**Fire Resistance** FD30

Floor / Location GF / Unit 14



Last Limited Inspection 22/01/2025


Last Inspection Type Limited Access Inspection



Inspection Type

LIMITED, OCCUPANT DID NOT ANSWER







Floor / Location GF / Unit 15

1 Action



Item Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



Inspection Type

**Fire Door Condition** 

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm hollow.

REFERENCE RB-BY51QA DUE No Due Date

**NO TIMESCALE** 

LIMITED, OCCUPANT DID NOT

ANSWER

**NO SEVERITY** 



### Fire Door RB-U5UZU4 🛛 🗢 Not Rated



ltem Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish Frame Finish

Floor / Location

GF / Unit 16

Paint Finish


Last Limited Inspection 22/01/2025

2 Actions

Last Inspection Type Limited Access Inspection



104





| Inspection Type   | LIMITED, OCCUPANT DID NOT<br>ANSWER |
|---|-------------------------------------|
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door survey. | TIMESCALE<br><b>SHORT TERM</b>      |
| REFERENCE RB-CDS6ER DUE 22/04/2025<br>CATEGORY Building: Doors  | SEVERITY<br>PROPERTY PROTECTION     |
| Fire Door Condition X The leaf and frame are adequately specified   |                                     |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow.  | NO TIMESCALE                        |

REFERENCE RB-6MCAJQ DUE No Due Date

**NO SEVERITY** 

**Risk**Base

### Fire Door RB-DEUWJF 🛛 🗢 Not Rated



Floor / Location GF / Unit 17



**Item** Fire Door

Fire Resistance Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

REFERENCE RB-2XJTUE DUE No Due Date

**Leaf Finish** Paint Finish

Frame Finish Paint Finish



| Inspection Type   | LIMITED ACCESS   |
|---|--|
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door survey.<br>REFERENCE RB-RAIVR8 DUE 22/04/2025<br>CATEGORY Building: Doors | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |
| Fire Door Condition  X The leaf and frame are adequately specified  |  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow.  | NO TIMESCALE   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 163 370



**NO SEVERITY** 





2 Actions

Item Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish Floor / Location GF / Unit 18

Frame Finish Paint Finish

Last Limited Inspection 22/01/2025

Last Inspection Type



106 

LIMITED, OCCUPANT DID NOT Inspection Type **ANSWER** Have the door fully inspected by a competent person. SHORT TERM The assessor had limited access to the door during the routine door survey. REFERENCE RB-E284KB DUE 22/04/2025 SEVERITY PROPERTY PROTECTION CATEGORY Building: Doors **Fire Door Condition** 

X The leaf and frame are adequately specified

The door is not fit for purpose - 38mm hollow.

Replace door with FD30s rated fire door.

REFERENCE RB-ANUYNW DUE No Due Date

**NO TIMESCALE** 

**NO SEVERITY** 

Limited Access Inspection



### Fire Door RB-5ARPDA 🛛 🗢 Not Rated

2 Actions

Floor / Location GF / Unit 19



Fire Door

ltem

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



| Have the door fully inspected by a competent person.       TIMESCALE         The assessor had limited access to the door during the routine door survey.       SHORT TERM         REFERENCE RB-B91S2V       DUE 22/04/2025         CATEGORY Building: Doors       SEVERITY | Inspection Type | LIMITED, OCCUPANT DID NOT<br>ANSWER |
|--|-----------------|-------------------------------------|
|  |                 |                                     |
|  |                 |                                     |

### **Fire Door Condition**

X The leaf and frame are adequately specified

#### Replace door with FD30s rated fire door.

The door is not fit for purpose - 38mm hollow.

REFERENCE RB-T1WCN7 DUE No Due Date

**NO TIMESCALE** 

**NO SEVERITY** 



### Fire Door RB-NY5RCM 🛛 🔊 Not Rated

**Item** Fire Door

Fire Resistance Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

GF / Unit 20

Floor / Location

Frame Finish Paint Finish

Last Limited Inspection 22/01/2025

2 Actions

Last Inspection Type Limited Access Inspection





Inspection Type

Have the door fully inspected by a competent person. The assessor had limited access to the door during the routine door survey.

REFERENCE RB-7LP8JH DUE 22/04/2025 CATEGORY Building: Doors

### **Fire Door Condition**

X The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose.

REFERENCE RB-WZSI7V DUE 22/04/2025 CATEGORY Building: Doors LIMITED, OCCUPANT DID NOT ANSWER


> TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

> TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION





**Fire Resistance** Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Floor / Location

GF / Unit 21

Last Full Inspection 22/01/2025

**1** Action

Last Inspection Type **Full Access Inspection** 





Inspection Type

### **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm hollow.


REFERENCE RB-MMZ37Z DUE No Due Date

FULL ACCESS

**NO TIMESCALE** 

**NO SEVERITY** 







**1** Action

Floor / Location GF / Unit 22



Fire Door

Item

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



### Inspection Type

**Fire Door Condition** 

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm hollow.

REFERENCE RB-QNWGNB DUE No Due Date

**NO TIMESCALE** 

LIMITED, OCCUPANT DID NOT

**ANSWER** 

**NO SEVERITY** 







2 Actions

ltem Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Floor / Location GF / Unit 23

Leaf Finish Paint Finish

Frame Finish Paint Finish



| LIMITED ACCESS |
|----------------|
| NO TIMESCALE   |
| NO SEVERITY    |
|                |
|                |

| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow. | <b>NO TIMESCALE</b> |
|--|---------------------|
| REFERENCE RB-IB159G DUE No Due Date  | NO SEVERITY         |



**Risk**Base

111



2 Actions



ltem Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

GF / Unit 24

Floor / Location

Frame Finish Paint Finish

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



| Inspection Type   | LIMITED, OCCUPANT DID NOT<br>Answer |
|---|-------------------------------------|
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door survey. | NO TIMESCALE                        |
| REFERENCE RB-SGCZQN DUE No Due Date   | NO SEVERITY                         |
| Fire Door Condition   |                                     |

X The leaf and frame are adequately specified

Replace door with FD30s rated fire door.

The door is not fit for purpose - 38mm hollow.

REFERENCE RB-94GSA7 DUE No Due Date

**NO TIMESCALE** 

**NO SEVERITY** 







Floor / Location

2 Actions



ltem Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

GF / Unit 25

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



| Inspection Type   | LIMITED, OCCUPANT DID NOT<br>ANSWER |
|---|-------------------------------------|
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door survey. | NO TIMESCALE                        |
| REFERENCE RB-FZZSWN DUE No Due Date   | NO SEVERITY                         |

### **Fire Door Condition**

X The leaf and frame are adequately specified


Replace door with FD30s rated fire door.

The door is not fit for purpose - 38mm hollow. REFERENCE RB-WE11DN DUE No Due Date

**NO TIMESCALE** 

**NO SEVERITY** 









GF / Unit 26

Item Fire Door

**Fire Resistance** Not Rated

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Non Fire Rated

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



| Inspection Type   | LIMITED, OCCUPANT DID NOT<br>Answer |
|---|-------------------------------------|
| Have the door fully inspected by a competent person.                        | TIMESCALE                           |
| The assessor had limited access to the door during the routine door survey. | SHORT TERM                          |
| REFERENCE RB-VLRH14 DUE 22/04/2025  | SEVERITY                            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION                 |

### **Fire Door Condition**

X The leaf and frame are adequately specified

### Replace door with FD30s rated fire door.

The door is not fit for purpose 38mm hollow.

REFERENCE RB-914Z8Y DUE No Due Date

**NO TIMESCALE** 

**NO SEVERITY** 







Floor / Location

GF / Unit 27

ltem Fire Door

**Fire Resistance** Not Rated

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Non Fire Rated

Last Limited Inspection 22/01/2025

1 Action


Last Inspection Type Limited Access Inspection



115

| Inspection Type   | LIMITED, OCCUPANT DID NOT<br>ANSWER |
|---|-------------------------------------|
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door survey. | NO TIMESCALE                        |
| REFERENCE RB-WCS653 DUE No Due Date   | NO SEVERITY                         |







1 Action

ltem Fire Door

**Fire Resistance** Not Rated

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels

Floor / Location

GF / Unit 27a

Yes - Non Fire Rated

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



| Inspection Type   | LIMITED, OCCUPANT DID NOT<br>ANSWER |
|---|-------------------------------------|
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door survey. | <b>NO TIMESCALE</b>                 |
| REFERENCE RB-28ZNCT DUE No Due Date   | NO SEVERITY                         |







Floor / Location GF / Unit 29

**1** Action



Fire Door

Item

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Single Leaf - Single Acting


Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Non Fire Rated

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



### **Inspection Type**

### **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm hollow.

REFERENCE RB-U15T6C DUE 22/04/2025 CATEGORY Building: Doors

FULL ACCESS

TIMESCALE SHORT TERM SEVERITY

**PROPERTY PROTECTION** 



### Fire Door RB-26HCY2 🔮 🕫



**Item** Fire Door

Fire Resistance


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Metal Finish

Frame Finish Metal Finish

Leaf Vision Panels No



Floor / Location

GF / Unit 30

Intumescent & Smoke Seals None

Self-Closing Devices None

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





Inspection Type

### **Fire Door Condition**

- × The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- × Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- ✓ When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached

| Replace fire door with FD30s fire rated door.             | TIMESCALE           |
|---|---------------------|
| The fire door is damaged beyond repair.                   | SHORT TERM          |
| REFERENCE RB-XBHAHG DUE 22/04/2025                        | SEVERITY            |
| CATEGORY Building: Doors                                  | PROPERTY PROTECTION |
| Steel partition door, no test evidence.<br>Certification. | NO TIMESCALE        |
|   |                     |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 17



**FULL ACCESS** 

118

### Fire Door RB-UXZU7D 🛛 🔊 🕫



**Item** Fire Door

Fire Resistance


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Metal Finish

Frame Finish Metal Finish

Leaf Vision Panels No



## .....

Floor / Location

GF / Unit 31

Intumescent & Smoke Seals None

Self-Closing Devices None

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





**FULL ACCESS** 


| Inspection | Туре |
|------------|------|
|------------|------|

### **Fire Door Condition**

- × The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- × Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- × When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached

| <b>Replace door with FD30s rated fire door.</b><br>The door is not fit for purpose. | NO TIMESCALE |
|---|--------------|
| REFERENCE RB-CBXXKM DUE No Due Date   | NO SEVERITY  |
| Steel partition door, no test evidence.<br>Certification.                           | NO TIMESCALE |
|   |              |





Fire Resistance FD30

Certification None

Leaf Configuration Single Leaf - Single Acting

**Leaf Finish** Metal Finish

Frame Finish Metal Finish

Leaf Vision Panels No

Floor / Location GF / Unit 32




Gaps Head 8mm Hinge 4mm Threshold 18mm

Intumescent & Smoke Seals None

Self-Closing Devices None









**Fire Resistance** FD30

Certification None

1 Action

Floor / Location

GF / Unit 33

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection





| Inspection Type   | LIMITED, OCCUPANT DID NOT<br>Answer |
|---|-------------------------------------|
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door survey. | NO TIMESCALE                        |
| REFERENCE RB-P127DC DUE No Due Date   | NO SEVERITY                         |



### Fire Door RB-ETVB21 🔮 FD30



**Item** Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No



# .....

Floor / Location

GF / Unit 34

Intumescent & Smoke Seals None

Self-Closing Devices None

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





#### A Additional Photos



### Inspection Type

#### **Fire Door Condition**

X The leaf and frame are adequately specified

# Replace door with FD30s rated fire door. NO TIMESCALE The door is not fit for purpose - no rebate at top of door (steel door set). NO TIMESCALE REFERENCE RB-ZAZ2VP DUE No Due Date NO SEVERITY





**FULL ACCESS** 





Floor / Location GF / Unit 35 / 01

1 Action



ltem Fire Door

**Fire Resistance** Not Rated

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Non Fire Rated



### **Fire Door Condition**

X The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose.

REFERENCE RB-61HA96 DUE 22/04/2025 CATEGORY Building: Doors

TIMESCALE SHORT TERM SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 181 370



## Fire Door RB-CW536F 🛛 🕏 Not Rated

**Item** Fire Door

Fire Resistance Not Rated

Leaf Configuration Single Leaf - Single Acting

**Leaf Finish** Paint Finish

Frame Finish Paint Finish Leaf Vision Panels Yes - Non Fire Rated

Floor / Location

GF / Unit 35

**1** Action

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



Fire Door Condition

Inspection Type

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose.

REFERENCE RB-UCFMW2 DUE No Due Date

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 182 370



<image>

FULL ACCESS

NO TIMESCALE

**NO SEVERITY** 









ltem Fire Door

**Fire Resistance** Not Rated

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish Floor / Location GF / Unit 36



Frame Finish Paint Finish

Leaf Vision Panels Yes - Non Fire Rated



#### **Fire Door Condition**

X The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose.

REFERENCE RB-ZKZXPK DUE 22/04/2025 CATEGORY Building: Doors



RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 183 370



# Fire Door RB-ZNZVWR 🛛 🕏 Not Rated





ltem Fire Door

**Fire Resistance** Not Rated

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish Floor / Location GF / Unit 37



Frame Finish Paint Finish

Leaf Vision Panels Yes - Non Fire Rated



### **Fire Door Condition**

X The leaf and frame are adequately specified


Replace door with FD30s rated fire door. The door is not fit for purpose.

REFERENCE RB-HCZ3BD DUE 22/04/2025 CATEGORY Building: Doors

TIMESCALE SHORT TERM SEVERITY PROPERTY PROTECTION

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 184 370







Floor / Location

GF / Unit 38

1 Action



ltem Fire Door

**Fire Resistance** Not Rated

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Non Fire Rated

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



| Inspection Type   | LIMITED, OCCUPANT DID NOT<br>Answer |
|---|-------------------------------------|
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door survey. | NO TIMESCALE                        |
| REFERENCE RB-BE5P16 DUE No Due Date   | NO SEVERITY                         |

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 185 370







**1** Action Floor / Location



ltem Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish Frame Finish

GF / Unit 40

Paint Finish

Leaf Vision Panels Yes - Non Fire Rated



**Fire Door Condition** 

X The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose.

REFERENCE RB-DYD7XG DUE 22/04/2025 CATEGORY Building: Doors

TIMESCALE SHORT TERM SEVERITY PROPERTY PROTECTION

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 186 370



# Fire Door RB-RFPMJH 🛛 🕏 Not Rated

1 Action

Floor / Location

GF / Unit 41

ltem Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Non Fire Rated



### **Fire Door Condition**

X The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose.

REFERENCE RB-C2Y4GF DUE No Due Date

**NO TIMESCALE** 

**NO SEVERITY** 

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 187 370







ed 1 Action

**Item** Fire Door

Fire Resistance Not Rated

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

GF / Unit 42

Floor / Location

Frame Finish Paint Finish

Leaf Vision Panels Yes - Non Fire Rated



Fire Door Condition

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose.

REFERENCE RB-DYSZZZ DUE 22/04/2025 CATEGORY Building: Doors TIMESCALE SHORT TERM SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 188 370







**1** Action

ltem Fire Door

**Fire Resistance** Not Rated

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish Floor / Location GF / Unit 43



Frame Finish

Paint Finish

Leaf Vision Panels Yes - Non Fire Rated



**Fire Door Condition** 

X The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose.

REFERENCE RB-TRZNQE DUE 22/04/2025 CATEGORY Building: Doors

TIMESCALE SHORT TERM SEVERITY PROPERTY PROTECTION

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 189 370



## Fire Door RB-FLC2UR 🛛 🗢 Not Rated



Floor / Location

**1** Action

Item Fire Door

> **Fire Resistance** Not Rated

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

GF / Unit 44

Leaf Vision Panels No

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



132



#### Inspection Type

## **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm hollow.

REFERENCE RB-MTB4QU DUE No Due Date

**NO TIMESCALE** 

LIMITED, OCCUPANT DID NOT

**ANSWER** 

**NO SEVERITY** 

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 190 370



## Fire Door RB-FJ8R7A 🛛 🕏 Not Rated



Item Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Floor / Location GF / Unit 45

Leaf Vision Panels No

Last Limited Inspection 22/01/2025

**1** Action

Last Inspection Type Limited Access Inspection



133



#### Inspection Type

## **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm hollow.

REFERENCE RB-7X5ZIL DUE No Due Date

**NO TIMESCALE** 

LIMITED, OCCUPANT DID NOT

**ANSWER** 

**NO SEVERITY** 

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 191 370







Floor / Location

GF / Unit 46

**1** Action



**Fire Resistance** Not Rated

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



134

#### **Inspection Type**

## **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm hollow.

REFERENCE RB-V5FI18 DUE 22/04/2025 CATEGORY Building: Doors

FULL ACCESS

TIMESCALE SHORT TERM SEVERITY

**PROPERTY PROTECTION** 

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 192 370







**1** Action

Floor / Location

GF / Unit 47

Item Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



135



### Inspection Type

## **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm hollow.

REFERENCE RB-YDMB7Q DUE No Due Date

FULL ACCESS

**NO TIMESCALE** 

**NO SEVERITY** 

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 193 370



## Fire Door RB-6M1EDY 🛛 👁 Not Rated

**Item** Fire Door

Fire Resistance Not Rated

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish Leaf Vision Panels No

Floor / Location

GF / Unit 48

Last Limited Inspection 22/01/2025

**1** Action

Last Inspection Type Limited Access Inspection



136



#### Inspection Type

Fire Door Condition

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm.

REFERENCE RB-KL37QW DUE No Due Date

NO TIMESCALE

LIMITED, OCCUPANT DID NOT

**ANSWER** 

**NO SEVERITY** 

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 194



## Fire Door RB-NNI1DK 🛛 🔊 Not Rated



**1** Action

Floor / Location

GF / Unit 50

ltem Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Single Leaf - Single Acting


Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Inspection Type

## **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm.


REFERENCE RB-Y27AEB DUE No Due Date

FULL ACCESS

**NO TIMESCALE** 

**NO SEVERITY** 







Floor / Location

GF / Unit 50

**1** Action

Item Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



Inspection Type

#### **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm hollow.

REFERENCE RB-PEMBED DUE No Due Date

**NO TIMESCALE** 

LIMITED, OCCUPANT DID NOT

**ANSWER** 

**NO SEVERITY** 

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 196 370



## Fire Door RB-RA4KPH 🛛 🔊 Not Rated

**1** Action

Floor / Location

GF / Unit 51

Item Fire Door

**Fire Resistance** Not Rated

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels

No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 





### **Inspection Type**

## **Fire Door Condition**

× The leaf and frame are adequately specified

Replace door with FD30s rated fire door. The door is not fit for purpose - 38mm hollow.

REFERENCE RB-RYYX58 DUE 22/04/2025 CATEGORY Building: Doors

FULL ACCESS

TIMESCALE SHORT TERM SEVERITY

**PROPERTY PROTECTION** 

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 197 370



# Fire Door RB-TB6HD7 🔮 FD30



**Item** Fire Door

Fire Resistance FD30

Certification None

Leaf Configuration Single Leaf - Single Acting

× The leaf and frame are adequately specified

Leaf Finish Paint Finish

Frame Finish Paint Finish .....

Floor / Location

GF / Unit 52

Leaf Vision Panels Yes - Fire Rated

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



| Inspection Type   | LIMITED, OCCUPANT DID NOT<br>ANSWER |
|---|-------------------------------------|
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door survey. | NO TIMESCALE                        |
| REFERENCE RB-BJJWXY DUE No Due Date   | NO SEVERITY                         |
| Fire Door Condition   |                                     |

| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - Steel door set, no certification and oversized air transfer grille. | NO TIMESCALE |
|---|--------------|
| REFERENCE RB-NPA4ZY DUE No Due Date   | NO SEVERITY  |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 198 370



## Fire Door RB-QDQ9R3



**Item** Fire Door

Fire Resistance FD30


Certification BWF Certifire

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No



Floor / Location GF / Unit 53

Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

Electrical Hold Open Device No

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection





**FULL ACCESS** 

Inspection Type

### **Fire Door Condition**

- The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached

| Replace hinges with BS EN standard fire door hinges.                        | TIMESCALE           |
|---|---------------------|
| All fire doors are required to have 3 hinges, which must be fire certified. | SHORT TERM          |
| REFERENCE RB-85W98N DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Adjust door alignment.  | TIMESCALE           |
| Door gaps exceed safe guidelines.   | SHORT TERM          |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 199 370



| Adjust the door closer for the door to latch closed.                                | TIMESCALE                       |
|---|---------------------------------|
| The door does not close in-line if released from an open position.                  | SHORT TERM                      |
| REFERENCE RB-8PN43G DUE 22/04/2025  | SEVERITY                        |
| CATEGORY Building: Doors  | PROPERTY PROTECTION             |
| Fit a fire door keep locked shut sign.  | TIMESCALE                       |
| REFERENCE RB-XF4CYH DUE 22/04/2025  | SHORT TERM                      |
| CATEGORY Building: Doors  | SEVERITY<br>PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.                                    | TIMESCALE                       |
| To ensure heat and smoke cannot pass through to escape route.                       | SHORT TERM                      |
| REFERENCE <b>RB-PHVNTN</b> DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors  | PROPERTY PROTECTION             |
| Repair split in head section of frame where closer arm is fitted.<br>Certification. | NO TIMESCALE                    |
| REFERENCE RB-JUX3Y9 DUE No Due Date<br>CATEGORY Building: Doors                     | NO SEVERITY                     |



# Fire Door RB-MNQKSS

Item Fire Door

**Fire Resistance** FD30


Certification **BWF** Certifire

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No



#### A Additional Photos



## **Inspection Type**

### **Fire Door Condition**

- ✓ The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- × Fire door signage correctly identifies door operation and is securely attached



**FD30** 

Intumescent & Smoke Seals Intumescent Only

4 Actions

Self-Closing Devices Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 







**FULL ACCESS** 



RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ

| Add/replace screws in hinges.  | TIMESCALE  |
|--|--|
| Hinges have less than the required three screws.                             | SHORT TERM   |
| REFERENCE RB-Q1FYMF DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Adjust the door closer for the door to latch closed.                         | TIMESCALE  |
| The door does not close in-line if released from an open position.           | SHORT TERM   |
| REFERENCE RB-BW2T98 DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Fit intumescent seals to the door frame.                                     | TIMESCALE  |
| Seals are damaged or missing in sections of the frame.                       | SHORT TERM   |
| REFERENCE RB-6QI6CY DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Fit a fire door keep locked shut sign.<br>REFERENCE RB-Y2DIPK DUE 22/04/2025 | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |



# Fire Door RB-59QWP5

**Item** Fire Door

Fire Resistance FD30

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish Floor / Location GF / Unit 55

**1** Action

**FD30** 





Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



Inspection Type

## FULL ACCESS

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- ✓ When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached

Replace fire door with FD30s fire rated door. The fire door is damaged beyond repair. REFERENCE RB-R2V4BL DUE 22/04/2025

CATEGORY Building: Doors

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

**Risk**Base

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 203 370

# Fire Door RB-E6EE7R 🛛 🕏 FD30



Item Fire Door

**Fire Resistance** FD30


Certification **BWF** Certifire

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No



#### A Additional Photos



## **Inspection Type**

## **Fire Door Condition**

- The leaf and frame are adequately specified
- ✓ There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- ✓ When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached

Floor / Location GF / Unit 56

**4 Actions** 

Intumescent & Smoke Seals Intumescent Only

Self-Closing Devices Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 





**FULL ACCESS** 

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 204 370



| Fit a fire door keep locked shut sign.<br>REFERENCE RB-4JAT6U DUE 22/04/2025<br>CATEGORY Building: Doors | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |
|--|--|
|  |  |
| REFERENCE RB-R2BFZS DUE 22/04/2025   | SEVERITY<br>PROPERTY PROTECTION                            |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.  | TIMESCALE<br>SHORT TERM                                    |
| REFERENCE <b>RB-246GCE</b> DUE 22/04/2025  | SEVERITY<br>PROPERTY PROTECTION                            |
| Fit intumescent seals to the door frame.   | TIMESCALE  |
| Seals are damaged or missing in sections of the frame.   | SHORT TERM   |
|  | PROPERTY PROTECTION  |







**1** Action

Floor / Location GF / Void door - Patra



**Fire Resistance** Not Rated

ltem

Fire Door

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



Blocked off from inside

Inspection Type

Door no longer in use.

REFERENCE RB-21L2AD DUE No Due Date

**NO TIMESCALE** 

LIMITED, OCCUPANT DID NOT

**ANSWER** 

**NO SEVERITY** 

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 206 370



## Fire Door RB-3E3PHK 🛛 🕏 FD30S

ltem

FD30

None

Fire Door

**Fire Resistance** 

Certification

Leaf Finish

Paint Finish

Frame Finish

Leaf Vision Panels Yes - Fire Rated

Paint Finish

Leaf Configuration

Single Leaf - Single Acting



**5** Actions

Floor / Location Ground / Howard Building

Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



146

Side & Overhead Panels Yes - Glazed

## Gaps Head 9mm Hinge Closing 5mm 6mm Threshold 10mm

Interview room A

### Inspection Type

## **Fire Door Condition**

- X The leaf and frame are adequately specified
- There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- X Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- ✓ When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached



**FULL ACCESS** 



| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire certified.<br>REFERENCE RB-6TSLNG DUE 22/04/2025 | TIMESCALE<br>SHORT TERM |
|---|-------------------------|
| CATEGORY Building: Doors  | PROPERTY PROTECTION     |
| Replace door with FD30s rated fire door.  | TIMESCALE               |
| The door is not fit for purpose 40mm door and frame.  | SHORT TERM              |
| REFERENCE RB-F8LYKK DUE 22/04/2025  | SEVERITY                |
| CATEGORY Building: Doors  | PROPERTY PROTECTION     |
| Reduce gaps between the door and the door frame.  | TIMESCALE               |
| To ensure heat and smoke cannot pass through to escape route.   | SHORT TERM              |
| REFERENCE RB-6QZ4MZ DUE 22/04/2025  | SEVERITY                |
| CATEGORY Building: Doors  | PROPERTY PROTECTION     |
| Fit intumescent seals to the door frame.  | TIMESCALE               |
| Seals are damaged or missing in sections of the frame.  | SHORT TERM              |
| REFERENCE <b>RB-EWW6KA</b> DUE 22/04/2025   | SEVERITY                |
| CATEGORY Building: Doors  | PROPERTY PROTECTION     |
| Fit a fire door keep locked shut sign.  | TIMESCALE<br>SHORT TERM |
| REFERENCE RB-V13N9X DUE 22/04/2025  | SEVERITY                |
| CATEGORY Building: Doors  | PROPERTY PROTECTION     |







**5** Actions

Floor / Location Ground / Howard Building



**Fire Resistance** FD30

Item

Fire Door


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Fire Rated



Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices Overhead

Electrical Hold Open Device No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



FMB radio room

A Additional Photos



Inspection Type

**FULL ACCESS** 

#### **Fire Door Condition**

- X The leaf and frame are adequately specified
- There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



- X Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- ✓ When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached

| Replace hinges with BS EN standard fire door hinges.   | TIMESCALE                       |
|--|---------------------------------|
| All fire doors are required to have 3 hinges, which must be fire certified.  | SHORT TERM                      |
| REFERENCE <b>RB-EK3JNH</b> DUE 22/04/2025  | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |
| Replace door with FD30s rated fire door.   | TIMESCALE<br>SHORT TERM         |
| The door is not fit for purpose 40mm door and frame.<br>REFERENCE RB-YUVB1W DUE 22/04/2025<br>CATEGORY Building: Doors | SEVERITY<br>PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.   | TIMESCALE                       |
| To ensure heat and smoke cannot pass through to escape route.  | SHORT TERM                      |
| REFERENCE RB-UF3L3W DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |
| Fit a fire door keep locked shut sign.   | TIMESCALE<br>SHORT TERM         |
| REFERENCE RB-N47PHD DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |
| Adjust door alignment.   | TIMESCALE                       |
| Door gaps exceed safe guidelines.  | SHORT TERM                      |
| REFERENCE RB-H1FGS2 DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |



## Fire Door RB-EXID89 States



ltem Fire Door

**Fire Resistance** FD30

Certification None


Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Fire Rated

Side & Overhead Panels Yes - Glazed



Broadcasting room

## Inspection Type

## **Fire Door Condition**

- X The leaf and frame are adequately specified
- There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- X Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- ✓ When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached



Intumescent & Smoke Seals Intumescent & Smoke

Ground / Howard Building

Self-Closing Devices Overhead

**5** Actions

Floor / Location

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 





**Risk**Base

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 211 370

| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire certified.<br>REFERENCE RB-YX744X DUE 22/04/2025  | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |
|--|--|
| CATEGORY Building: Doors<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose 40mm door and frame.<br>REFERENCE RB-IGY9B9 DUE 22/04/2025         |  |
| CATEGORY Building: Doors Reduce gaps between the door and the door frame. To ensure heat and smoke cannot pass through to escape route. REFERENCE RB-BYI334 DUE 22/04/2025 | PROPERTY PROTECTION<br>TIMESCALE<br>SHORT TERM             |
| CATEGORY Building: Doors<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.   | TIMESCALE<br>SHORT TERM                                    |
| REFERENCE RB-6TUUP3 DUE 22/04/2025<br>CATEGORY Building: Doors<br>Fit a fire door keep locked shut sign.<br>REFERENCE RB-CP2XIP DUE 22/04/2025                             | SEVERITY<br>PROPERTY PROTECTION<br>TIMESCALE<br>SHORT TERM |
| CATEGORY Building: Doors   | SEVERITY<br>PROPERTY PROTECTION                            |



# Fire Door RB-G366XR 🛛 🕏 FD305



**Fire Resistance** FD30

Item

Fire Door


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance



Intumescent & Smoke Seals Intumescent & Smoke

Ground / Howard Building

**1** Action

Floor / Location

Self-Closing Devices Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025


Last Inspection Type **Full Access Inspection** 



149



Kitchen utility store



#### FULL ACCESS

TIMESCALE SHORT TERM


SEVERITY PROPERTY PROTECTION

**Fire Door Condition** × The leaf and frame are adequately specified

#### Replace door with FD30s rated fire door.

The door is not fit for purpose fails to close due to catching on floor surface and door has dropped so that it will not engage into the frame.

### REFERENCE RB-E4MHW7 DUE 22/04/2025 CATEGORY Building: Doors



RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



## Fire Door RB-RVRETR 🛛 🕏 FD305



Floor / Location Ground / Howard Building

**6** Actions

Item Fire Door

**Fire Resistance** FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance



Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Conference room emergency escape

Inspection Type

FULL ACCESS

#### **Fire Door Condition**

- X The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- × An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

Replace hinges with BS EN standard fire door hinges. All fire doors are required to have 3 hinges, which must be fire certified. REFERENCE RB-9NFQ1E DUE 22/04/2025 CATEGORY Building: Doors





RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ

| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair. Leading edge of door leaf is split and covered by masking tape, door has dropped and does not close freely.<br>REFERENCE RB-XSBY95 DUE 22/04/2025<br>(ATEGORY Building: Doors | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |
|--|--|
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-42B87C DUE 22/04/2025  | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |
| CATEGORY Building: Doors<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-6UGHAL DUE 22/04/2025<br>CATEGORY Building: Doors   | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |
| Replace the door closer.<br>The door does not close-in-line if released from an open position.<br>REFERENCE RB-34VCVT DUE No Due Date  | NO TIMESCALE<br>NO SEVERITY                                |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-JJP9ZS DUE 22/04/2025<br>CATEGORY Building: Doors  | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |







7 Actions

Floor / Location Ground / Howard Building



**Fire Resistance** FD30

Item

Fire Door


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance



Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices Overhead

Electrical Hold Open Device No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Conference room

### A Additional Photos



Inspection Type

## **FULL ACCESS**

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)


RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- X Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- ✓ Fire door signage correctly identifies door operation and is securely attached

| Replace hinges with BS EN standard fire door hinges.  | TIMESCALE                   |
|---|-----------------------------|
| All fire doors are required to have 3 hinges, which must be fire certified.   | SHORT TERM                  |
| REFERENCE RB-375G6W DUE 22/04/2025  | SEVERITY                    |
| CATEGORY Building: Doors  | PROPERTY PROTECTION         |
| Replace door with FD30s rated fire door.  | TIMESCALE                   |
| The door is not fit for purpose - 40mm door and frame.  | SHORT TERM                  |
| REFERENCE RB-ED5SLB DUE 22/04/2025  | SEVERITY                    |
| CATEGORY Building: Doors  | PROPERTY PROTECTION         |
| Reduce gaps between the door and the door frame.  | TIMESCALE                   |
| To ensure heat and smoke cannot pass through to escape route.   | SHORT TERM                  |
| REFERENCE RB-1TB4KL DUE 22/04/2025  | SEVERITY                    |
| CATEGORY Building: Doors  | PROPERTY PROTECTION         |
| Fit intumescent seals to the door frame.  | TIMESCALE                   |
| Seals are damaged or missing in sections of the frame.  | SHORT TERM                  |
| REFERENCE RB-8BJ152 DUE 22/04/2025  | SEVERITY                    |
| CATEGORY Building: Doors  | PROPERTY PROTECTION         |
| Confirm glazing meets BS EN fire regulations. Outer beading missing, glass held in place with steel<br>pins / filler material.<br>Ensure the integrity of the fire door.<br>REFERENCE RB-PHJFCM DUE No Due Date | NO TIMESCALE<br>NO SEVERITY |
| Adjust door alignment.  | TIMESCALE                   |
| Door gaps exceed safe guidelines.   | SHORT TERM                  |
| REFERENCE RB-26D6G8 DUE 22/04/2025  | SEVERITY                    |
| CATEGORY Building: Doors  | PROPERTY PROTECTION         |
| Adjust the closer to ensure the door sits flush with the rebate.  | TIMESCALE                   |
| To ensure heat and smoke cannot pass through to escape route.   | SHORT TERM                  |
| REFERENCE RB-I3N57Y DUE 22/04/2025  | SEVERITY                    |
| CATEGORY Building: Doors  | PROPERTY PROTECTION         |







**5** Actions

Floor / Location Ground / Howard Building

Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



152



Frame Finish

Leaf Finish

Paint Finish

Item Fire Door

FD30

None

**Fire Resistance** 


Certification

Leaf Configuration

Single Leaf - Single Acting

Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance



### Kitchen

### Inspection Type

### **FULL ACCESS**

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- X Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- × When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

Replace hinges with BS EN standard fire door hinges. SHORT TERM All fire doors are required to have 3 hinges, which must be fire certified. REFERENCE RB-ZTB65D DUE 22/04/2025 SEVERITY **PROPERTY PROTECTION** 



RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ

CATEGORY Building: Doors

| Replace door with FD30s rated fire door.                         | TIMESCALE           |
|--|---------------------|
| The door is not fit for purpose.                                 | SHORT TERM          |
| REFERENCE RB-R5GQEF DUE 22/04/2025                               | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.                 | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.    | SHORT TERM          |
| REFERENCE RB-B77PBQ DUE 22/04/2025                               | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
| Adjust the closer to ensure the door sits flush with the rebate. | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.    | SHORT TERM          |
| REFERENCE RB-8TH4JK DUE 22/04/2025                               | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
| Adjust door alignment.   | TIMESCALE           |
| Door gaps exceed safe guidelines.                                | SHORT TERM          |
| REFERENCE RB-M3LU1D DUE 22/04/2025                               | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |



# Fire Door RB-2H5NBL



Fire Door

Item

Fire Resistance FD30

Certification None



# First floor / Howard Building

7 Actions

Floor / Location

Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices Overhead

Electrical Hold Open Device No


Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



153

Female WC





### .ACTION CONTINUED



TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

REFERENCE RB-IURS7E DUE 22/04/2025 CATEGORY Building: Doors

Reduce gaps between the door and the door frame.

To ensure heat and smoke cannot pass through to escape route.



| Fit intumescent seals to the door frame.                           | TIMESCALE           |
|--|---------------------|
| Seals are damaged or missing in sections of the frame.             | SHORT TERM          |
| REFERENCE RB-76CG6G DUE 22/04/2025                                 | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
| Adjust the door closer.  | TIMESCALE           |
| The door does not close-in-line if released from an open position. | SHORT TERM          |
| REFERENCE RB-93GBRS DUE 22/04/2025                                 | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
| Adjust door alignment.   | TIMESCALE           |
| Doors do not close in-line if released from an open position.      | SHORT TERM          |
| REFERENCE RB-47PULN DUE 22/04/2025                                 | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
| Adjust door alignment.   | TIMESCALE           |
| Door gaps exceed safe guidelines.                                  | SHORT TERM          |
| REFERENCE RB-3HPLUZ DUE 22/04/2025                                 | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 221







**Fire Resistance** FD30

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels No

First floor / Howard Building

**1** Action

Floor / Location

Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices None

Electrical Hold Open Device No

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection





Unit T1

### LIMITED, OCCUPANT DID NOT **Inspection Type** ANSWER Have the door fully inspected by a competent person. TIMESCALE SHORT TERM The assessor had limited access to the door during the routine door survey. REFERENCE RB-TTWMC6 DUE 22/04/2025 SEVERITY PROPERTY PROTECTION CATEGORY Building: Doors

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 222 370



154





Fire Resistance FD30

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

First floor / Howard Building

**1** Action

Floor / Location

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection





Unit T2

### LIMITED, OCCUPANT DID NOT **Inspection Type ANSWER** Have the door fully inspected by a competent person. TIMESCALE SHORT TERM The assessor had limited access to the door during the routine door survey. REFERENCE RB-EEPA4K DUE 22/04/2025 SEVERITY PROPERTY PROTECTION CATEGORY Building: Doors

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



# Fire Door RB-4FU1H8



**ltem** Fire Door

Fire Resistance FD30

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels No

First floor / Howard Building

**1** Action

Floor / Location

Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices None

Electrical Hold Open Device No

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



Unit T11

# Inspection Type LIMITED, OCCUPANT DID NOT ANSWER Have the door fully inspected by a competent person. Timescale The assessor had limited access to the door during the routine door survey. SHORT TERM REFERENCE RB-FTENSQ\_DUE 22/04/2025 SEVERITY CATEGORY Building: Doors PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 224 370









Fire Resistance FD30

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Side & Overhead Panels Yes - Glazed

Intumescent & Smoke Seals Intumescent & Smoke

First floor / Howard Building

Self-Closing Devices Overhead

**1** Action

Floor / Location

**Electrical Hold Open Device** Yes

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



Unit T14

### Inspection Type

Have the door fully inspected by a competent person. The assessor had limited access to the door during the routine door survey.

REFERENCE RB-6TA561 DUE 22/04/2025 CATEGORY Building: Doors

LIMITED, OCCUPANT DID NOT ANSWER

TIMESCALE SHORT TERM SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ







**Fire Resistance** FD30

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels No

First floor / Howard Building

Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices None

**1** Action

Floor / Location

Electrical Hold Open Device No

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



158

Unit T5

### LIMITED, OCCUPANT DID NOT **Inspection Type** ANSWER Have the door fully inspected by a competent person. TIMESCALE SHORT TERM The assessor had limited access to the door during the routine door survey. REFERENCE RB-UJXJBP DUE 22/04/2025 SEVERITY PROPERTY PROTECTION CATEGORY Building: Doors

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ



# Fire Door RB-9EN3B8 🛛 🕏 FD30



Item Fire Door

**Fire Resistance** FD30

Certification None


Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Side & Overhead Panels No




Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Stair well





Floor / Location First floor / Howard Building

**5** Actions





| Replace door with FD30s rated fire door.                      | TIMESCALE           |
|---|---------------------|
| The door is not fit for purpose.                              | SHORT TERM          |
| REFERENCE RB-T25BM1 DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.              | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route. | SHORT TERM          |
| REFERENCE <b>RB-HXFIHB</b> DUE 22/04/2025                     | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.                      | TIMESCALE           |
| Seals are damaged or missing in sections of the frame.        | SHORT TERM          |
| REFERENCE RB-XT7INS DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Adjust door alignment.  | TIMESCALE           |
| Door gaps exceed safe guidelines.                             | SHORT TERM          |
| REFERENCE RB-Q69SZ7 DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
|   |                     |








**Fire Resistance** FD30

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

### Side & Overhead Panels Yes - Glazed



### Unit T6

LIMITED, OCCUPANT DID NOT Inspection Type ANSWER Have the door fully inspected by a competent person. TIMESCALE SHORT TERM The assessor had limited access to the door during the routine door survey. REFERENCE RB-9ZK26K DUE 22/04/2025 SEVERITY **PROPERTY PROTECTION** CATEGORY Building: Doors

Intumescent & Smoke Seals Intumescent & Smoke

First floor / Howard Building

Last Limited Inspection 22/01/2025

**1** Action

Floor / Location

Last Inspection Type Limited Access Inspection







# Fire Door RB-9ZUWI7



6 Actions

Floor / Location First floor / Howard Building



Fire Resistance


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Side & Overhead Panels Yes - Glazed



Intumescent & Smoke Seals None

Self-Closing Devices Overhead

Electrical Hold Open Device No

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



Emergency escape lobby

### Inspection Type

### **FULL ACCESS**

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- ✓ When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

Replace hinges with BS EN standard fire door hinges.TIMESCALEAll fire doors are required to have 3 hinges, which must be fire certified.SHORT TERMREFERENCE RB-IKZF83 DUE 22/04/2025<br/>CATEGORY Building: DoorsSEVERITY<br/>PROPERTY PROTECTION




RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 230

**Item** Fire Door

| Replace door with FD30s rated fire door.                      | TIMESCALE           |
|---|---------------------|
| The door is not fit for purpose - 40mm door and frame.        | SHORT TERM          |
| REFERENCE RB-D4VX3T DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.              | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route. | SHORT TERM          |
| REFERENCE RB-6141C9 DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.                      | TIMESCALE           |
| Seals are damaged or missing in sections of the frame.        | SHORT TERM          |
| REFERENCE RB-CKWUQ1 DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Confirm glazing meets BS EN fire regulations.                 | TIMESCALE           |
| Ensure the integrity of the fire door.                        | SHORT TERM          |
| REFERENCE RB-51DFS2 DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Adjust door alignment.  | TIMESCALE           |
| Door gaps exceed safe guidelines.                             | SHORT TERM          |
| REFERENCE RB-R1H4PW DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |





FD30S

**Item** Fire Door

Fire Resistance FD30

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Side & Overhead Panels Yes - Glazed

Gaps Head **5mm** Hinge Closing **5mm** Threshold **7mm** 

Unit T7

### Inspection Type

### **Fire Door Condition**

- X The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- ✓ When closed, the leaf sits against a securely installed stop without distortion
- ✓ Fire door signage correctly identifies door operation and is securely attached



Intumescent & Smoke Seals Intumescent & Smoke

First floor / Howard Building

**6** Actions

Floor / Location

Self-Closing Devices None

Electrical Hold Open Device No

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



### FULL ACCESS



| Replace hinges with BS EN standard fire door hinges.   | TIMESCALE                       |
|--|---------------------------------|
| All fire doors are required to have 3 hinges, which must be fire certified.  | SHORT TERM                      |
| REFERENCE RB-6NKNLL DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |
| Replace door with FD30s rated fire door.   | TIMESCALE                       |
| The door is not fit for purpose. The door and frame have previously been machined for access                                     | SHORT TERM                      |
| control and the frame repaired with an aluminium fillet plate.<br>REFERENCE RB-G7XG4I DUE 22/04/2025<br>CATEGORY Building: Doors | SEVERITY<br>PROPERTY PROTECTION |
|  |                                 |
| Reduce gaps between the door and the door frame.   | TIMESCALE                       |
| To ensure heat and smoke cannot pass through to escape route.  | SHORT TERM                      |
| REFERENCE RB-AYWK1A DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |
| Fit intumescent seals to the door frame.   | TIMESCALE                       |
| Seals are damaged or missing in sections of the frame.   | SHORT TERM                      |
| REFERENCE RB-MKF5EC DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |
| Adjust the door closer for the door to latch closed.   | TIMESCALE                       |
| The door does not close in-line if released from an open position.   | SHORT TERM                      |
| REFERENCE RB-M2GI61 DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |
| Adjust door alignment.   | TIMESCALE                       |
| Door gaps exceed safe guidelines.  | SHORT TERM                      |
| REFERENCE RB-VUDY2P DUE 22/04/2025   | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |








**Fire Resistance** FD30

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Side & Overhead Panels Yes - Glazed



Intumescent & Smoke Seals Intumescent & Smoke

First floor / Howard Building

7 Actions

Floor / Location

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



163

Unit T8 FULL ACCESS Inspection Type

### **Fire Door Condition**

- × The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- When closed, the leaf sits against a securely installed stop without distortion  $\checkmark$
- Fire door signage correctly identifies door operation and is securely attached

### Replace hinges with BS EN standard fire door hinges.

All fire doors are required to have 3 hinges, which must be fire certified.

REFERENCE RB-PIV7DI DUE 22/04/2025 CATEGORY Building: Doors

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

**Risk**Base RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 234 370

| Replace door with FD30s rated fire door.         The door is not fit for purpose door and frame have previously been machined for access control, frame has been repaired with an aluminium fillet plate.         REFERENCE RB-YC3MPA_DUE22/04/2025         CATEGORY Building: Doors | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |
|--|--|
| Reduce gaps between the door and the door frame.   | TIMESCALE  |
| To ensure heat and smoke cannot pass through to escape route.  | SHORT TERM   |
| REFERENCE RB-T9XVBN DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Fit intumescent seals to the door frame.   | TIMESCALE  |
| Seals are damaged or missing in sections of the frame.   | SHORT TERM   |
| REFERENCE RB-YQDBV3 DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Adjust the door closer.  | TIMESCALE  |
| The door does not close-in-lin if released from an open position.  | SHORT TERM   |
| REFERENCE RB-BWKYNQ DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Adjust door alignment.   | TIMESCALE  |
| Door gaps exceed safe guidelines.  | SHORT TERM   |
| REFERENCE RB-HDJDX9 DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Adjust door alignment.   | TIMESCALE  |
| Doors do not close in-line if released from an open position.  | SHORT TERM   |
| REFERENCE RB-1B7HS1 DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |







S 8 Actions

**Item** Fire Door

Fire Resistance FD30

Certification None


Leaf Configuration Double Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance

Side & Overhead Panels No



Intumescent & Smoke Seals Intumescent & Smoke


First floor / Howard Building

Self-Closing Devices Overhead

Electrical Hold Open Device No

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



Corridor next to unit T9

.....

### Inspection Type

### **Fire Door Condition**

- × The leaf and frame are adequately specified
- There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- ✓ Fire door signage correctly identifies door operation and is securely attached

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 236 370



**Risk**Base

| Replace hinges with BS EN standard fire door hinges.                        | TIMESCALE                   |
|---|-----------------------------|
| All fire doors are required to have 3 hinges, which must be fire certified. | SHORT TERM                  |
| REFERENCE RB-UMMIH6 DUE 22/04/2025  | SEVERITY                    |
| CATEGORY Building: Doors  | PROPERTY PROTECTION         |
| Replace door with FD30s rated fire door.                                    | TIMESCALE                   |
| The door is not fit for purpose.  | SHORT TERM                  |
| REFERENCE RB-7V6RGM DUE 22/04/2025  | SEVERITY                    |
| CATEGORY Building: Doors  | PROPERTY PROTECTION         |
| Reduce gaps between the door and the door frame.                            | TIMESCALE                   |
| To ensure heat and smoke cannot pass through to escape route.               | SHORT TERM                  |
| REFERENCE RB-MHLNJ4 DUE 22/04/2025  | SEVERITY                    |
| CATEGORY Building: Doors  | PROPERTY PROTECTION         |
| Fit intumescent seals to the door frame.                                    | TIMESCALE                   |
| Seals are damaged or missing in sections of the frame.                      | SHORT TERM                  |
| REFERENCE <b>RB-ZNTEHH</b> DUE 22/04/2025                                   | SEVERITY                    |
| CATEGORY <b>Building: Doors</b>   | PROPERTY PROTECTION         |
| Adjust door alignment.  | TIMESCALE                   |
| Door gaps exceed safe guidelines.   | SHORT TERM                  |
| REFERENCE RB-MJYV3P DUE 22/04/2025  | SEVERITY                    |
| CATEGORY Building: Doors  | PROPERTY PROTECTION         |
|   |                             |
| Door selector not functional.<br>Certification.                             | NO TIMESCALE                |
|   | NO TIMESCALE<br>NO SEVERITY |
| Certification.  |                             |
| Certification.<br>REFERENCE <b>RB-T7NV4C</b> DUE <b>No Due Date</b>         |                             |
| Certification.<br>REFERENCE RB-T7NV4C DUE No Due Date                       | NO SEVERITY                 |



Reduce gaps between the door and the door frame. To ensure heat and smoke cannot pass through to escape route.


REFERENCE RB-EQGAV6 DUE 22/04/2025 CATEGORY Building: Doors TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 238 370 💎 F



# Fire Door RB-DGAH7G 🛛 🕫 FD305



**Item** Fire Door

Fire Resistance FD30

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Side & Overhead Panels Yes - Glazed Intumescent & Smoke Seals Intumescent & Smoke

First floor / Howard Building

Self-Closing Devices Overhead

Floor / Location

Electrical Hold Open Device Yes

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection





Unit T10

### Inspection Type

Have the door fully inspected by a competent person. The assessor had limited access to the door during the routine door survey.

REFERENCE RB-S68YQJ DUE 22/04/2025 CATEGORY Building: Doors LIMITED, OCCUPANT DID NOT ANSWER

TIMESCALE SHORT TERM SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 239 370



# Fire Door RB-DP9XRM



**Item** Fire Door

Fire Resistance FD30

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Side & Overhead Panels Yes - Glazed Intumescent & Smoke Seals

First floor / Howard Building

**1** Action

Floor / Location


Intumescent & Smoke

Self-Closing Devices Overhead

Electrical Hold Open Device Yes

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



Unit T16

### Inspection Type

Have the door fully inspected by a competent person. The assessor had limited access to the door during the routine door survey.

REFERENCE RB-JVVEK3 DUE 22/04/2025 CATEGORY Building: Doors LIMITED, OCCUPANT DID NOT ANSWER

TIMESCALE SHORT TERM SEVERITY PROPERTY PROTECTION

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 240 370







4 Actions

Floor / Location First floor / Howard Building



**Fire Resistance** FD30

ltem


Fire Door

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Side & Overhead Panels Yes - Glazed



Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices Overhead

**Electrical Hold Open Device** Yes

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Kitchen

### Inspection Type

### **Fire Door Condition**

- × The leaf and frame are adequately specified
- There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- X Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- ✓ When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

### Replace hinges with BS EN standard fire door hinges.

All fire doors are required to have 3 hinges, which must be fire certified.

REFERENCE RB-131FRZ DUE 22/04/2025 CATEGORY Building: Doors

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

FULL ACCESS

**Risk**Base RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 241 370

| Replace door with FD30s rated fire door.                      | TIMESCALE           |
|---|---------------------|
| The door is not fit for purpose.                              | SHORT TERM          |
| REFERENCE RB-CD11Y9 DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.              | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route. | SHORT TERM          |
| REFERENCE RB-TALBMN DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.                      | TIMESCALE           |
| Seals are damaged or missing in sections of the frame.        | SHORT TERM          |
| REFERENCE RB-8UPBSQ DUE 22/04/2025                            | SEVERITY            |
| CATEGORY Building: Doors                                      | PROPERTY PROTECTION |
| 299   |                     |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 242 370 V Risk Base



# Fire Door RB-EKGWZ6



**Item** Fire Door

Fire Resistance FD30


Certification None

Leaf Configuration Double Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance



Intumescent & Smoke Seals

**6** Actions

First / Howard Building

Floor / Location

Self-Closing Devices Overhead

Electrical Hold Open Device No

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



168



Stair lobby

### Inspection Type

### **FULL ACCESS**

**Risk**Base

**Fire Door Condition** 

- X The leaf and frame are adequately specified
- × There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

| Adjust door alignment.             | TIMESCALE           |
|------------------------------------|---------------------|
| Door gaps exceed safe guidelines.  | SHORT TERM          |
| REFERENCE RB-QR82DJ DUE 22/04/2025 | SEVERITY            |
| CATEGORY Building: Doors           | PROPERTY PROTECTION |
|                                    | ACTION CONTINUES    |



### ..ACTION CONTINUED



Adjust the closer to ensure the door sits flush with the rebate. To ensure heat and smoke cannot pass through to escape route.

REFERENCE RB-9FMVZR DUE 22/04/2025 CATEGORY Building: Doors



Fit intumescent seals to the door frame.

Seals are damaged or missing in sections of the frame.

REFERENCE RB-SHEG7F DUE 22/04/2025

CATEGORY Building: Doors

Image: Constraint of the door frame.

Image: Constraint of the door and the door frame.

To ensure heat and smoke cannot pass through to escape route.

REFERENCE RB-SAREC6. DUE 22/04/2025

TIMESCALE SHORT TERM

TIMESCALE SHORT TERM

SEVERITY PROPERTY PROTECTION

SEVERITY PROPERTY PROTECTION

> TIMESCALE SHORT TERM

| REFERENCE RB-S8REC6 DUE 22/04/2025  | SEVERITY            |
|---|---------------------|
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Replace hinges with BS EN standard fire door hinges.                        | TIMESCALE           |
| All fire doors are required to have 3 hinges, which must be fire certified. | SHORT TERM          |
| REFERENCE RB-FG3H7A DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Replace fire door with FD30s fire rated door.                               | TIMESCALE           |
| The fire door is damaged beyond repair.                                     | SHORT TERM          |
| REFERENCE RB-FVL698 DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |









**6** Actions

Floor / Location First floor / Howard Building



**Fire Resistance** FD30

Item


Fire Door

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Side & Overhead Panels Yes - Glazed



Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Unit T17

### Inspection Type

### **Fire Door Condition**

- × The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- × Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- When closed, the leaf sits against a securely installed stop without distortion  $\checkmark$
- Fire door signage correctly identifies door operation and is securely attached

### Replace hinges with BS EN standard fire door hinges.

All fire doors are required to have 3 hinges, which must be fire certified.

REFERENCE RB-HBWD9X DUE 22/04/2025 CATEGORY Building: Doors

SEVERITY PROPERTY PROTECTION

TIMESCALE SHORT TERM

FULL ACCESS



| Replace fire door with FD30s fire rated door.         The fire door is damaged beyond repair. Frame and door machined for access control, frame repaired with an aluminium fillet plate.         REFERENCE RB-MFYX1N_DUE 22/04/2025         CATEGORY Building: Doors | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |
|--|--|
| Reduce gaps between the door and the door frame.   | TIMESCALE  |
| To ensure heat and smoke cannot pass through to escape route.  | SHORT TERM   |
| REFERENCE RB-E9GVAC DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Fit intumescent seals to the door frame.   | TIMESCALE  |
| Seals are damaged or missing in sections of the frame.   | SHORT TERM   |
| REFERENCE RB-VG53F4 DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Adjust the door closer for the door to latch closed.   | TIMESCALE  |
| The door does not close in-line if released from an open position.   | SHORT TERM   |
| REFERENCE RB-WSE4TH DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Adjust door alignment.   | TIMESCALE  |
| Door gaps exceed safe guidelines.  | SHORT TERM   |
| REFERENCE RB-8VZWSV DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |



# Fire Door RB-L84BB4 🛛 🕏 FD305



Item Fire Door

**Fire Resistance** FD30

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels No

First floor / Howard Building

**1** Action

Floor / Location

Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices None

Electrical Hold Open Device No

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



Unit T3

### LIMITED, OCCUPANT DID NOT **Inspection Type** ANSWER Have the door fully inspected by a competent person. TIMESCALE SHORT TERM The assessor had limited access to the door during the routine door survey. REFERENCE RB-SQUX6J DUE 22/04/2025 SEVERITY PROPERTY PROTECTION CATEGORY Building: Doors

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 247 370



170

# Fire Door RB-LRRGE8 🛛 🔊 FD305



Item Fire Door

**Fire Resistance** FD30

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels No

First floor / Howard Building

**1** Action

Floor / Location

Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices None

Electrical Hold Open Device No

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection






Unit T9

### LIMITED, OCCUPANT DID NOT **Inspection Type** ANSWER Have the door fully inspected by a competent person. TIMESCALE SHORT TERM The assessor had limited access to the door during the routine door survey. REFERENCE RB-S45K1V DUE 22/04/2025 SEVERITY PROPERTY PROTECTION CATEGORY Building: Doors

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 248 370







**Fire Resistance** FD30

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Side & Overhead Panels Yes - Glazed

Intumescent & Smoke Seals Intumescent & Smoke

First floor / Howard Building

Self-Closing Devices Overhead

**1** Action

Floor / Location

**Electrical Hold Open Device** Yes

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection



172



Unit T12

### **Inspection Type**

Have the door fully inspected by a competent person. The assessor had limited access to the door during the routine door survey.

REFERENCE RB-TBLNP4 DUE 22/04/2025 CATEGORY Building: Doors

LIMITED, OCCUPANT DID NOT ANSWER

TIMESCALE SHORT TERM SEVERITY PROPERTY PROTECTION

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 249 370



# Fire Door RB-MBOMJK 🛛 🕫 FD30

Item Fire Door

**Fire Resistance** FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No



Intumescent & Smoke Seals None

**1** Action

First / Howard Building

Floor / Location

Self-Closing Devices Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



173

CCTV room

**Inspection Type** 

**FULL ACCESS** 

### **Fire Door Condition**

- × The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- X Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

### Replace door with FD30s rated fire door.

The door is not fit for purpose - 44mm door fitted in a 38mm frame.

REFERENCE RB-AXEV7X DUE 22/04/2025 CATEGORY Building: Doors

ACTION CONTINUES..



SHORT TERM

**PROPERTY PROTECTION** 



..ACTION CONTINUED



RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 251 370







**1** Action

Floor / Location First floor / Howard Building



**Fire Resistance** FD30

ltem

Fire Door


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels No



Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Male wc

A Additional Photos



Inspection Type

FULL ACCESS

**Risk**Base

**Fire Door Condition** X The leaf and frame are adequately specified

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 252 370

| Replace door with FD30s rated fire door.                                 | TIMESCALE           |
|--|---------------------|
| The door is not fit for purpose - 44mm door fitted into 38mm door frame. | SHORT TERM          |
| REFERENCE RB-LSLS4Y DUE 22/04/2025                                       | SEVERITY            |
| CATEGORY Building: Doors   | PROPERTY PROTECTION |
|  |                     |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 253 370 V Risk Base



## Fire Door RB-Q99RL7 🛛 🕏 FD305



7 Actions

Floor / Location

Item Fire Door

**Fire Resistance** FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels No



Intumescent & Smoke Seals Intumescent & Smoke

First floor / Howard Building

Self-Closing Devices None

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Unit T15

**Inspection Type** 

**FULL ACCESS** 


**Fire Door Condition** 

- X The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- X Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

#### Replace hinges with BS EN standard fire door hinges.

All fire doors are required to have 3 hinges, which must be fire certified.

REFERENCE RB-UJ384Y DUE 22/04/2025 CATEGORY Building: Doors



SHORT TERM

**PROPERTY PROTECTION** 

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 254 370



| Replace fire door with FD30s fire rated door.         The fire door is damaged beyond repair. Door and frame have been machined for access control.         Frame has been repaired with an aluminium fillet plate.         REFERENCE RB-B49AK3 DUE 22/04/2025         CATEGORY Building: Doors | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |
|---|--|
| Reduce gaps between the door and the door frame.  | TIMESCALE  |
| To ensure heat and smoke cannot pass through to escape route.   | SHORT TERM   |
| REFERENCE RB-4XUDH8 DUE 22/04/2025  | SEVERITY   |
| CATEGORY Building: Doors  | PROPERTY PROTECTION  |
| Fit intumescent seals to the door frame.  | TIMESCALE  |
| Seals are damaged or missing in sections of the frame.  | SHORT TERM   |
| REFERENCE RB-PAT24M DUE 22/04/2025  | SEVERITY   |
| CATEGORY Building: Doors  | PROPERTY PROTECTION  |
| Replace the door closer.<br>The door does not close-in-line if released from an open position.<br>REFERENCE RB-F69UJQ DUE No Due Date   | NO TIMESCALE<br>NO SEVERITY                                |
| Adjust door alignment.  | TIMESCALE  |
| Door gaps exceed safe guidelines.   | SHORT TERM   |
| REFERENCE RB-FPYVZ5 DUE 22/04/2025  | SEVERITY   |
| CATEGORY Building: Doors  | PROPERTY PROTECTION  |
| Adjust door alignment.  | TIMESCALE  |
| Doors do not close in-line if released from an open position.   | SHORT TERM   |
| REFERENCE RB-RKQHQ6 DUE 22/04/2025  | SEVERITY   |
| CATEGORY Building: Doors  | PROPERTY PROTECTION  |







Floor / Location

or

**Item** Fire Door


Fire Resistance FD30

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

#### Frame Finish

Paint Finish



Intumescent & Smoke Seals Intumescent & Smoke

First floor / Howard Building

**5** Actions

Last Full Inspection 22/01/2025

Last Inspection Type Full Access Inspection



#### Unit T4

#### A Additional Photos



#### Inspection Type


### Fire Door Condition


- × The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- X Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- × When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 25



FULL ACCESS











ltem Fire Door

**Fire Resistance** FD30

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Intumescent & Smoke Seals

First floor / Howard Building

Intumescent & Smoke

**1** Action

Floor / Location

Self-Closing Devices None

**Electrical Hold Open Device** No

Last Limited Inspection 22/01/2025

Last Inspection Type Limited Access Inspection




177

FE NO. 1

Unit T13

| Inspection Type   | LIMITED, OCCUPANT DID NOT<br>Answer |
|---|-------------------------------------|
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door survey. | NO TIMESCALE                        |
| REFERENCE RB-M58FYD DUE No Due Date   | NO SEVERITY                         |







**6** Actions

Floor / Location First floor / Howard Building



**Fire Resistance** FD30

ltem

Fire Door

Certification None


Leaf Configuration Double Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels Yes - Unknown Fire Resistance

Side & Overhead Panels No



Intumescent & Smoke Seals Intumescent & Smoke

Self-Closing Devices Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Corridor next to unit T14

Inspection Type

#### **Fire Door Condition**

- X The leaf and frame are adequately specified
- There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- X Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- X An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- × When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

**FULL ACCESS** 





| Replace hinges with BS EN standard fire door hinges.  | TIMESCALE           |
|---|---------------------|
| All fire doors are required to have 3 hinges, which must be fire certified.   | SHORT TERM          |
| REFERENCE RB-NVXDCX DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Replace door with FD30s rated fire door.  | TIMESCALE           |
| The door is not fit for purpose.  | SHORT TERM          |
| REFERENCE RB-WNXTBL DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Reduce gaps between the door and the door frame.  | TIMESCALE           |
| To ensure heat and smoke cannot pass through to escape route.   | SHORT TERM          |
| REFERENCE RB-AVXC7U DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Fit intumescent seals to the door frame.  | TIMESCALE           |
| Seals are damaged or missing in sections of the frame. Intumescent line broken by hinges.                           | SHORT TERM          |
| REFERENCE RB-DUN41H DUE 22/04/2025  | SEVERITY            |
| CATEGORY Building: Doors  | PROPERTY PROTECTION |
| Replace door closer on RH door leaf.  | NO TIMESCALE        |
| Certification - closer leaking, no door control so door slams.<br>REFERENCE <b>RB-6TX3EX</b> DUE <b>No Due Date</b> | NO SEVERITY         |
| 320   |                     |
| Adjust door alignment.<br>Doors do not close in-line if released from an open position. Door twisted at bottom.     | NO TIMESCALE        |
| REFERENCE RB-GNH77Y DUE No Due Date   | NO SEVERITY         |
| 321   |                     |



## Fire Door RB-Y4ZDXA 🛛 😎 FD30



ltem Fire Door

**Fire Resistance** FD30


Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Paint Finish

Frame Finish Paint Finish

Leaf Vision Panels No



Intumescent & Smoke Seals

**1** Action

First / Howard Building

Floor / Location

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



179

Cleaners store

**Inspection Type** 

**FULL ACCESS** 

#### **Fire Door Condition**

- × The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- X Seals are undamaged and well fitted / continuous around the whole leaf or frame
- × Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- Fire door signage correctly identifies door operation and is securely attached

#### Replace door with FD30s rated fire door.

The door is not fit for purpose - 44mm door fixed into 38mm frame.

REFERENCE RB-TNEQCZ DUE 22/04/2025 CATEGORY Building: Doors

ACTION CONTINUES..



SHORT TERM

**PROPERTY PROTECTION** 

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ

Self-Closing Devices Overhead

None

**Electrical Hold Open Device** No

..ACTION CONTINUED



RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 262 370



## Fire Door RB-MYQB29 🛛 🔊 FD30



Floor / Location Second floor / Howard Building

7 Actions



**Fire Resistance** FD30

Item Fire Door

Certification None

Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Side & Overhead Panels No

#### Gaps Head 9mm Hinge Closing 3mm 6mm Threshold 15mm


Intumescent & Smoke Seals None

Self-Closing Devices Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Unit T18 office lobby

#### Inspection Type

#### **Fire Door Condition**

- × The leaf and frame are adequately specified
- There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- X Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- × Vision panels are undamaged, properly installed with intumescent seals and glazing beads to all sides
- × An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- × When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached


**FULL ACCESS** 

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 263 370



| Replace hinges with BS EN standard fire door hinges.                        | TIMESCALE               |
|---|-------------------------|
| All fire doors are required to have 3 hinges, which must be fire certified. | SHORT TERM              |
| REFERENCE RB-GMZTAH DUE 22/04/2025  | SEVERITY                |
| CATEGORY Building: Doors  | PROPERTY PROTECTION     |
| Replace door with FD30s rated fire door.                                    | TIMESCALE               |
| The door is not fit for purpose.  | SHORT TERM              |
| REFERENCE RB-9LECSM DUE 22/04/2025  | SEVERITY                |
| CATEGORY Building: Doors  | PROPERTY PROTECTION     |
| Reduce gaps between the door and the door frame.                            | TIMESCALE               |
| To ensure heat and smoke cannot pass through to escape route.               | SHORT TERM              |
| REFERENCE RB-7MU64H DUE 22/04/2025  | SEVERITY                |
| CATEGORY Building: Doors  | PROPERTY PROTECTION     |
| Fit intumescent seals to the door frame.                                    | TIMESCALE               |
| Seals are damaged or missing in sections of the frame.                      | SHORT TERM              |
| REFERENCE RB-STAIDZ DUE 22/04/2025  | SEVERITY                |
| CATEGORY Building: Doors  | PROPERTY PROTECTION     |
| Fit a fire door keep locked shut sign.                                      | TIMESCALE<br>SHORT TERM |
| REFERENCE RB-2FI3LQ DUE 22/04/2025  | SEVERITY                |
| CATEGORY Building: Doors  | PROPERTY PROTECTION     |
| <b>Confirm glazing meets BS EN fire regulations.</b>                        | TIMESCALE               |
| Ensure the integrity of the fire door.                                      | SHORT TERM              |
| REFERENCE RB-DFE3V6 DUE 22/04/2025  | SEVERITY                |
| CATEGORY Building: Doors  | PROPERTY PROTECTION     |
| Adjust door alignment.  | TIMESCALE               |
| Door gaps exceed safe guidelines.   | SHORT TERM              |
| REFERENCE RB-Z7AW5T DUE 22/04/2025  | SEVERITY                |
| CATEGORY Building: Doors  | PROPERTY PROTECTION     |
| 324   |                         |





Item

FD30

None

Fire Door

**Fire Resistance** 

Certification

Leaf Finish

Wood Finish

Frame Finish

Leaf Vision Panels

Paint Finish

No

Leaf Configuration

Single Leaf - Single Acting



7 Actions

Floor / Location Second floor / Howard Building

Intumescent & Smoke Seals None

Self-Closing Devices Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



181 -

Side & Overhead Panels No



Unit T18 kitchenette

#### Inspection Type

#### **Fire Door Condition**

- X The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- X Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- ✓ An effective device closes the leaf from 5° or 75mm (leaves hung in pairs close in-line)
- X When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached

**Risk**Base 265 370

RB-U8LT5M - 22/01/2025 - LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ

**FULL ACCESS** 

| Replace hinges with BS EN standard fire door hinges.   | TIMESCALE  |
|--|--|
| All fire doors are required to have 3 hinges, which must be fire certified.                              | SHORT TERM   |
| REFERENCE RB-DXAQDU DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Replace door with FD30s rated fire door.   | TIMESCALE  |
| The door is not fit for purpose.   | SHORT TERM   |
| REFERENCE RB-7CTTUW DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Reduce gaps between the door and the door frame.   | TIMESCALE  |
| To ensure heat and smoke cannot pass through to escape route.  | SHORT TERM   |
| REFERENCE RB-X3U5AE DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Fit intumescent seals to the door frame.   | TIMESCALE  |
| Seals are damaged or missing in sections of the frame.   | SHORT TERM   |
| REFERENCE RB-V8APFM DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Fit a fire door keep locked shut sign.<br>REFERENCE RB-QLAS29 DUE 22/04/2025<br>CATEGORY Building: Doors | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |
| Adjust door alignment.   | TIMESCALE  |
| Door gaps exceed safe guidelines.  | SHORT TERM   |
| REFERENCE RB-8628B5 DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Adjust the closer to ensure the door sits flush with the rebate.   | TIMESCALE  |
| To ensure heat and smoke cannot pass through to escape route.  | SHORT TERM   |
| REFERENCE RB-DVJBPJ DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |



## Fire Door RB-UR5101 🔮 FD30

Item Fire Door

FD30

None

**Fire Resistance** 

Certification

Leaf Finish

Wood Finish

Frame Finish

Paint Finish

Leaf Configuration

Single Leaf - Single Acting



7 Actions

Floor / Location Second floor / Howard Building

Intumescent & Smoke Seals None

Self-Closing Devices

Overhead

**Electrical Hold Open Device** No

Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



182



Side & Overhead Panels

Leaf Vision Panels

No

No



Unit T18 wc lobby

#### Inspection Type

#### **Fire Door Condition**

- X The leaf and frame are adequately specified
- X There is no damage significant enough to affect the fire integrity of the leaf or frame
- X Gaps around the frame are within tolerance (and/or manufacturers guidelines)
- X Seals are undamaged and well fitted / continuous around the whole leaf or frame
- X Minimum of three single axis hinges of BS EN 1935 Grade 11 or above are fitted with all screws present
- X When closed, the leaf sits against a securely installed stop without distortion
- × Fire door signage correctly identifies door operation and is securely attached

## Replace hinges with BS EN standard fire door hinges.

All fire doors are required to have 3 hinges, which must be fire certified.

REFERENCE RB-ZW2FQW DUE 22/04/2025 CATEGORY Building: Doors

TIMESCALE SHORT TERM SEVERIT **PROPERTY PROTECTION** 

**FULL ACCESS** 





| Replace door with FD30s rated fire door.                         | TIMESCALE                       |
|--|---------------------------------|
| The door is not fit for purpose.                                 | SHORT TERM                      |
| REFERENCE RB-TKC6LT DUE 22/04/2025                               | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |
| Reduce gaps between the door and the door frame.                 | TIMESCALE                       |
| To ensure heat and smoke cannot pass through to escape route.    | SHORT TERM                      |
| REFERENCE RB-LVSP1Q DUE 22/04/2025                               | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |
| Fit intumescent seals to the door frame.                         | TIMESCALE                       |
| Seals are damaged or missing in sections of the frame.           | SHORT TERM                      |
| REFERENCE RB-113GHK DUE 22/04/2025                               | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |
| Fit a fire door keep locked shut sign.                           | TIMESCALE<br>SHORT TERM         |
| CATEGORY Building: Doors   | SEVERITY<br>PROPERTY PROTECTION |
| Adjust the closer to ensure the door sits flush with the rebate. | TIMESCALE                       |
| To ensure heat and smoke cannot pass through to escape route.    | SHORT TERM                      |
| REFERENCE <b>RB-YFJJAG</b> DUE <b>22/04/2025</b>                 | SEVERITY                        |
| CATEGORY <b>Building: Doors</b>                                  | PROPERTY PROTECTION             |
| Adjust door alignment.   | TIMESCALE                       |
| Door gaps exceed safe guidelines.                                | SHORT TERM                      |
| REFERENCE RB-MM2CTB DUE 22/04/2025                               | SEVERITY                        |
| CATEGORY Building: Doors   | PROPERTY PROTECTION             |



## Fire Door RB-X6Y1YG 🛛 🔊 FD30



8 Actions

Floor / Location Second floor / Howard Building



**Fire Resistance** FD30

Item Fire Door

Certification None


Leaf Configuration Single Leaf - Single Acting

Leaf Finish Wood Finish

Frame Finish Paint Finish

Leaf Vision Panels No

Side & Overhead Panels No




Last Full Inspection 22/01/2025

Last Inspection Type **Full Access Inspection** 



Unit T18





#### ...ACTION CONTINUED

| ACTION CONTINUED   |  |
|--|--|
|  |  |
| Reduce gaps between the door and the door frame.   | TIMESCALE  |
| To ensure heat and smoke cannot pass through to escape route.  | SHORT TERM   |
| REFERENCE RB-LW1AR6 DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Fit intumescent seals to the door frame.   | TIMESCALE  |
| Seals are damaged or missing in sections of the frame.   | SHORT TERM   |
| REFERENCE RB-HT7LG6 DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Fit a fire door keep locked shut sign.<br>REFERENCE RB-SR9HCL DUE 22/04/2025<br>CATEGORY Building: Doors | TIMESCALE<br>SHORT TERM<br>SEVERITY<br>PROPERTY PROTECTION |
| Adjust the door closer for the door to latch closed.   | TIMESCALE  |
| The door does not close in-line if released from an open position.                                       | SHORT TERM   |
| REFERENCE RB-CS8IKI DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Adjust door alignment.   | TIMESCALE  |
| Door gaps exceed safe guidelines.  | SHORT TERM   |
| REFERENCE RB-6C1Z8M DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |
| Adjust the closer to ensure the door sits flush with the rebate.   | TIMESCALE  |
| To ensure heat and smoke cannot pass through to escape route.  | SHORT TERM   |
| REFERENCE RB-ZNMEP2 DUE 22/04/2025   | SEVERITY   |
| CATEGORY Building: Doors   | PROPERTY PROTECTION  |



# **3** ACTION PLAN

| Add/replace screws in hinges.<br>Hinges have less than the required three screws.                                |                   |
|--|-------------------|
| REFERENCE RB-Q1FYMF<br>SEVERITY Property Protection<br>ELEMENT Fire Door MNQKSS (Floor: GF. Location: Unit 54)   |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |                   |
| REFERENCE RB-246GCE<br>SEVERITY Property Protection<br>ELEMENT Fire Door E6EE7R (Floor: GF. Location: Unit 56)   |                   |
| due by / Assigned to 22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |                   |
| REFERENCE RB-ZJ3NGT<br>SEVERITY Property Protection<br>ELEMENT Fire Door 37DAH3 (Floor: GF. Location: Male WC)   |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |                   |
| REFERENCE RB-XD1FSB<br>SEVERITY Property Protection<br>ELEMENT Fire Door L3UT9D (Floor: GF. Location: Female WC) |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |                   |
| REFERENCE RB-QWY3DU<br>SEVERITY Property Protection<br>ELEMENT Fire Door QDQ9R3 (Floor: GF. Location: Unit 53)   |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |



| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
|---|-------------------|
| REFERENCE RB-21AVW8<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q2XDJJ (Floor: GF. Location: Patra Corridor Lobby)   |                   |
| due BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
| REFERENCE RB-9KP9TR<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)                |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
| REFERENCE RB-F7EKU8<br>SEVERITY Property Protection<br>ELEMENT Fire Door JRZGWA (Floor: GF. Location: Corridor lobby)         |                   |
| due BY / Assigned to 22 April 2025  | COMPLETED ON / BY |
| Adjust door alignment.<br>Doors do not close in-line if released from an open position.                                       |                   |
| REFERENCE RB-HCNPNL<br>SEVERITY Property Protection<br>ELEMENT Fire Door JRZGWA (Floor: GF. Location: Corridor lobby)         |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
| REFERENCE RB-EZNF7E<br>SEVERITY Property Protection<br>ELEMENT Fire Door A57JCK (Floor: GF. Location: Corridor / stair lobby) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.  |                   |
| Door gaps exceed safe guidelines.   |                   |
| REFERENCE RB-VSKX3W<br>SEVERITY Property Protection   |                   |
| ELEMENT Fire Door 9NGMW8 (Floor: GF. Location: Corridor next to unit 19)  |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 272 370 V Risk Base



| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
|---|-------------------|
| REFERENCE RB-3AYNN8<br>SEVERITY Property Protection<br>ELEMENT Fire Door 3JXMUG (Floor: GF. Location: Corridor next to unit 23) |                   |
| due BY / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Doors do not close in-line if released from an open position.   |                   |
| REFERENCE RB-5EIRYA<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)         |                   |
| due BY / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
| REFERENCE RB-M4AGLG<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18) |                   |
| due By / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
| REFERENCE RB-7SG4Z5<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18) |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
| REFERENCE RB-TZ79YB<br>SEVERITY Property Protection<br>ELEMENT Fire Door PCXWMV (Floor: GF. Location: Corridor next to unit 15) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.  |                   |
| Doors do not close in-line if released from an open position.   |                   |
| REFERENCE RB-74VQT9<br>SEVERITY Property Protection<br>ELEMENT Fire Door TYV5EP (Floor: GF. Location: Corridor next to unit 47) |                   |
| DUE BY / ASSIGNED TO  |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 273 370 VRISK Base



| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
|---|-------------------|
| REFERENCE RB-U2B93E<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4Y6J1S (Floor: GF. Location: Corridor near to unit 48)   |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
| REFERENCE RB-33CBDF<br>SEVERITY Property Protection<br>ELEMENT Fire Door PJGGE7 (Floor: Basement. Location: Escape lobby door)  |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
| REFERENCE RB-BA7NNN<br>SEVERITY Property Protection<br>ELEMENT Fire Door L5NNXW (Floor: Basement. Location: Rear workshop # 2)  |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.  |                   |
| Door gaps exceed safe guidelines.   |                   |
| REFERENCE RB-ZHDHEI<br>SEVERITY Property Protection<br>ELEMENT Fire Door FQ56JD (Floor: GF. Location: Howard Building)  |                   |
| DUE BY / ASSIGNED TO  |                   |
|   | COMPLETED ON / BY |
| 22 April 2025   | COMPLETED ON / BY |
|   | COMPLETED ON / BY |
| 22 April 2025<br>Adjust door alignment.   | COMPLETED ON / BY |
| 22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-DA465E<br>SEVERITY Property Protection<br>ELEMENT Fire Door FQ56JD (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO  | COMPLETED ON / BY |
| 22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-DA465E<br>SEVERITY Property Protection<br>ELEMENT Fire Door FQ56JD (Floor: GF. Location: Howard Building)  |                   |
| 22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-DA465E<br>SEVERITY Property Protection<br>ELEMENT Fire Door FQ56JD (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO  |                   |
| 22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-DA465E<br>SEVERITY Property Protection<br>ELEMENT Fire Door FQ56JD (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025   |                   |
| 22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-DA465E<br>SEVERITY Property Protection<br>ELEMENT Fire Door FQ56JD (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-PZ3MFX                                 |                   |
| 22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-DA465E<br>SEVERITY Property Protection<br>ELEMENT Fire Door FQ56JD (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.  |                   |
| 22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFFRENCE RB-DA465E<br>SEVERITY Property Protection<br>ELEMENT Fire Door FQ56JD (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFFRENCE RB-PZ3MFX<br>SEVERITY Property Protection |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 274 370 V Risk Base



| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |  |
|--|--|
| REFERENCE RB-X1N4VJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door AP5BJW (Floor: GF. Location: Howard Building)   |  |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY                      |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |  |
| REFERENCE RB-ZXPXGH<br>SEVERITY Property Protection<br>ELEMENT Fire Door NL5VST (Floor: GF. Location: Howard Building)   |  |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY                      |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |  |
| REFERENCE RB-18UU2R<br>SEVERITY Property Protection<br>ELEMENT Fire Door 8V34BM (Floor: GF. Location: Howard Building)   |  |
| due By / Assigned to<br>22 April 2025  | COMPLETED ON / BY                      |
|  |  |
| Adjust door alignment.   |  |
| Door gaps exceed safe guidelines.  |  |
|  |  |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-GDHB22<br>SEVERITY Property Protection   | COMPLETED ON / BY                      |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-GDHB22<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.   | COMPLETED ON / BY                      |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-GDHB22<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.  | COMPLETED ON / BY                      |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-GDHB22<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.   | COMPLETED ON / BY                      |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-GDHB22<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-PU8DN2<br>SEVERITY Property Protection   | COMPLETED ON / BY<br>COMPLETED ON / BY |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-GDHB22<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-PU8DN2<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO  |  |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-GDHB22<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-PU8DN2<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025   |  |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-GDHB22<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-PU8DN2<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-4949V7                                 |  |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-GDHB22<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-PU8DN2<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.  |  |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-GDHB22<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-PU8DN2<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-4949V7<br>SEVERITY Property Protection |  |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 275 370 V Risk Base



| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
|---|-------------------|
| REFERENCE RB-PYPJYZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)          |                   |
| due BY / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
| REFERENCE RB-51RCZN<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)          |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
| REFERENCE RB-QR82DJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door EKGWZ6 (Floor: First. Location: Howard Building)       |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Doors do not close in-line if released from an open position.   |                   |
| REFERENCE RB-XNPBZS<br>SEVERITY Property Protection<br>ELEMENT Fire Door WSTDT3 (Floor: First floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
| REFERENCE RB-MJYV3P<br>SEVERITY Property Protection<br>ELEMENT Fire Door D7CUPT (Floor: First floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.  |                   |
| Door gaps exceed safe guidelines. Doors bowed 9mm mid-leaf.   |                   |
| REFERENCE RB-EKDY8M<br>SEVERITY Property Protection<br>ELEMENT Fire Door D7CUPT (Floor: First floor. Location: Howard Building) |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |



| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |                   |
|--|-------------------|
| REFERENCE RB-R1H4PW<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9ZUWI7 (Floor: First floor. Location: Howard Building)  |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |                   |
| REFERENCE RB-8VZWSV<br>SEVERITY Property Protection<br>ELEMENT Fire Door FTZ3EB (Floor: First floor. Location: Howard Building)  |                   |
| due By / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |                   |
| REFERENCE RB-H1FGS2<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZACXD (Floor: Ground. Location: Howard Building)   |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |
|  |                   |
| Adjust door alignment.   |                   |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |                   |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-M3LU1D<br>SEVERITY Property Protection   |                   |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-M3LU1D<br>SEVERITY Property Protection<br>ELEMENT Fire Door TKJLLH (Floor: Ground. Location: Howard Building)  | COMPLETED ON / RY |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-M3LU1D<br>SEVERITY Property Protection   | COMPLETED ON / BY |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-M3LU1D<br>SEVERITY Property Protection<br>ELEMENT Fire Door TKJLLH (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.   | COMPLETED ON / BY |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-M3LU1D<br>SEVERITY Property Protection<br>ELEMENT Fire Door TKJLLH (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.  | COMPLETED ON / BY |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-M3LU1D<br>SEVERITY Property Protection<br>ELEMENT Fire Door TKJLLH (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.   | COMPLETED ON / BY |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-M3LU1D<br>SEVERITY Property Protection<br>ELEMENT Fire Door TKJLLH (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-26D6G8<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSUSVQ (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO  | COMPLETED ON / BY |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-M3LU1D<br>SEVERITY Property Protection<br>ELEMENT Fire Door TKJLLH (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-26D6G8<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)  |                   |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-M3LU1D<br>SEVERITY Property Protection<br>ELEMENT Fire Door TKJLLH (Floor: Ground. Location: Howard Building)<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-26D6G8<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.   |                   |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-M3LU1D<br>SEVERITY Property Protection<br>ELEMENT Fire Door TKJLLH (Floor: Ground. Location: Howard Building)<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-26D6G8<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025   |                   |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-M3LU1D<br>SEVERITY Property Protection<br>ELEMENT Fire Door TKJLLH (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-26D6G8<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSUSVQ (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-2025                                   |                   |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-M3LU1D<br>SEVERITY Property Protection<br>ELEMENT Fire Door TKJLLH (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-26D6G8<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.  |                   |
| Door gaps exceed safe guidelines.<br>REFERENCE RB-M3LU1D<br>SEVERITY Property Protection<br>ELEMENT Fire Door TKJLLH (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-26D6G8<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust door alignment.<br>Door gaps exceed safe guidelines.<br>REFERENCE RB-JJP9ZS<br>SEVERITY Property Protection |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 277 370 V Risk Base

| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
|---|-------------------|
| REFERENCE RB-Q69SZ7<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9EN3B8 (Floor: First floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
| REFERENCE RB-FPYVZ5<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q99RL7 (Floor: First floor. Location: Howard Building) |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Doors do not close in-line if released from an open position.   |                   |
| REFERENCE RB-RKQHQ6<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q99RL7 (Floor: First floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.   |                   |
| REFERENCE RB-HDJDX9<br>SEVERITY Property Protection<br>ELEMENT Fire Door BAI8Z6 (Floor: First floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.<br>Doors do not close in-line if released from an open position.   |                   |
| REFERENCE RB-1B7HS1<br>SEVERITY Property Protection<br>ELEMENT Fire Door BAI8Z6 (Floor: First floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Adjust door alignment.  |                   |
| Doors do not close in-line if released from an open position.   |                   |
|   |                   |
| REFERENCE RB-47PULN<br>SEVERITY Property Protection<br>ELEMENT Fire Door 2H5NBL (Floor: First floor. Location: Howard Building) |                   |



| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |                   |
|--|-------------------|
| REFERENCE RB-3HPLUZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door 2H5NBL (Floor: First floor. Location: Howard Building)  |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |                   |
| REFERENCE RB-6C1Z8M<br>SEVERITY Property Protection<br>ELEMENT Fire Door X6Y1YG (Floor: Second floor. Location: Howard Building) |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |                   |
| REFERENCE RB-Z7AW5T<br>SEVERITY Property Protection<br>ELEMENT Fire Door MYQB29 (Floor: Second floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLEED ON / BY  |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |                   |
| REFERENCE RB-8628B5<br>SEVERITY Property Protection<br>ELEMENT Fire Door PZSHGC (Floor: Second floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLEED ON / BY  |
| Adjust door alignment.   |                   |
| Door gaps exceed safe guidelines.  |                   |
| REFERENCE RB-MM2CTB<br>SEVERITY Property Protection<br>ELEMENT Fire Door UR51QI (Floor: Second floor. Location: Howard Building) |                   |
| due BY / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Adjust door alignment.   |                   |
| Door gaps exceed safe guidelines. REFERENCE <b>RB-VUDY2P</b>   |                   |
| SEVERITY Property Protection<br>ELEMENT Fire Door 468GQH (Floor: First floor. Location: Howard Building)                         |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLEED ON / BY  |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 279 370 V Risk Base

| Adjust the closer to ensure the door sits flush with the rebate.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
|--|-------------------|
| REFERENCE RB-HQQRLE<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q2XDJJ (Floor: GF. Location: Patra Corridor Lobby)  |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Adjust the closer to ensure the door sits flush with the rebate.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
| REFERENCE RB-KJL3TI<br>SEVERITY Property Protection<br>ELEMENT Fire Door JRZGWA (Floor: GF. Location: Corridor lobby)  |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Adjust the closer to ensure the door sits flush with the rebate.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
| REFERENCE RB-5U7EI2<br>SEVERITY Property Protection<br>ELEMENT Fire Door 3JXMUG (Floor: GF. Location: Corridor next to unit 23)  |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
|  |                   |
| Adjust the closer to ensure the door sits flush with the rebate.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
|  |                   |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-XB943Z<br>SEVERITY Property Protection   | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-XB943Z<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18)<br>DUE BY / ASSIGNED TO   | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-XB943Z<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the closer to ensure the door sits flush with the rebate.  | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-XB943Z<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the closer to ensure the door sits flush with the rebate.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-GCHG3S<br>SEVERITY Property Protection  | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-XB943Z<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the closer to ensure the door sits flush with the rebate.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-GCHG3S<br>SEVERITY Property Protection<br>ELEMENT Fire Door AP5BJW (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025  |                   |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-XB943Z<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the closer to ensure the door sits flush with the rebate.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-GCHG3S<br>SEVERITY Property Protection<br>ELEMENT Fire Door AP5BJW (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO   |                   |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-XB943Z<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the closer to ensure the door sits flush with the rebate.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-GCHG3S<br>SEVERITY Property Protection<br>ELEMENT Fire Door AP5BJW (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the closer to ensure the door sits flush with the rebate.  |                   |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-XB943Z<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the closer to ensure the door sits flush with the rebate.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-GCHG3S<br>SEVERITY Property Protection<br>ELEMENT Fire Door AP5BJW (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the closer to ensure the door sits flush with the rebate.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-GCHG3S<br>SEVERITY Property Protection<br>ELEMENT Fire Door AP5BJW (Floor: GF. Location: Howard Building) |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 280 370 V Risk Base

| Adjust the closer to ensure the door sits flush with the rebate.<br>To ensure heat and smoke cannot pass through to escape route. |                   |
|---|-------------------|
| REFERENCE RB-8TH4JK<br>SEVERITY Property Protection<br>ELEMENT Fire Door TKJLLH (Floor: Ground. Location: Howard Building)        |                   |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY |
| Adjust the closer to ensure the door sits flush with the rebate.<br>To ensure heat and smoke cannot pass through to escape route. |                   |
| REFERENCE RB-I3N57Y<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)        |                   |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY |
| Adjust the closer to ensure the door sits flush with the rebate.<br>To ensure heat and smoke cannot pass through to escape route. |                   |
| REFERENCE RB-ZNMEP2<br>SEVERITY Property Protection<br>ELEMENT Fire Door X6Y1YG (Floor: Second floor. Location: Howard Building)  |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Adjust the closer to ensure the door sits flush with the rebate.<br>To ensure heat and smoke cannot pass through to escape route. |                   |
| REFERENCE RB-DVJBPJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door PZSHGC (Floor: Second floor. Location: Howard Building)  |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Adjust the closer to ensure the door sits flush with the rebate.<br>To ensure heat and smoke cannot pass through to escape route. |                   |
| REFERENCE RB-YFJJAG<br>SEVERITY Property Protection<br>ELEMENT Fire Door UR51QI (Floor: Second floor. Location: Howard Building)  |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Adjust the door closer for the door to latch closed.  |                   |
| The door does not close in-line if released from an open position.  |                   |
| REFERENCE RB-BW2T98<br>SEVERITY Property Protection<br>ELEMENT Fire Door MNQKSS (Floor: GF. Location: Unit 54)                    |                   |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 281 370 V Risk Base



| Adjust the door closer for the door to latch closed.<br>The door does not close in-line if released from an open position.   |                   |
|--|-------------------|
| REFERENCE RB-VJUA8M<br>SEVERITY Property Protection<br>ELEMENT Fire Door 37DAH3 (Floor: GF. Location: Male WC)   |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Adjust the door closer for the door to latch closed.<br>The door does not close in-line if released from an open position.   |                   |
| REFERENCE RB-WWDDYB<br>SEVERITY Property Protection<br>ELEMENT Fire Door L3UT9D (Floor: GF. Location: Female WC)   |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Adjust the door closer for the door to latch closed.<br>The door does not close in-line if released from an open position.   |                   |
| REFERENCE RB-8PN43G<br>SEVERITY Property Protection<br>ELEMENT Fire Door QDQ9R3 (Floor: GF. Location: Unit 53)   |                   |
| due By / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
|  |                   |
| Adjust the door closer for the door to latch closed.<br>The door does not close in-line if released from an open position.   |                   |
|  |                   |
| The door does not close in-line if released from an open position.<br>REFERENCE RB-1832TT<br>SEVERITY Property Protection  | COMPLETED ON / BY |
| The door does not close in-line if released from an open position.<br>REFERENCE RB-1832TT<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO   | COMPLETED ON / BY |
| The door does not close in-line if released from an open position.<br>REFERENCE RB-1832TT<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the door closer for the door to latch closed.  | COMPLETED ON / BY |
| The door does not close in-line if released from an open position.<br>REFERENCE RB-1832TT<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the door closer for the door to latch closed.<br>The door does not close in-line if released from an open position.<br>REFERENCE RB-9WBZZ8<br>SEVERITY Property Protection   | COMPLETED ON / BY |
| The door does not close in-line if released from an open position.<br>REFERENCE RB-1832TT<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the door closer for the door to latch closed.<br>The door does not close in-line if released from an open position.<br>REFERENCE RB-9WBZZ8<br>SEVERITY Property Protection<br>ELEMENT Fire Door WSTDT3 (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025  |                   |
| The door does not close in-line if released from an open position.<br>REFERENCE RB-1832TT<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the door closer for the door to latch closed.<br>The door does not close in-line if released from an open position.<br>REFERENCE RB-9WBZZ8<br>SEVERITY Property Protection<br>ELEMENT Fire Door WSTDT3 (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO   |                   |
| The door does not close in-line if released from an open position.<br>REFERENCE RB-1832TT<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the door closer for the door to latch closed.<br>The door does not close in-line if released from an open position.<br>REFERENCE RB-9WBZZ8<br>SEVERITY Property Protection<br>ELEMENT Fire Door WSTDT3 (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the door closer for the door to latch closed.  |                   |
| The door does not close in-line if released from an open position.<br>REFERENCE RB-1832TT<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the door closer for the door to latch closed.<br>The door does not close in-line if released from an open position.<br>REFERENCE RB-9WBZZ8<br>SEVERITY Property Protection<br>ELEMENT Fire Door WSTDT3 (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the door closer for the door to latch closed.<br>The door does not close in-line if released from an open position.<br>REFERENCE RB-WSE4TH<br>SEVERITY Property Protection |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 282 370 V Risk Base



| Adjust the door closer for the door to latch closed.<br>The door does not close in-line if released from an open position.   |                   |
|--|-------------------|
| REFERENCE RB-CS8IKI<br>SEVERITY Property Protection<br>ELEMENT Fire Door X6Y1YG (Floor: Second floor. Location: Howard Building)   |                   |
| due BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Adjust the door closer for the door to latch closed.<br>The door does not close in-line if released from an open position.   |                   |
| REFERENCE RB-M2GI61<br>SEVERITY Property Protection<br>ELEMENT Fire Door 468GQH (Floor: First floor. Location: Howard Building)  |                   |
| due BY / Assigned to 22 April 2025   | COMPLETED ON / BY |
| Adjust the door closer.<br>The door does not close-in-line if released from an open position.  |                   |
| REFERENCE RB-RUYTEC<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)   |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Adjust the door closer.<br>The door does not close-in-line if released from an open position.  |                   |
|  |                   |
| REFERENCE RB-88JJU4<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)  |                   |
| REFERENCE RB-88JJU4<br>SEVERITY Property Protection  | COMPLETED ON / BY |
| REFERENCE RB-88JJU4<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)<br>DUE BY / ASSIGNED TO  | COMPLETED ON / BY |
| REFERENCE RB-88JJU4<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the door closer.  | COMPLETED ON / BY |
| REFERENCE RB-88JJU4<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the door closer.<br>The door does not close-in-line if released from an open position.<br>REFERENCE RB-B85JN3<br>SEVERITY Property Protection   | COMPLETED ON / BY |
| REFERENCE RB-88JJU4<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)<br>22 April 2025<br>Adjust the door closer.<br>The door does not close-in-line if released from an open position.<br>REFERENCE RB-885JN3<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4Y6J1S (Floor: GF. Location: Corridor near to unit 48)<br>DUE BY / ASSIGNED TO<br>22 April 2025                              |                   |
| REFFERENCE RB-88JJU4<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the door closer.<br>The door does not close-in-line if released from an open position.<br>REFERENCE RB-885JN3<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4Y6J1S (Floor: GF. Location: Corridor near to unit 48)<br>DUE BY / ASSIGNED TO                      |                   |
| REFFERENCE RB-88JJU4<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)<br>22 April 2025<br>Adjust the door closer.<br>The door does not close-in-line if released from an open position.<br>REFFERENCE RB-885JN3<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4Y6J1S (Floor: GF. Location: Corridor near to unit 48)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Adjust the door closer. |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 283 370 VRISKBASE

| Adjust the door closer.<br>The door does not close-in-lin if released from an open position.                                    |                   |
|---|-------------------|
| REFERENCE RB-BWKYNQ<br>SEVERITY Property Protection<br>ELEMENT Fire Door BAI8Z6 (Floor: First floor. Location: Howard Building) |                   |
| due BY / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Adjust the door closer.<br>The door does not close-in-line if released from an open position.                                   |                   |
| REFERENCE RB-93GBRS<br>SEVERITY Property Protection<br>ELEMENT Fire Door 2H5NBL (Floor: First floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| <b>Confirm glazing meets BS EN fire regulations.</b><br>Ensure the integrity of the fire door.                                  |                   |
| REFERENCE RB-C4P96K<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q2XDJJ (Floor: GF. Location: Patra Corridor Lobby)     |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Confirm glazing meets BS EN fire regulations.<br>Ensure the integrity of the fire door.   |                   |
| REFERENCE RB-PGJEGU<br>SEVERITY Property Protection<br>ELEMENT Fire Door JRZGWA (Floor: GF. Location: Corridor lobby)           |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Confirm glazing meets BS EN fire regulations.<br>Ensure the integrity of the fire door.   |                   |
| REFERENCE RB-NZYG6A<br>SEVERITY Property Protection<br>ELEMENT Fire Door A57JCK (Floor: GF. Location: Corridor / stair lobby)   |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Confirm glazing meets BS EN fire regulations.<br>Ensure the integrity of the fire door.   |                   |
| REFERENCE RB-5PITEN<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9NGMW8 (Floor: GF. Location: Corridor next to unit 19) |                   |
| DUE BY / ASSIGNED TO  | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 284 370 V Risk Base

| Confirm glazing meets BS EN fire regulations.<br>Ensure the integrity of the fire door.   |                   |
|---|-------------------|
| REFERENCE RB-G5D9WJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door 3JXMUG (Floor: GF. Location: Corridor next to unit 23) |                   |
| due BY / Assigned to 22 April 2025  | COMPLETED ON / BY |
| Confirm glazing meets BS EN fire regulations.<br>Ensure the integrity of the fire door.   |                   |
| REFERENCE RB-QG3F8J<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18) |                   |
| due BY / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Confirm glazing meets BS EN fire regulations.<br>Ensure the integrity of the fire door.   |                   |
| REFERENCE RB-NGGH83<br>SEVERITY Property Protection<br>ELEMENT Fire Door PCXWMV (Floor: GF. Location: Corridor next to unit 15) |                   |
| due BY / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| <b>Confirm glazing meets BS EN fire regulations.</b><br>Ensure the integrity of the fire door.                                  |                   |
| REFERENCE RB-MZ2K7B<br>SEVERITY Property Protection<br>ELEMENT Fire Door L5NNXW (Floor: Basement. Location: Rear workshop # 2)  |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Confirm glazing meets BS EN fire regulations.<br>Ensure the integrity of the fire door.   |                   |
| REFERENCE RB-GSHC7Z<br>SEVERITY Property Protection<br>ELEMENT Fire Door AP5BJW (Floor: GF. Location: Howard Building)          |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Confirm glazing meets BS EN fire regulations.<br>Ensure the integrity of the fire door.   |                   |
| REFERENCE RB-LUYRRY<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)          |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 285 370 V Risk Base

| <b>Confirm glazing meets BS EN fire regulations.</b><br>Ensure the integrity of the fire door.  |                                       |
|---|---------------------------------------|
| REFERENCE RB-51DFS2<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9ZUWI7 (Floor: First floor. Location: Howard Building)   |                                       |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY                     |
| Confirm glazing meets BS EN fire regulations.<br>Ensure the integrity of the fire door.   |                                       |
| REFERENCE RB-DFE3V6<br>SEVERITY Property Protection<br>ELEMENT Fire Door MYQB29 (Floor: Second floor. Location: Howard Building)  |                                       |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY                     |
| Correct frame fixings.<br>Frame fixings left exposed, should be capped or filled. Five fixings  | to LHleaf, only 3 fixings to RH leaf. |
| REFERENCE RB-48G971<br>SEVERITY Property Protection<br>ELEMENT Fire Door FQ56JD (Floor: GF. Location: Howard Building)  |                                       |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY                     |
|   |                                       |
| Door selector not functional.<br>Certification.   |                                       |
|   |                                       |
| Certification.<br>REFERENCE RB-MIA9HJ<br>SEVERITY Property Protection   | COMPLETED ON / BY                     |
| Certification.<br>REFERENCE RB-MIA9HJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door A57JCK (Floor: GF. Location: Corridor / stair lobby)<br>DUE BY / ASSIGNED TO   | COMPLETED ON / BY                     |
| Certification.<br>REFERENCE RB-MIA9HJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door A57JCK (Floor: GF. Location: Corridor / stair lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Door selector not functional.   | COMPLETED ON / BY                     |
| Certification.<br>REFERENCE RB-MIA9HJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door A57JCK (Floor: GF. Location: Corridor / stair lobby)<br>DUE BY / ASSIGNEDTO<br>22 April 2025<br>Door selector not functional.<br>Certification.<br>REFERENCE RB-X3QD9D<br>SEVERITY Property Protection   | COMPLETED ON / BY                     |
| Certification.<br>REFERENCE RB-MIA9HJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door A57JCK (Floor: GF. Location: Corridor / stair lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Door selector not functional.<br>Certification.<br>REFERENCE RB-X3QD9D<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9NGMW8 (Floor: GF. Location: Corridor next to unit 19)<br>DUE BY / ASSIGNED TO<br>22 April 2025   |                                       |
| Certification.<br>REFERENCE RB-MIA9HJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door A57JCK (Floor: GF. Location: Corridor / stair lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Door selector not functional.<br>Certification.<br>REFERENCE RB-X3QD9D<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9NGMW8 (Floor: GF. Location: Corridor next to unit 19)<br>DUE BY / ASSIGNED TO  |                                       |
| Certification.<br>REFERENCE RB-MIA9HJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door A57JCK (Floor: GF. Location: Corridor / stair lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Door selector not functional.<br>Certification.<br>REFERENCE RB-X3QD9D<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9NGMW8 (Floor: GF. Location: Corridor next to unit 19)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Door selector not functional.<br>Certification.<br>REFERENCE RB-712VE1                                 |                                       |
| Certification.<br>REFERENCE RB-MIA9HJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door A57JCK (Floor: GF. Location: Corridor / stair lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Door selector not functional.<br>Certification.<br>REFERENCE RB-X3QD9D<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9NGMW8 (Floor: GF. Location: Corridor next to unit 19)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Door selector not functional.<br>Certification.  |                                       |
| Certification.<br>REFERENCE RB-MIA9HJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door A57JCK (Floor: GF. Location: Corridor / stair lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Door selector not functional.<br>Certification.<br>REFERENCE RB-X3QD9D<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9NGMW8 (Floor: GF. Location: Corridor next to unit 19)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Door selector not functional.<br>Certification.<br>REFERENCE RB-712VE1<br>SEVERITY Property Protection |                                       |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 286 370 V Risk Base

| Fit a fire door keep locked shut sign.   |                   |
|--|-------------------|
| REFERENCE RB-4JAT6U<br>SEVERITY Property Protection<br>ELEMENT Fire Door E6EE7R (Floor: GF. Location: Unit 56)             |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Fit a fire door keep locked shut sign.   |                   |
| REFERENCE RB-Y2DIPK<br>SEVERITY Property Protection<br>ELEMENT Fire Door MNQKSS (Floor: GF. Location: Unit 54)             |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Fit a fire door keep locked shut sign.   |                   |
| REFERENCE RB-XF4CYH<br>SEVERITY Property Protection<br>ELEMENT Fire Door QDQ9R3 (Floor: GF. Location: Unit 53)             |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Fit a fire door keep locked shut sign.   |                   |
| REFERENCE RB-G8WPE5<br>SEVERITY Property Protection<br>ELEMENT Fire Door NL5VST (Floor: GF. Location: Howard Building)     |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Fit a fire door keep locked shut sign.   |                   |
| REFERENCE RB-4ZW47L<br>SEVERITY Property Protection<br>ELEMENT Fire Door HVHKZH (Floor: GF. Location: Howard Building)     |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Fit a fire door keep locked shut sign.   |                   |
| REFERENCE RB-7CN911<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)     |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |
| Fit a fire door keep locked shut sign.   |                   |
| REFERENCE RB-N47PHD<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZACXD (Floor: Ground. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |



| Fit a fire door keep locked shut sign.   |                   |
|--|-------------------|
| REFERENCE RB-CP2XIP<br>SEVERITY Property Protection<br>ELEMENT Fire Door EXID89 (Floor: Ground. Location: Howard Building)       |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Fit a fire door keep locked shut sign.   |                   |
| REFERENCE RB-V13N9X<br>SEVERITY Property Protection<br>ELEMENT Fire Door 3E3PHK (Floor: Ground. Location: Howard Building)       |                   |
| due by / Assigned to 22 April 2025   | COMPLETED ON / BY |
| Fit a fire door keep locked shut sign.   |                   |
| REFERENCE RB-SR9HCL<br>SEVERITY Property Protection<br>ELEMENT Fire Door X6Y1YG (Floor: Second floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |
| Fit a fire door keep locked shut sign.   |                   |
| REFERENCE RB-2FI3LQ<br>SEVERITY Property Protection<br>ELEMENT Fire Door MYQB29 (Floor: Second floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Fit a fire door keep locked shut sign.   |                   |
| REFERENCE RB-QLAS29<br>SEVERITY Property Protection<br>ELEMENT Fire Door PZSHGC (Floor: Second floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |
| Fit a fire door keep locked shut sign.   |                   |
| REFERENCE RB-JAN4ID<br>SEVERITY Property Protection<br>ELEMENT Fire Door UR51QI (Floor: Second floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.                               |                   |
| REFERENCE RB-XQNXAN  |                   |
| SEVERITY Property Protection<br>ELEMENT Fire Door E6EE7R (Floor: GF. Location: Unit 56)  |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 288 370 V Risk Base

| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.   |                   |
|--|-------------------|
| REFERENCE RB-6QI6CY<br>SEVERITY Property Protection<br>ELEMENT Fire Door MNQKSS (Floor: GF. Location: Unit 54)   |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.   |                   |
| REFERENCE RB-ZPZQZN<br>SEVERITY Property Protection<br>ELEMENT Fire Door 37DAH3 (Floor: GF. Location: Male WC)   |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.   |                   |
| REFERENCE RB-IDGP62<br>SEVERITY Property Protection<br>ELEMENT Fire Door L3UT9D (Floor: GF. Location: Female WC)   |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Fit intumescent seals to the door frame.   |                   |
| Seals are damaged or missing in sections of the frame.   |                   |
|  |                   |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-58HGP2<br>SEVERITY Property Protection  | COMPLETED ON / BY |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-58HGP2<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)   | COMPLETED ON / BY |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-58HGP2<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.  | COMPLETED ON / BY |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-58HGP2<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-S9W411<br>SEVERITY Property Protection   | COMPLETED ON / BY |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-58HGP2<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-S9W411<br>SEVERITY Property Protection<br>ELEMENT Fire Door JRZGWA (Floor: GF. Location: Corridor lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025  |                   |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-58HGP2<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-S9W411<br>SEVERITY Property Protection<br>ELEMENT Fire Door JRZGWA (Floor: GF. Location: Corridor lobby)<br>DUE BY / ASSIGNED TO   |                   |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-58HGP2<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-S9W411<br>SEVERITY Property Protection<br>ELEMENT Fire Door JRZGWA (Floor: GF. Location: Corridor lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.  |                   |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-58HGP2<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-S9W411<br>SEVERITY Property Protection<br>ELEMENT Fire Door JRZGWA (Floor: GF. Location: Corridor lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-M35MAY<br>SEVERITY Property Protection |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 289 370 V Risk Base

| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.                              |                   |
|---|-------------------|
| REFERENCE RB-U4CY2Y<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9NGMW8 (Floor: GF. Location: Corridor next to unit 19) |                   |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.                              |                   |
| REFERENCE RB-HUSEK5<br>SEVERITY Property Protection<br>ELEMENT Fire Door 3JXMUG (Floor: GF. Location: Corridor next to unit 23) |                   |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.                              |                   |
| REFERENCE RB-2C3DEG<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)         |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.                              |                   |
| REFERENCE RB-XFXG5T<br>SEVERITY Property Protection<br>ELEMENT Fire Door PCXWMV (Floor: GF. Location: Corridor next to unit 15) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.                              |                   |
| REFERENCE RB-1WRP9X<br>SEVERITY Property Protection<br>ELEMENT Fire Door TYV5EP (Floor: GF. Location: Corridor next to unit 47) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Eit intumorcont coals to the dear frame   |                   |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.                              |                   |
| REFERENCE RB-AXPNQ5<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4Y6J1S (Floor: GF. Location: Corridor near to unit 48) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 290 370 V Risk Base



| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.                             |   |
|--|---|
| REFERENCE RB-1RQ5JF<br>SEVERITY Property Protection<br>ELEMENT Fire Door PJGGE7 (Floor: Basement. Location: Escape lobby door) |   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY   |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.                             |   |
| REFERENCE RB-IRVNN9<br>SEVERITY Property Protection<br>ELEMENT Fire Door L5NNXW (Floor: Basement. Location: Rear workshop # 2) |   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY   |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame. Seals are b                 | roken where hinges are located, seals do not butt together. |
| REFERENCE RB-YC64LX<br>SEVERITY Property Protection<br>ELEMENT Fire Door FQ56JD (Floor: GF. Location: Howard Building)         |   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY   |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.                             |   |
| REFERENCE RB-D65AZ2<br>SEVERITY Property Protection<br>ELEMENT Fire Door SQWDQ7 (Floor: GF. Location: Howard Building)         |   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY   |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.                             |   |
| REFERENCE RB-VH3Z15<br>SEVERITY Property Protection<br>ELEMENT Fire Door QWSMXS (Floor: GF. Location: Howard Building)         |   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY   |
| Fit intumescent seals to the door frame.   |   |
| Seals are damaged or missing in sections of the frame.   |   |
| REFERENCE RB-AZ3U42<br>SEVERITY Property Protection<br>ELEMENT Fire Door NL5VST (Floor: GF. Location: Howard Building)         |   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 291 370 V Risk Base



| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.  |                   |
|---|-------------------|
| REFERENCE RB-E2JDMR<br>SEVERITY Property Protection<br>ELEMENT Fire Door 8V34BM (Floor: GF. Location: Howard Building)  |                   |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.  |                   |
| REFERENCE RB-X8X746<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)  |                   |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.  |                   |
| REFERENCE RB-83BZMQ<br>SEVERITY Property Protection<br>ELEMENT Fire Door HVHKZH (Floor: GF. Location: Howard Building)  |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.  |                   |
|   |                   |
| REFERENCE RB-GBZNMV<br>SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)  |                   |
| SEVERITY Property Protection  | COMPLETED ON / BY |
| SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO   | COMPLETED ON / BY |
| SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.  | COMPLETED ON / BY |
| SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-73Z4VQ<br>SEVERITY Property Protection   | COMPLETED ON / BY |
| SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-73Z4VQ<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO  |                   |
| SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-73Z4VQ<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025   |                   |
| SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-73Z4VQ<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame. |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 292 370 VRISKBASE



| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame. Hinges and   | d door contacts break the seal line. |
|---|--------------------------------------|
| REFERENCE RB-Z2J661<br>SEVERITY Property Protection<br>ELEMENT Fire Door WSTDT3 (Floor: First floor. Location: Howard Building)   |                                      |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY                    |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.  |                                      |
| REFERENCE RB-ZNTEHH<br>SEVERITY Property Protection<br>ELEMENT Fire Door D7CUPT (Floor: First floor. Location: Howard Building)   |                                      |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY                    |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.  |                                      |
| REFERENCE RB-8UPBSQ<br>SEVERITY Property Protection<br>ELEMENT Fire Door DVCJM6 (Floor: First floor. Location: Howard Building)   |                                      |
| due By / Assigned to<br>22 April 2025   | COMPLETED ON / BY                    |
|   |                                      |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame. Intumesce  | nt line broken by hinges.            |
|   | nt line broken by hinges.            |
| Seals are damaged or missing in sections of the frame. Intumesce<br>REFERENCE RB-DUN41H<br>SEVERITY Property Protection   | nt line broken by hinges.            |
| Seals are damaged or missing in sections of the frame. Intumesce<br>REFERENCE RB-DUN41H<br>SEVERITY Property Protection<br>ELEMENT Fire Door XSJL8M (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO   |                                      |
| Seals are damaged or missing in sections of the frame. Intumesce<br>REFERENCE RB-DUN41H<br>SEVERITY Property Protection<br>ELEMENT Fire Door XSJL8M (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.  |                                      |
| Seals are damaged or missing in sections of the frame. Intumesce<br>REFERENCE RB-DUN41H<br>SEVERITY Property Protection<br>ELEMENT Fire Door XSJL8M (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-CKWUQ1<br>SEVERITY Property Protection   |                                      |
| Seals are damaged or missing in sections of the frame. Intumesce<br>REFERENCE RB-DUN41H<br>SEVERITY Property Protection<br>ELEMENT Fire Door XSJL8M (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-CKWUQ1<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9ZUWI7 (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY                    |
| Seals are damaged or missing in sections of the frame. Intumesce<br>REFERENCE RB-DUN41H<br>SEVERITY Property Protection<br>ELEMENT Fire Door XSJL8M (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-CKWUQ1<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9ZUWI7 (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO   | COMPLETED ON / BY                    |
| Seals are damaged or missing in sections of the frame. Intumesce<br>REFERENCE RB-DUN41H<br>SEVERITY Property Protection<br>ELEMENT Fire Door XSJL8M (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-CKWUQ1<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9ZUWI7 (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-VG53F4<br>SEVERITY Property Protection | COMPLETED ON / BY                    |
| Seals are damaged or missing in sections of the frame. Intumesce<br>REFERENCE RB-DUN41H<br>SEVERITY Property Protection<br>ELEMENT Fire Door XSJL8M (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-CKWUQ1<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9ZUWI7 (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-CKGSF4                                 | COMPLETED ON / BY                    |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 293 370 V Risk Base



| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.   |  |
|--|--|
| REFERENCE RB-6TUUP3<br>SEVERITY Property Protection<br>ELEMENT Fire Door EXID89 (Floor: Ground. Location: Howard Building)   |  |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY                      |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.   |  |
| REFERENCE RB-EWW6KA<br>SEVERITY Property Protection<br>ELEMENT Fire Door 3E3PHK (Floor: Ground. Location: Howard Building)   |  |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY                      |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.   |  |
| REFERENCE RB-8BJ152<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)   |  |
| due BY / Assigned to<br>22 April 2025  | COMPLETED ON / BY                      |
|  |  |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.   |  |
|  |  |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-6UGHAL<br>SEVERITY Property Protection  | COMPLETED ON / BY                      |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-6UGHAL<br>SEVERITY Property Protection<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building)   | COMPLETED ON / BY                      |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-6UGHAL<br>SEVERITY Property Protection<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.  | COMPLETED ON / BY                      |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-6UGHAL<br>SEVERITY Property Protection<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-XT7INS<br>SEVERITY Property Protection   | COMPLETED ON / BY<br>COMPLETED ON / BY |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-6UGHAL<br>SEVERITY Property Protection<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-XT7INS<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9EN3B8 (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025  |  |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-6UGHAL<br>SEVERITY Property Protection<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-XT7INS<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9EN3B8 (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO   |  |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-6UGHAL<br>SEVERITY Property Protection<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-XT7INS<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9EN3B8 (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-PAT24M                                 |  |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-6UGHAL<br>SEVERITY Property Protection<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-XT7INS<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9EN3B8 (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.  |  |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-6UGHAL<br>SEVERITY Property Protection<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-XT7INS<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9EN3B8 (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-PAT24M<br>SEVERITY Property Protection |  |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 294 370 V Risk Base



| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.  |                   |
|---|-------------------|
| REFERENCE RB-YQDBV3<br>SEVERITY Property Protection<br>ELEMENT Fire Door BAI8Z6 (Floor: First floor. Location: Howard Building)   |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.  |                   |
| REFERENCE RB-76CG6G<br>SEVERITY Property Protection<br>ELEMENT Fire Door 2H5NBL (Floor: First floor. Location: Howard Building)   |                   |
| due by / Assigned to 22 April 2025  | COMPLETED ON / BY |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.  |                   |
| REFERENCE RB-HT7LG6<br>SEVERITY Property Protection<br>ELEMENT Fire Door X6Y1YG (Floor: Second floor. Location: Howard Building)  |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
|   |                   |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.  |                   |
|   |                   |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE <b>RB-STAIDZ</b><br>SEVERITY <b>Property Protection</b>   | COMPLETED ON / BY |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-STAIDZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door MYQB29 (Floor: Second floor. Location: Howard Building)  | COMPLETED ON / BY |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-STAIDZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door MYQB29 (Floor: Second floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.   | COMPLETED ON / BY |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-STAIDZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door MYQB29 (Floor: Second floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-V8APFM<br>SEVERITY Property Protection  | COMPLETED ON / BY |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-STAIDZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door MYQB29 (Floor: Second floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-V8APFM<br>SEVERITY Property Protection<br>ELEMENT Fire Door PZSHGC (Floor: Second floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO   |                   |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-STAIDZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door MYQB29 (Floor: Second floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-V8APFM<br>SEVERITY Property Protection<br>ELEMENT Fire Door PZSHGC (Floor: Second floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-113GHK<br>SEVERITY Property Protection   |                   |
| Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-STAIDZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door MYQB29 (Floor: Second floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-V8APFM<br>SEVERITY Property Protection<br>ELEMENT Fire Door PZSHGC (Floor: Second floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-USAPFM<br>Second Floor. Location: Howard Building)<br>REFERENCE RB-USAPFM<br>Seals are damaged or missing in sections of the frame.<br>REFERENCE RB-113GHK |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 295 370 VRISKBASE



| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.  |                   |
|---|-------------------|
| REFERENCE RB-MKF5EC<br>SEVERITY Property Protection<br>ELEMENT Fire Door 468GQH (Floor: First floor. Location: Howard Building)   |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door   | or survey.        |
| REFERENCE RB-7LP8JH<br>SEVERITY Property Protection<br>ELEMENT Fire Door NY5RCM (Floor: GF. Location: Unit 20)  |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door   | or survey.        |
| REFERENCE RB-B9152V<br>SEVERITY Property Protection<br>ELEMENT Fire Door 5ARPDA (Floor: GF. Location: Unit 19)  |                   |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.  |                   |
| The assessor had limited access to the door during the routine door   | or survey.        |
|   | ər survey.        |
| The assessor had limited access to the door during the routine door<br>REFERENCE RB-VLRH14<br>SEVERITY Property Protection  | or survey.        |
| The assessor had limited access to the door during the routine door<br>REFERENCE RB-VLRH14<br>SEVERITY Property Protection<br>ELEMENT Fire Door HHN85J (Floor: GF. Location: Unit 26)<br>DUE BY / ASSIGNED TO   | COMPLETED ON / BY |
| The assessor had limited access to the door during the routine door<br>REFERENCE RB-VLRH14<br>SEVERITY Property Protection<br>ELEMENT Fire Door HHN85J (Floor: GF. Location: Unit 26)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Have the door fully inspected by a competent person.  | COMPLETED ON / BY |
| The assessor had limited access to the door during the routine door<br>REFERENCE RB-VLRH14<br>SEVERITY Property Protection<br>ELEMENT Fire Door HHN85J (Floor: GF. Location: Unit 26)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door<br>REFERENCE RB-1Y2KHN<br>SEVERITY Property Protection  | COMPLETED ON / BY |
| The assessor had limited access to the door during the routine door<br>REFERENCE RB-VLRH14<br>SEVERITY Property Protection<br>ELEMENT Fire Door HHN85J (Floor: GF. Location: Unit 26)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door<br>REFERENCE RB-1Y2KHN<br>SEVERITY Property Protection<br>ELEMENT Fire Door ZHJ6V9 (Floor: GF. Location: Unit 1)<br>DUE BY / ASSIGNED TO  | COMPLETED ON / BY |
| The assessor had limited access to the door during the routine door<br>REFERENCE RB-VLRH14<br>SEVERITY Property Protection<br>ELEMENT Fire Door HHN85J (Floor: GF. Location: Unit 26)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door<br>REFERENCE RB-1Y2KHN<br>SEVERITY Property Protection<br>ELEMENT Fire Door ZHJ6V9 (Floor: GF. Location: Unit 1)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Have the door fully inspected by a competent person. | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 296 370 V Risk Base

| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door         | survey.           |
|---|-------------------|
| REFERENCE RB-RAIVR8<br>SEVERITY Property Protection<br>ELEMENT Fire Door DEUWJF (Floor: GF. Location: Unit 17)                      |                   |
| due by / Assigned to 22 April 2025  | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door         | survey.           |
| REFERENCE RB-CDS6ER<br>SEVERITY Property Protection<br>ELEMENT Fire Door U5UZU4 (Floor: GF. Location: Unit 16)                      |                   |
| due by / Assigned to 22 April 2025  | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door         | survey.           |
| REFERENCE RB-KYG32J<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9ZN8AS (Floor: Basement. Location: Unit 7)                 |                   |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door         | survey.           |
| REFERENCE RB-496N9R<br>SEVERITY Property Protection<br>ELEMENT Fire Door J4UUYW (Floor: Basement. Location: Unit 8)                 |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door         | survey.           |
| REFERENCE RB-WCPRZR<br>SEVERITY Property Protection<br>ELEMENT Fire Door SY5BVL (Floor: Basement. Location: Unit 9A)                |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door         | survey.           |
| REFERENCE RB-VFUYH7<br>SEVERITY Property Protection<br>ELEMENT Fire Door 68TD97 (Floor: Basement. Location: Restricted access door) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 297 370 **Risk**Base

| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door sur        | rvey.         |
|--|---------------|
| REFERENCE RB-YLFPIZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door CFM2DV (Floor: Basement. Location: Restricted access door #2  | )             |
| DUE BY / ASSIGNED TO COMPL<br>22 April 2025  | LETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door sur        | rvey.         |
| REFERENCE RB-NHJIAV<br>SEVERITY Property Protection<br>ELEMENT Fire Door DV9HIX (Floor: Basement. Location: Restricted access door #3) |               |
| DUE BY / ASSIGNED TO COMPL<br>22 April 2025  | LETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door su         | rvey.         |
| REFERENCE RB-U7ZETU<br>SEVERITY Property Protection<br>ELEMENT Fire Door 3367EB (Floor: Basement. Location: Unit 9B)                   |               |
| DUE BY / ASSIGNED TO COMPL<br>22 April 2025  | LETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door sur        | rvey.         |
| REFERENCE RB-23S1ZN<br>SEVERITY Property Protection<br>ELEMENT Fire Door M1P5E6 (Floor: Basement. Location: Meter room)                |               |
| DUE BY / ASSIGNED TO COMPL<br>22 April 2025  | LETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door su         | rvey.         |
| REFERENCE RB-EEPA4K<br>SEVERITY Property Protection<br>ELEMENT Fire Door 3BT7KS (Floor: First floor. Location: Howard Building)        |               |
| DUE BY / ASSIGNED TO COMPL<br>22 April 2025  | LETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door sur        | rvey.         |
| REFERENCE RB-9ZK26K<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9SR5PD (Floor: First floor. Location: Howard Building)        |               |
| DUE BY / ASSIGNED TO COMPL<br>22 April 2025  | LETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 298 370 V Risk Base



| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door     | survey.           |
|---|-------------------|
| REFERENCE RB-S68YQJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door DGAH7G (Floor: First floor. Location: Howard Building) |                   |
| due by / Assigned to 22 April 2025  | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door     | survey.           |
| REFERENCE RB-TBLNP4<br>SEVERITY Property Protection<br>ELEMENT Fire Door LVGI7I (Floor: First floor. Location: Howard Building) |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door     | survey.           |
| REFERENCE RB-6TA561<br>SEVERITY Property Protection<br>ELEMENT Fire Door 7CY73Z (Floor: First floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door     | survey.           |
| REFERENCE RB-JVVEK3<br>SEVERITY Property Protection<br>ELEMENT Fire Door DP9XRM (Floor: First floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door     | survey.           |
| REFERENCE RB-FTENSQ<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FU1H8 (Floor: First floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door     | survey.           |
| REFERENCE RB-S45K1V<br>SEVERITY Property Protection<br>ELEMENT Fire Door LRRGE8 (Floor: First floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |



| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine do       | or survey.        |
|---|-------------------|
| REFERENCE RB-UJXJBP<br>SEVERITY Property Protection<br>ELEMENT Fire Door 8IKCET (Floor: First floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine do       | or survey.        |
| REFERENCE RB-SQUX6J<br>SEVERITY Property Protection<br>ELEMENT Fire Door L84BB4 (Floor: First floor. Location: Howard Building) |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine do       | or survey.        |
| REFERENCE RB-TTWMC6<br>SEVERITY Property Protection<br>ELEMENT Fire Door 2VNJ9V (Floor: First floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Install a door closer compliant to BS EN1154.<br>To ensure heat and smoke cannot pass through to escape route.                  |                   |
| REFERENCE RB-KR1A2X<br>SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)          |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Panic bolt fouling on RH leaf.<br>Stops door closing - see images.  |                   |
| REFERENCE RB-LATACU<br>SEVERITY Property Protection<br>ELEMENT Fire Door FQ56JD (Floor: GF. Location: Howard Building)          |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Re fix hinges correctly, not fitted flush.<br>Hinges badly fitted.  |                   |
| REFERENCE RB-1GFPHB<br>SEVERITY Property Protection<br>ELEMENT Fire Door FQ56JD (Floor: GF. Location: Howard Building)          |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |



| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.   |  |
|---|--|
| REFERENCE RB-Q41Q9S<br>SEVERITY Property Protection<br>ELEMENT Fire Door 37DAH3 (Floor: GF. Location: Male WC)  |  |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY                      |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.   |  |
| REFERENCE RB-KWNYDC<br>SEVERITY Property Protection<br>ELEMENT Fire Door L3UT9D (Floor: GF. Location: Female WC)  |  |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY                      |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.   |  |
| REFERENCE RB-PHVNTN<br>SEVERITY Property Protection<br>ELEMENT Fire Door QDQ9R3 (Floor: GF. Location: Unit 53)  |  |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY                      |
|   |  |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.   |  |
|   |  |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-SE2J82<br>SEVERITY Property Protection  | COMPLETED ON / BY                      |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-SE2J82<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q2XDJJ (Floor: GF. Location: Patra Corridor Lobby)  | COMPLETED ON / BY                      |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-SE2J82<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q2XDJJ (Floor: GF. Location: Patra Corridor Lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.   | COMPLETED ON / BY                      |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-SE2J82<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q2XDJJ (Floor: GF. Location: Patra Corridor Lobby)<br>DUE BY / ASSIGNEDTO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-LEIPIC<br>SEVERITY Property Protection  | COMPLETED ON / BY<br>COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-SE2J82<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q2XDJJ (Floor: GF. Location: Patra Corridor Lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-LEIPIC<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025   |  |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-SE2J82<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q2XDJJ (Floor: GF. Location: Patra Corridor Lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-LEIPIC<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO  |  |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-SE2J82<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q2XDJJ (Floor: GF. Location: Patra Corridor Lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-LEIPIC<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-TATIGK8                                |  |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-SE2J82<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q2XDJJ (Floor: GF. Location: Patra Corridor Lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-LEIPIC<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |  |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-SE2J82<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q2XDJJ (Floor: GF. Location: Patra Corridor Lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-LEIPIC<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-7ATGK8<br>SEVERITY Property Protection |  |



| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.   |  |
|---|--|
| REFERENCE RB-WYVA13<br>SEVERITY Property Protection<br>ELEMENT Fire Door A57JCK (Floor: GF. Location: Corridor / stair lobby)   |  |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY                      |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.   |  |
| REFERENCE RB-R82X1Z<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9NGMW8 (Floor: GF. Location: Corridor next to unit 19)   |  |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY                      |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.   |  |
| REFERENCE RB-QFDN2T<br>SEVERITY Property Protection<br>ELEMENT Fire Door 3JXMUG (Floor: GF. Location: Corridor next to unit 23)   |  |
| due By / Assigned to<br>22 April 2025   | COMPLETED ON / BY                      |
|   |  |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.   |  |
|   |  |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-2PCGBG<br>SEVERITY Property Protection  | COMPLETED ON / BY                      |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-2PCGBG<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)  | COMPLETED ON / BY                      |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-2PCGBG<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.   | COMPLETED ON / BY                      |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-2PCGBG<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)<br>DUE BY / ASSIGNEDTO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-94CGLU<br>SEVERITY Property Protection  | COMPLETED ON / BY<br>COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-2PCGBG<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-94CGLU<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18)<br>DUE BY / ASSIGNED TO<br>22 April 2025  |  |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-2PCGBG<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-94CGLU<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18)<br>DUE BY / ASSIGNED TO   |  |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-2PCGBG<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-94CGLU<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.  |  |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-2PCGBG<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-94CGLU<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-8tWeen the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-KTCDPA<br>SEVERITY Property Protection |  |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 302 370 V Risk Base



| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
|--|-------------------|
| REFERENCE RB-RUXJGS<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4Y6J1S (Floor: GF. Location: Corridor near to unit 48)  |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
| REFERENCE RB-3F66Z9<br>SEVERITY Property Protection<br>ELEMENT Fire Door PJGGE7 (Floor: Basement. Location: Escape lobby door)   |                   |
| due by / Assigned to 22 April 2025   | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
| REFERENCE RB-SMT2ST<br>SEVERITY Property Protection<br>ELEMENT Fire Door L5NNXW (Floor: Basement. Location: Rear workshop # 2)   |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
|  |                   |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
|  |                   |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-VJS9MM<br>SEVERITY Property Protection   | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-VJS9MM<br>SEVERITY Property Protection<br>ELEMENT Fire Door SQWDQ7 (Floor: GF. Location: Howard Building)  | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-VJS9MM<br>SEVERITY Property Protection<br>ELEMENT Fire Door SQWDQ7 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.   | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-VJS9MM<br>SEVERITY Property Protection<br>ELEMENT Fire Door SQWDQ7 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-B242KE<br>SEVERITY Property Protection   | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-VJS9MM<br>SEVERITY Property Protection<br>ELEMENT Fire Door SQWDQ7 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-B242KE<br>SEVERITY Property Protection<br>ELEMENT Fire Door NL5VST (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO  |                   |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-VJS9MM<br>SEVERITY Property Protection<br>ELEMENT Fire Door SQWDQ7 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-B242KE<br>SEVERITY Property Protection<br>ELEMENT Fire Door NL5VST (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025   |                   |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-VJS9MM<br>SEVERITY Property Protection<br>ELEMENT Fire Door SQWDQ7 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-B242KE<br>SEVERITY Property Protection<br>ELEMENT Fire Door NL5VST (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-B242KE<br>REGUCE Gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-JTRSGR |                   |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-VJS9MM<br>SEVERITY Property Protection<br>ELEMENT Fire Door SQWDQ7 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-B242KE<br>SEVERITY Property Protection<br>ELEMENT Fire Door NL5VST (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-VJS9MM<br>SEVERITY Property Protection<br>ELEMENT Fire Door SQWDQ7 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-B242KE<br>SEVERITY Property Protection<br>ELEMENT Fire Door NL5VST (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-JTRSGR<br>SEVERITY Property Protection   |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 303 370 VRISKBASE

| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
|--|-------------------|
| REFERENCE RB-9DNS8I<br>SEVERITY Property Protection<br>ELEMENT Fire Door 8V34BM (Floor: GF. Location: Howard Building)   |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
| REFERENCE RB-DV5CLQ<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)   |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
| REFERENCE RB-1CNKCK<br>SEVERITY Property Protection<br>ELEMENT Fire Door HVHKZH (Floor: GF. Location: Howard Building)   |                   |
| due By / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
|  |                   |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
|  |                   |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE <b>RB-ELBLFJ</b><br>SEVERITY <b>Property Protection</b>   | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-ELBLFJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)  | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-ELBLFJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.   | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-ELBLFJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-WUEBN1<br>SEVERITY Property Protection   | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-ELBLFJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-WUEBN1<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO  |                   |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-ELBLFJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-WUEBN1<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame. |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 304 370 V Risk Base



| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
|--|-------------------|
| REFERENCE RB-MHLNJ4<br>SEVERITY Property Protection<br>ELEMENT Fire Door D7CUPT (Floor: First floor. Location: Howard Building)  |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
| REFERENCE RB-TALBMN<br>SEVERITY Property Protection<br>ELEMENT Fire Door DVCJM6 (Floor: First floor. Location: Howard Building)  |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
| REFERENCE RB-AVXC7U<br>SEVERITY Property Protection<br>ELEMENT Fire Door XSJL8M (Floor: First floor. Location: Howard Building)  |                   |
| due By / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
| REFERENCE RB-6141C9<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9ZUWI7 (Floor: First floor. Location: Howard Building)  |                   |
| due BY / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.   |                   |
| To ensure heat and smoke cannot pass through to escape route.  |                   |
| REFERENCE RB-E9GVAC<br>SEVERITY Property Protection<br>ELEMENT Fire Door FTZ3EB (Floor: First floor. Location: Howard Building)  |                   |
| REFERENCE <b>RB-E9GVAC</b><br>SEVERITY <b>Property Protection</b>  | COMPLETED ON / BY |
| REFERENCE RB-E9GVAC<br>SEVERITY Property Protection<br>ELEMENT Fire Door FTZ3EB (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| REFERENCE RB-E9GVAC<br>SEVERITY Property Protection<br>ELEMENT Fire Door FTZ3EB (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO  | COMPLETED ON / BY |
| REFERENCE RB-E9GVAC<br>SEVERITY Property Protection<br>ELEMENT Fire Door FTZ3EB (Floor: First floor. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.   | COMPLETED ON / BY |
| REFERENCE RB-E9GVAC<br>SEVERITY Property Protection<br>ELEMENT Fire Door FTZ3EB (Floor: First floor. Location: Howard Building)<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-UF3L3W<br>SEVERITY Property Protection | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 305 370 V Risk Base



| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.   |                   |
|---|-------------------|
| REFERENCE RB-BY1334<br>SEVERITY Property Protection<br>ELEMENT Fire Door EXID89 (Floor: Ground. Location: Howard Building)  |                   |
| due BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.   |                   |
| REFERENCE RB-6QZ4MZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door 3E3PHK (Floor: Ground. Location: Howard Building)  |                   |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.   |                   |
| REFERENCE RB-B77PBQ<br>SEVERITY Property Protection<br>ELEMENT Fire Door TKJLLH (Floor: Ground. Location: Howard Building)  |                   |
| due BY / Assigned to 22 April 2025  | COMPLETED ON / BY |
|   |                   |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.   |                   |
|   |                   |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-1TB4KL<br>SEVERITY Property Protection  | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-1TB4KL<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)   | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-1TB4KL<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.  | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route. REFERENCE RB-1TB4KL SEVERITY Property Protection ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building) DUE BY / ASSIGNED TO 22 April 2025 Reduce gaps between the door and the door frame. To ensure heat and smoke cannot pass through to escape route. REFERENCE RB-42B87C SEVERITY Property Protection   | COMPLETED ON / BY |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-1TB4KL<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-42B87C<br>SEVERITY Property Protection<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025  |                   |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-1TB4KL<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-42B87C<br>SEVERITY Property Protection<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building)<br>DUE BY / ASSIGNED TO   |                   |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-1TB4KL<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-42B87C<br>SEVERITY Property Protection<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building)<br>OUE BY / ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.  |                   |
| To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-1TB4KL<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)<br>DUE BY/ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-42B87C<br>SEVERITY Property Protection<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building)<br>DUE BY/ASSIGNED TO<br>22 April 2025<br>Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.<br>REFERENCE RB-42B87C<br>SEVERITY Property Protection<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building) |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 306 370 V Risk Base

| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.                |                   |
|--|-------------------|
| REFERENCE RB-4XUDH8<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q99RL7 (Floor: First floor. Location: Howard Building)  |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.                |                   |
| REFERENCE RB-EQGAV6<br>SEVERITY Property Protection<br>ELEMENT Fire Door D7CUPT (Floor: First floor. Location: Howard Building)  |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.                |                   |
| REFERENCE RB-T9XVBN<br>SEVERITY Property Protection<br>ELEMENT Fire Door BAI8Z6 (Floor: First floor. Location: Howard Building)  |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.                |                   |
| REFERENCE RB-IURS7E<br>SEVERITY Property Protection<br>ELEMENT Fire Door 2H5NBL (Floor: First floor. Location: Howard Building)  |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.                |                   |
| REFERENCE RB-LW1AR6<br>SEVERITY Property Protection<br>ELEMENT Fire Door X6Y1YG (Floor: Second floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.                |                   |
| REFERENCE RB-7MU64H<br>SEVERITY Property Protection<br>ELEMENT Fire Door MYQB29 (Floor: Second floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |



| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
|--|-------------------|
| REFERENCE RB-X3U5AE<br>SEVERITY Property Protection<br>ELEMENT Fire Door PZSHGC (Floor: Second floor. Location: Howard Building)   |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
| REFERENCE RB-LVSP1Q<br>SEVERITY Property Protection<br>ELEMENT Fire Door UR51QI (Floor: Second floor. Location: Howard Building)   |                   |
| due By / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.  |                   |
| REFERENCE RB-AYWK1A<br>SEVERITY Property Protection<br>ELEMENT Fire Door 468GQH (Floor: First floor. Location: Howard Building)  |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.   |                   |
| The door is not fit for purpose.   |                   |
| The door is not fit for purpose.<br>REFERENCE RB-DDHLKN<br>SEVERITY Property Protection<br>ELEMENT Fire Door SNGHXD (Floor: GF. Location: Stair lobby)   |                   |
| REFERENCE RB-DDHLKN<br>SEVERITY Property Protection  | COMPLETED ON / BY |
| REFERENCE RB-DDHLKN<br>SEVERITY Property Protection<br>ELEMENT Fire Door SNGHXD (Floor: GF. Location: Stair lobby)<br>DUE BY / ASSIGNED TO   | COMPLETED ON / BY |
| REFERENCE RB-DDHLKN<br>SEVERITY Property Protection<br>ELEMENT Fire Door SNGHXD (Floor: GF. Location: Stair lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.  | COMPLETED ON / BY |
| REFERENCE RB-DDHLKN<br>SEVERITY Property Protection<br>ELEMENT Fire Door SNGHXD (Floor: GF. Location: Stair lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose.<br>REFERENCE RB-PTKCBM<br>SEVERITY Property Protection   | COMPLETED ON / BY |
| REFERENCE RB-DDHLKN<br>SEVERITY Property Protection<br>ELEMENT Fire Door SNGHXD (Floor: GF. Location: Stair lobby)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose.<br>REFERENCE RB-PTKCBM<br>SEVERITY Property Protection<br>ELEMENT Fire Door G8Z1TF (Floor: GF. Location: Patra interview)<br>DUE BY / ASSIGNED TO                                      |                   |
| REFERENCE RB-DDHLKN<br>SEVERITY Property Protection<br>ELEMENT Fire Door SNGHXD (Floor: GF. Location: Stair lobby)<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose.<br>REFERENCE RB-PTKCBM<br>SEVERITY Property Protection<br>ELEMENT Fire Door G8Z1TF (Floor: GF. Location: Patra interview)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door. |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 308 370 V Risk Base



| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.  |  |
|---|--|
| REFERENCE RB-5CDU9P<br>SEVERITY Property Protection<br>ELEMENT Fire Door 6STZGB (Floor: GF. Location: Unit 13)  |  |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY                      |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.  |  |
| REFERENCE RB-DYD7XG<br>SEVERITY Property Protection<br>ELEMENT Fire Door V35D7F (Floor: GF. Location: Unit 40)  |  |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY                      |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.  |  |
| REFERENCE RB-61HA96<br>SEVERITY Property Protection<br>ELEMENT Fire Door I7QXFQ (Floor: GF. Location: Unit 35 / 01)   |  |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY                      |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.  |  |
|   |  |
| REFERENCE RB-ZKZXPK<br>SEVERITY Property Protection<br>ELEMENT Fire Door IQM8RF (Floor: GF. Location: Unit 36)  |  |
| SEVERITY Property Protection  | COMPLETED ON / BY                      |
| SEVERITY Property Protection<br>ELEMENT Fire Door IQM8RF (Floor: GF. Location: Unit 36)<br>DUE BY / ASSIGNED TO   | COMPLETED ON / BY                      |
| SEVERITY Property Protection<br>ELEMENT Fire Door IQM8RF (Floor: GF. Location: Unit 36)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.  | COMPLETED ON / BY                      |
| SEVERITY Property Protection<br>ELEMENT Fire Door IQM8RF (Floor: GF. Location: Unit 36)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose.<br>REFERENCE RB-DYSZZZ<br>SEVERITY Property Protection   | COMPLETED ON / BY<br>COMPLETED ON / BY |
| SEVERITY Property Protection<br>ELEMENT Fire Door IQM8RF (Floor: GF. Location: Unit 36)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose.<br>REFERENCE RB-DYSZZZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door 8GS9EM (Floor: GF. Location: Unit 42)<br>DUE BY / ASSIGNED TO  |  |
| SEVERITY Property Protection<br>ELEMENT Fire Door IQM8RF (Floor: GF. Location: Unit 36)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose.<br>REFERENCE RB-DYSZZZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door 8GS9EM (Floor: GF. Location: Unit 42)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door. |  |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 309 370 V Risk Base

| <b>Replace door with FD30s rated fire door.</b><br>The door is not fit for purpose.   |                   |
|---|-------------------|
| REFERENCE RB-HCZ3BD<br>SEVERITY Property Protection<br>ELEMENT Fire Door ZNZVWR (Floor: GF. Location: Unit 37)                  |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.  |                   |
| REFERENCE RB-SSBRCP<br>SEVERITY Property Protection<br>ELEMENT Fire Door A57JCK (Floor: GF. Location: Corridor / stair lobby)   |                   |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.  |                   |
| REFERENCE RB-5EYETA<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9NGMW8 (Floor: GF. Location: Corridor next to unit 19) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.  |                   |
| REFERENCE RB-WZSI7V<br>SEVERITY Property Protection<br>ELEMENT Fire Door NY5RCM (Floor: GF. Location: Unit 20)                  |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow.                                      |                   |
| REFERENCE RB-U15T6C<br>SEVERITY Property Protection<br>ELEMENT Fire Door IKQKHD (Floor: GF. Location: Unit 29)                  |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.  |                   |
| The door is not fit for purpose - panelled door, 2 x GG type.   |                   |
| REFERENCE RB-7IVEQX<br>SEVERITY Property Protection   |                   |
| ELEMENT Fire Door ZHJ6V9 (Floor: GF. Location: Unit 1)  |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 310 370 V Risk Base



| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow.  |                   |
|---|-------------------|
| REFERENCE RB-D1IT1W<br>SEVERITY Property Protection<br>ELEMENT Fire Door SJWVTA (Floor: GF. Location: Cleaners cupboard)  |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow.  |                   |
| REFERENCE RB-RYYX58<br>SEVERITY Property Protection<br>ELEMENT Fire Door RA4KPH (Floor: GF. Location: Unit 51)  |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow.  |                   |
| REFERENCE RB-V5FI18<br>SEVERITY Property Protection<br>ELEMENT Fire Door 1LTJVG (Floor: GF. Location: Unit 46)  |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.  |                   |
| The door is not fit for purpose.  |                   |
|   |                   |
| The door is not fit for purpose.<br>REFERENCE <b>RB-2J7NAC</b><br>SEVERITY <b>Property Protection</b>   | COMPLETED ON / BY |
| The door is not fit for purpose.<br>REFERENCE RB-2J7NAC<br>SEVERITY Property Protection<br>ELEMENT Fire Door WTG24P (Floor: GF. Location: Electrical panel)<br>DUE BY / ASSIGNED TO   |                   |
| The door is not fit for purpose.<br>REFERENCE RB-2J7NAC<br>SEVERITY Property Protection<br>ELEMENT Fire Door WTG24P (Floor: GF. Location: Electrical panel)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.  |                   |
| The door is not fit for purpose.<br>REFERENCE RB-2J7NAC<br>SEVERITY Property Protection<br>ELEMENT Fire Door WTG24P (Floor: GF. Location: Electrical panel)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose steel clad timber door core, no certi<br>REFERENCE RB-AYY4JL<br>SEVERITY Property Protection  |                   |
| The door is not fit for purpose.<br>REFERENCE RB-2J7NAC<br>SEVERITY Property Protection<br>ELEMENT Fire Door WTG24P (Floor: GF. Location: Electrical panel)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose steel clad timber door core, no certi<br>REFERENCE RB-AYY4JL<br>SEVERITY Property Protection<br>ELEMENT Fire Door PJGGE7 (Floor: Basement. Location: Escape lobby door)<br>DUE BY / ASSIGNED TO   | fication.         |
| The door is not fit for purpose.<br>REFERENCE RB-2J7NAC<br>SEVERITY Property Protection<br>ELEMENT Fire Door WTG24P (Floor: GF. Location: Electrical panel)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose steel clad timber door core, no certi<br>REFERENCE RB-AYY4JL<br>SEVERITY Property Protection<br>ELEMENT Fire Door PJGGE7 (Floor: Basement. Location: Escape lobby door)<br>DUE BY / ASSIGNED TO<br>22 April 2025  | fication.         |
| The door is not fit for purpose.<br>REFERENCE RB-2J7NAC<br>SEVERITY Property Protection<br>ELEMENT Fire Door WTG24P (Floor: GF. Location: Electrical panel)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose steel clad timber door core, no certi<br>REFERENCE RB-AYY4JL<br>SEVERITY Property Protection<br>ELEMENT Fire Door PJGGE7 (Floor: Basement. Location: Escape lobby door)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose.<br>REFERENCE RB-7EX3WF                                 | fication.         |
| The door is not fit for purpose.<br>REFERENCE RB-2J7NAC<br>SEVERITY Property Protection<br>ELEMENT Fire Door WTG24P (Floor: GF. Location: Electrical panel)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose steel clad timber door core, no certi<br>REFERENCE RB-AYY4JL<br>SEVERITY Property Protection<br>ELEMENT Fire Door PJGGE7 (Floor: Basement. Location: Escape lobby door)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose.  | fication.         |
| The door is not fit for purpose.<br>REFERENCE RB-2J7NAC<br>SEVERITY Property Protection<br>ELEMENT Fire Door WTG24P (Floor: GF. Location: Electrical panel)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose steel clad timber door core, no certi<br>REFERENCE RB-AYY4JL<br>SEVERITY Property Protection<br>ELEMENT Fire Door PJGGE7 (Floor: Basement. Location: Escape lobby door)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose.<br>REFERENCE RB-7EX3WF<br>SEVERITY Property Protection | fication.         |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 311 370 VRISKBASE



| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - timber door fitted in an aluminium              | n frame.   |
|---|--|
| REFERENCE RB-AF31X3<br>SEVERITY Property Protection<br>ELEMENT Fire Door XWDYWQ (Floor: GF. Location: Howard Building)        |  |
| due by / Assigned to 22 April 2025  | COMPLETED ON / BY  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - timber door in an aluminium fram                | e.   |
| REFERENCE RB-4Q4TLH<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9CJ52S (Floor: GF. Location: Howard Building)        |  |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose timber door in an aluminium.                      |  |
| REFERENCE RB-JX6XF6<br>SEVERITY Property Protection<br>ELEMENT Fire Door L4XTPK (Floor: GF. Location: Howard Building)        |  |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - timber door in an aluminium fram                | e.   |
| REFERENCE RB-GGSMBV<br>SEVERITY Property Protection<br>ELEMENT Fire Door J6RSA7 (Floor: GF. Location: Howard Building)        |  |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - timber door in an aluminium fram                | e.   |
| REFERENCE RB-TCXBI7<br>SEVERITY Property Protection<br>ELEMENT Fire Door 2PHDZC (Floor: GF. Location: Howard Building)        |  |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - stop section of frame has been cut<br>2m clear. | t away to allow mag lock installation, head room reduced below |
| REFERENCE RB-4BD3BC<br>SEVERITY Property Protection<br>ELEMENT Fire Door NEPL5S (Floor: GF. Location: Howard Building)        |  |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY  |



| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - located in a panelled partition - or  | riginal panelled door has been refaced.                       |
|---|---|
| REFERENCE RB-89HAND<br>SEVERITY Property Protection<br>ELEMENT Fire Door PFNULF (Floor: GF. Location: Howard Building)  |   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - fitted in a panelled partition. Orig  | inal door has been re- faced.                                 |
| REFERENCE RB-DFT3MT<br>SEVERITY Property Protection<br>ELEMENT Fire Door Y18LFE (Floor: GF. Location: Howard Building)  |   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose door located in panelled partition.   | Original panelled door has been refaced.                      |
| REFERENCE RB-HRFSMD<br>SEVERITY Property Protection<br>ELEMENT Fire Door MYTV28 (Floor: GF. Location: Howard Building)  |   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - door located in panelled partition  | . Original panelled door has been refaced.                    |
| REFERENCE RB-Z4TTE3<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9VKZCK (Floor: GF. Location: Howard Building)  |   |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose, frame cut away at lock area, only tw<br>arm. Door located in panelled partition. | wo inadequate hinges fitted. Door closer disconnected missing |
| REFERENCE RB-5FD6IR<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4WCGQ6 (Floor: GF. Location: Howard Building)  |   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose. Panelled door fitted in a panelled p   | partition, door has been resurfaced.                          |
| REFERENCE RB-QBD9L5<br>SEVERITY Property Protection<br>ELEMENT Fire Door KXKXR4 (Floor: GF. Location: Howard Building)  |   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 313 370 VRISK Base



| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.   |
|--|
| REFERENCE RB-BXRMFX<br>SEVERITY Property Protection<br>ELEMENT Fire Door QWSMXS (Floor: GF. Location: Howard Building)   |
| DUE BY / ASSIGNED TO     COMPLETED ON / BY       22 April 2025   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose 38mm hollow.   |
| REFERENCE RB-QNI3M4<br>SEVERITY Property Protection<br>ELEMENT Fire Door Z932V9 (Floor: GF. Location: Howard Building)   |
| DUE BY / ASSIGNED TO     COMPLETED ON / BY       22 April 2025   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose, floor spring has full shoe at bottom, this is not certified.                          |
| REFERENCE RB-B9KY6S<br>SEVERITY Property Protection<br>ELEMENT Fire Door 72SMJ6 (Floor: GF. Location: Howard Building)   |
| DUE BY / ASSIGNED TO COMPLETED ON / BY 22 April 2025   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.   |
| REFERENCE RB-CXK8IQ<br>SEVERITY Property Protection<br>ELEMENT Fire Door 8V34BM (Floor: GF. Location: Howard Building)   |
| DUE BY / ASSIGNED TO COMPLETED ON / BY 22 April 2025   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.   |
| REFERENCE RB-Z1VNCZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door JPS8JW (Floor: GF. Location: Howard Building) LOCATION Panelled door has been resurfaced. |
| DUE BY / ASSIGNED TO COMPLETED ON / BY 22 April 2025   |
| Replace door with FD30s rated fire door.   |
| The door is not fit for purpose. Panelled door has been refaced.<br>REFERENCE <b>RB-BRLAUN</b>   |
| SEVERITY Property Protection<br>ELEMENT Fire Door RCZR6Q (Floor: GF. Location: Howard Building)  |
| DUE BY / ASSIGNED TO         COMPLETED ON / BY           22 April 2025         Completed on / BY   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 314 370 VRISKBASE

| Replace door with FD30s rated fire door.<br>The door is not fit for purpose. Panelled door, no test evidence.   |                         |
|---|-------------------------|
| REFERENCE RB-1722ER<br>SEVERITY Property Protection<br>ELEMENT Fire Door UDMK9Q (Floor: GF. Location: Howard Building)  |                         |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY       |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.  |                         |
| REFERENCE RB-2D5ZNV<br>SEVERITY Property Protection<br>ELEMENT Fire Door HVHKZH (Floor: GF. Location: Howard Building)  |                         |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY       |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose. Panelled door has been refaced.  |                         |
| REFERENCE RB-8YXX8T<br>SEVERITY Property Protection<br>ELEMENT Fire Door KRNXIE (Floor: GF. Location: Howard Building)  |                         |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY       |
| Deale an de annuitte ED20e ante diffue de an  |                         |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.  |                         |
|   |                         |
| The door is not fit for purpose.<br>REFERENCE RB-WZEF7A<br>SEVERITY Property Protection   | COMPLETED ON / BY       |
| The door is not fit for purpose.<br>REFERENCE RB-WZEF7A<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)  |                         |
| The door is not fit for purpose.<br>REFERENCE RB-WZEF7A<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.   |                         |
| The door is not fit for purpose.<br>REFERENCE RB-WZEF7A<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 44mm door fixed into 38mm frame<br>REFERENCE RB-TNEQCZ<br>SEVERITY Property Protection   |                         |
| The door is not fit for purpose.<br>REFERENCE RB-WZEF7A<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 44mm door fixed into 38mm frame<br>REFERENCE RB-TNEQCZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door Y4ZDXA (Floor: First. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.  | e.<br>Completed on / By |
| The door is not fit for purpose.<br>REFERENCE RB-WZEF7A<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 44mm door fixed into 38mm frame<br>REFERENCE RB-TNEQCZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door Y4ZDXA (Floor: First. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 44mm door fitted in a 38mm frame<br>REFERENCE RB-AXEV7X | e.<br>Completed on / By |
| The door is not fit for purpose.<br>REFERENCE RB-WZEF7A<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 44mm door fixed into 38mm frame<br>REFERENCE RB-TNEQCZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door Y4ZDXA (Floor: First. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 44mm door fitted in a 38mm frame                        | e.<br>Completed on / By |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 315 370 V Risk Base

| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 44mm door fitted into 38mm door   | r frame.          |
|---|-------------------|
| REFERENCE RB-LSLS4Y<br>SEVERITY Property Protection<br>ELEMENT Fire Door NCC6RL (Floor: First floor. Location: Howard Building)   |                   |
| due BY / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - door appears to be machined with<br>control and repaired with an aluminium fillet plate at the lock Stril |                   |
| REFERENCE RB-PC8U9U<br>SEVERITY Property Protection<br>ELEMENT Fire Door WSTDT3 (Floor: First floor. Location: Howard Building)   |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.  |                   |
| REFERENCE RB-7V6RGM<br>SEVERITY Property Protection<br>ELEMENT Fire Door D7CUPT (Floor: First floor. Location: Howard Building)   |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.  |                   |
| REFERENCE RB-CD11Y9<br>SEVERITY Property Protection<br>ELEMENT Fire Door DVCJM6 (Floor: First floor. Location: Howard Building)   |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.  |                   |
| REFERENCE RB-WNXTBL<br>SEVERITY Property Protection<br>ELEMENT Fire Door XSJL8M (Floor: First floor. Location: Howard Building)   |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 40mm door and frame.  |                   |
| REFERENCE RB-D4VX3T<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9ZUWI7 (Floor: First floor. Location: Howard Building)   |                   |
| due BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 316 370 V Risk Base



| Replace door with FD30s rated fire door.<br>The door is not fit for purpose 40mm door and frame.                                 |   |
|--|---|
| REFERENCE RB-YUVB1W<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZACXD (Floor: Ground. Location: Howard Building)       |   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose 40mm door and frame.                                 |   |
| REFERENCE RB-IGY9B9<br>SEVERITY Property Protection<br>ELEMENT Fire Door EXID89 (Floor: Ground. Location: Howard Building)       |   |
| due By / Assigned to<br>22 April 2025  | COMPLETED ON / BY   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose 40mm door and frame.                                 |   |
| REFERENCE RB-F8LYKK<br>SEVERITY Property Protection<br>ELEMENT Fire Door 3E3PHK (Floor: Ground. Location: Howard Building)       |   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.   |   |
| REFERENCE RB-R5GQEF<br>SEVERITY Property Protection<br>ELEMENT Fire Door TKJLLH (Floor: Ground. Location: Howard Building)       |   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose fails to close due to catching on floo<br>the frame. | or surface and door has dropped so that it will not engage into |
| REFERENCE RB-E4MHW7<br>SEVERITY Property Protection<br>ELEMENT Fire Door G366XR (Floor: Ground. Location: Howard Building)       |   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 40mm door and frame.                               |   |
| REFERENCE RB-ED5SLB<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)       |   |
| due BY / Assigned to<br>22 April 2025  | COMPLETED ON / BY   |



| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.   |  |
|--|--|
| REFERENCE RB-T25BM1<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9EN3B8 (Floor: First floor. Location: Howard Building)              |  |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose door and frame have previously bee<br>an aluminium fillet plate. | n machined for access control, frame has been repaired with  |
| REFERENCE RB-YC3MPA<br>SEVERITY Property Protection<br>ELEMENT Fire Door BAI8Z6 (Floor: First floor. Location: Howard Building)              |  |
| due BY / Assigned to 22 April 2025   | COMPLETED ON / BY  |
| Replace door with FD30s rated fire door.   |  |
| The door is not fit for purpose.   |  |
| REFERENCE RB-9LECSM<br>SEVERITY Property Protection<br>ELEMENT Fire Door MYQB29 (Floor: Second floor. Location: Howard Building)             |  |
| DUE BY / ASSIGNED TO   | COMPLETED ON / BY  |
| 22 April 2025  |  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.   |  |
| REFERENCE RB-7CTTUW<br>SEVERITY Property Protection<br>ELEMENT Fire Door PZSHGC (Floor: Second floor. Location: Howard Building)             |  |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.   |  |
| REFERENCE RB-TKC6LT<br>SEVERITY Property Protection<br>ELEMENT Fire Door UR51QI (Floor: Second floor. Location: Howard Building)             |  |
| DUE BY / ASSIGNED TO   | COMPLETED ON / BY  |
| 22 April 2025  |  |
| Replace door with FD30s rated fire door.   |  |
| The door is not fit for purpose. The door and frame have previously an aluminium fillet plate.   | been machined for access control and the frame repaired with |
| REFERENCE RB-G7XG4I<br>SEVERITY Property Protection<br>ELEMENT Fire Door 468GQH (Floor: First floor. Location: Howard Building)              |  |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY  |
|  |  |



| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.                               |                   |
|--|-------------------|
| REFERENCE RB-3ILLWJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door DB1BKP (Floor: GF. Location: Kitchen)         |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.                               |                   |
| REFERENCE RB-R2V4BL<br>SEVERITY Property Protection<br>ELEMENT Fire Door 59QWP5 (Floor: GF. Location: Unit 55)         |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.                               |                   |
| REFERENCE RB-VF6SRV<br>SEVERITY Property Protection<br>ELEMENT Fire Door AR48PJ (Floor: GF. Location: Corridor)        |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.                               |                   |
| REFERENCE RB-JSMFKU<br>SEVERITY Property Protection<br>ELEMENT Fire Door HEUGL8 (Floor: GF. Location: Stair lobby #14) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.                               |                   |
| REFERENCE RB-ABY3CE<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4CRAI4 (Floor: GF. Location: Comms Room)      |                   |
|  |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |
| 22 April 2025<br>Replace fire door with FD30s fire rated door.   | COMPLETED ON / BY |
| 22 April 2025  | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 319 370 V Risk Base

| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.                                      |                   |
|---|-------------------|
| REFERENCE RB-AXNPSC<br>SEVERITY Property Protection<br>ELEMENT Fire Door DFYUN4 (Floor: GF. Location: Corridor to goods lift) |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.                                      |                   |
| REFERENCE RB-9JKHAB<br>SEVERITY Property Protection<br>ELEMENT Fire Door 53DQQM (Floor: GF. Location: Corridor lobby)         |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.                                      |                   |
| REFERENCE RB-RT2GK7<br>SEVERITY Property Protection<br>ELEMENT Fire Door 7BQ6P4 (Floor: GF. Location: Corridor lobby)         |                   |
| due BY / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.                                      |                   |
| REFERENCE RB-XBHAHG<br>SEVERITY Property Protection<br>ELEMENT Fire Door 26HCY2 (Floor: GF. Location: Unit 30)                |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.                                      |                   |
| REFERENCE RB-44AY9M<br>SEVERITY Property Protection<br>ELEMENT Fire Door 78MCHD (Floor: GF. Location: Basement stair lobby)   |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.                                      |                   |
| REFERENCE RB-4BTSRF   |                   |
| SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)                              |                   |
| DUE BY / ASSIGNED TO  |                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 320 370 V Risk Base

| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.   |                                  |  |
|--|----------------------------------|--|
| REFERENCE RB-DBG9TK<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18)                |                                  |  |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY                |  |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.   |                                  |  |
| REFERENCE RB-512EJ3<br>SEVERITY Property Protection<br>ELEMENT Fire Door PCXWMV (Floor: GF. Location: Corridor next to unit 15)                |                                  |  |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY                |  |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair. Morticed 3 times holes ex                             | posed or cover with face plates. |  |
| REFERENCE RB-WWRQ6G<br>SEVERITY Property Protection<br>ELEMENT Fire Door TYV5EP (Floor: GF. Location: Corridor next to unit 47)                |                                  |  |
| DUE BY / ASSIGNED TO   | COMPLETED ON / BY                |  |
| 22 April 2025  |                                  |  |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.   |                                  |  |
| REFERENCE RB-2LSWAK<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4Y6J1S (Floor: GF. Location: Corridor near to unit 48)                |                                  |  |
| DUE BY / ASSIGNED TO   | COMPLETED ON / BY                |  |
| 22 April 2025  |                                  |  |
| <b>Replace fire door with FD30s fire rated door.</b><br>The fire door is damaged beyond repair. Top of RH leaf missing at top centre location. |                                  |  |
| REFERENCE RB-YDEGNK  |                                  |  |
| SEVERITY Property Protection<br>ELEMENT Fire Door AP5BJW (Floor: GF. Location: Howard Building)  |                                  |  |
| DUE BY / ASSIGNED TO   | COMPLETED ON / BY                |  |
| 22 April 2025  |                                  |  |
| Replace fire door with FD30s fire rated door.  |                                  |  |
| The fire door is damaged beyond repair.  |                                  |  |
| REFERENCE RB-21KJED  |                                  |  |
| SEVERITY Property Protection<br>ELEMENT Fire Door NL5VST (Floor: GF. Location: Howard Building)  |                                  |  |
| DUE BY / ASSIGNED TO   | COMPLETED ON / BY                |  |
| 22 April 2025  |                                  |  |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 321 370 V Risk Base

| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.  |   |
|---|---|
| REFERENCE RB-TRDG22<br>SEVERITY Property Protection<br>ELEMENT Fire Door ESVT97 (Floor: GF. Location: Howard Building)                      |   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY   |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.  |   |
| REFERENCE RB-GYSAVD<br>SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)                      |   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY   |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.  |   |
| REFERENCE RB-FVL698<br>SEVERITY Property Protection<br>ELEMENT Fire Door EKGWZ6 (Floor: First. Location: Howard Building)                   |   |
| due BY / Assigned to<br>22 April 2025   | COMPLETED ON / BY   |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair. Frame and door machine<br>plate.                   | ed for access control, frame repaired with an aluminium fillet  |
| REFERENCE RB-MFYX1N<br>SEVERITY Property Protection<br>ELEMENT Fire Door FTZ3EB (Floor: First floor. Location: Howard Building)             |   |
| due BY / Assigned to<br>22 April 2025   | COMPLETED ON / BY   |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair. Leading edge of door leadoes not close freely.     | f is split and covered by masking tape, door has dropped and    |
| REFERENCE RB-XSBY95<br>SEVERITY Property Protection<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building)                  |   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY   |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair. Door and frame have bee<br>aluminium fillet plate. | en machined for access control. Frame has been repaired with an |
| REFERENCE RB-B49AK3<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q99RL7 (Floor: First floor. Location: Howard Building)             |   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 322 370 **Risk**Base

| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair. The door and frame have previously been machined for access control and the frame<br>fitted with an aluminium fillet plate. |                   |  |
|--|-------------------|--|
| REFERENCE RB-PVSGX7<br>SEVERITY Property Protection<br>ELEMENT Fire Door X6Y1YG (Floor: Second floor. Location: Howard Building)   |                   |  |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |  |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire ce  | rtified.          |  |
| REFERENCE RB-R2BFZS<br>SEVERITY Property Protection<br>ELEMENT Fire Door E6EE7R (Floor: GF. Location: Unit 56)   |                   |  |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |  |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire ce  | rtified.          |  |
| REFERENCE RB-DRCY3G<br>SEVERITY Property Protection<br>ELEMENT Fire Door 37DAH3 (Floor: GF. Location: Male WC)   |                   |  |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |  |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire ce  | rtified.          |  |
| REFERENCE RB-G1NKJ8<br>SEVERITY Property Protection<br>ELEMENT Fire Door L3UT9D (Floor: GF. Location: Female WC)   |                   |  |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |  |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire certified.  |                   |  |
| REFERENCE RB-85W98N<br>SEVERITY Property Protection<br>ELEMENT Fire Door QDQ9R3 (Floor: GF. Location: Unit 53)   |                   |  |
| due by / Assigned to 22 April 2025   | COMPLETED ON / BY |  |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire certified.  |                   |  |
| REFERENCE RB-U66UXR<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9KTZBJ (Floor: GF. Location: Kitchen)   |                   |  |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |  |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 323 370 VRISKBASE

| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer        | tified.           |
|---|-------------------|
| REFERENCE RB-KUWXD7<br>SEVERITY Property Protection<br>ELEMENT Fire Door JRZGWA (Floor: GF. Location: Corridor lobby)               |                   |
| due by / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer        | tified.           |
| REFERENCE RB-6FHA17<br>SEVERITY Property Protection<br>ELEMENT Fire Door SC1QF3 (Floor: GF. Location: Corridor lobby next to unit 2 | 27a)              |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer        | tified.           |
| REFERENCE RB-3IPRGN<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9NGMW8 (Floor: GF. Location: Corridor next to unit 19)     |                   |
| due By / Assigned to<br>22 April 2025   | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer        | tified.           |
| REFERENCE RB-FE9K6Y<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)             |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer        | tified.           |
| REFERENCE RB-EKL5CL<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZY9S1 (Floor: GF. Location: Corridor next to unit 18)     |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer        | tified.           |
| REFERENCE RB-DQM7NJ<br>SEVERITY Property Protection<br>ELEMENT Fire Door PCXWMV (Floor: GF. Location: Corridor next to unit 15)     |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 324 370 V Risk Base

| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire ce   | rtified.                      |
|---|-------------------------------|
| REFERENCE RB-TQ1L5F<br>SEVERITY Property Protection<br>ELEMENT Fire Door TYV5EP (Floor: GF. Location: Corridor next to unit 47)   |                               |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY             |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire ce   | rtified.                      |
| REFERENCE RB-4CRF5W<br>SEVERITY Property Protection<br>ELEMENT Fire Door 4Y6J1S (Floor: GF. Location: Corridor near to unit 48)   |                               |
| DUE BY / ASSIGNED TO 22 April 2025  | COMPLETED ON / BY             |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire ce   | rtified.                      |
| REFERENCE RB-STMDKA<br>SEVERITY Property Protection<br>ELEMENT Fire Door PJGGE7 (Floor: Basement. Location: Escape lobby door)  |                               |
| DUE BY / ASSIGNED TO<br>22 April 2025   | COMPLETED ON / BY             |
|   |                               |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire ce   | rtified.                      |
|   |                               |
| All fire doors are required to have 3 hinges, which must be fire ce<br>REFERENCE RB-I7X21V<br>SEVERITY Property Protection  |                               |
| All fire doors are required to have 3 hinges, which must be fire cere<br>REFERENCE RB-I7X21V<br>SEVERITY Property Protection<br>ELEMENT Fire Door L5NNXW (Floor: Basement. Location: Rear workshop # 2<br>DUE BY / ASSIGNED TO  | COMPLETED ON / BY             |
| All fire doors are required to have 3 hinges, which must be fire cere<br>REFERENCE RB-I7X21V<br>SEVERITY Property Protection<br>ELEMENT Fire Door L5NNXW (Floor: Basement. Location: Rear workshop # 2<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace hinges with BS EN standard fire door hinges.   | COMPLETED ON / BY             |
| All fire doors are required to have 3 hinges, which must be fire cere<br>REFERENCE RB-I7X21V<br>SEVERITY Property Protection<br>ELEMENT Fire Door L5NNXW (Floor: Basement. Location: Rear workshop # 2<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cere<br>REFERENCE RB-5RD73H<br>SEVERITY Property Protection   | COMPLETED ON / BY             |
| All fire doors are required to have 3 hinges, which must be fire ce<br>REFERENCE RB-I7X21V<br>SEVERITY Property Protection<br>ELEMENT Fire Door L5NNXW (Floor: Basement. Location: Rear workshop # 2<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire ce<br>REFERENCE RB-5RD73H<br>SEVERITY Property Protection<br>ELEMENT Fire Door SQWDQ7 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO  | COMPLETED ON / BY<br>rtified. |
| All fire doors are required to have 3 hinges, which must be fire ce<br>REFERENCE RB-I7X21V<br>SEVERITY Property Protection<br>ELEMENT Fire Door L5NNXW (Floor: Basement. Location: Rear workshop # 2<br>22 April 2025<br>Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire ce<br>REFERENCE RB-5RD73H<br>SEVERITY Property Protection<br>ELEMENT Fire Door SQWDQ7 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace hinges with BS EN standard fire door hinges. | COMPLETED ON / BY<br>rtified. |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 325 370 V Risk Base



| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire ce  | rtified.                                     |
|--|--|
| REFERENCE RB-QEKMI4<br>SEVERITY Property Protection<br>ELEMENT Fire Door NL5VST (Floor: GF. Location: Howard Building)   |  |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY                            |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire ce  | rtified.                                     |
| REFERENCE RB-JEFUDI<br>SEVERITY Property Protection<br>ELEMENT Fire Door 8V34BM (Floor: GF. Location: Howard Building)   |  |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY                            |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire ce  | rtified.                                     |
| REFERENCE RB-4QHFE8<br>SEVERITY Property Protection<br>ELEMENT Fire Door HVHKZH (Floor: GF. Location: Howard Building)   |  |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY                            |
|  |  |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire ce  | rtified.                                     |
|  | rtified.                                     |
| All fire doors are required to have 3 hinges, which must be fire ce<br>REFERENCE RB-ML4CC9<br>SEVERITY Property Protection   | rtified.<br>COMPLETED ON / BY                |
| All fire doors are required to have 3 hinges, which must be fire cere<br>REFERENCE RB-ML4CC9<br>SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)  | COMPLETED ON / BY                            |
| All fire doors are required to have 3 hinges, which must be fire cere<br>REFERENCE RB-ML4CC9<br>SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace hinges with BS EN standard fire door hinges.   | COMPLETED ON / BY                            |
| All fire doors are required to have 3 hinges, which must be fire cere<br>REFERENCE RB-ML4CC9<br>SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cere<br>REFERENCE RB-KB961K<br>SEVERITY Property Protection   | COMPLETED ON / BY                            |
| All fire doors are required to have 3 hinges, which must be fire cere<br>REFERENCE RB-ML4CC9<br>SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cere<br>REFERENCE RB-KB961K<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>22 April 2025<br>Replace hinges with BS EN standard fire door hinges.<br>Replace hinges with BS EN standard fire door hinges.                                     | COMPLETED ON / BY rtified. COMPLETED ON / BY |
| All fire doors are required to have 3 hinges, which must be fire cere<br>REFERENCE RB-ML4CC9<br>SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)<br>DUE BY/ASSIGNED TO<br>22 April 2025<br>Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cere<br>REFERENCE RB-KB961K<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)<br>DUE BY/ASSIGNED TO<br>22 April 2025<br>Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cere<br>REFERENCE RB-FG3H7A | COMPLETED ON / BY rtified. COMPLETED ON / BY |
| All fire doors are required to have 3 hinges, which must be fire cere<br>REFERENCE RB-ML4CC9<br>SEVERITY Property Protection<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)<br>DUE BY/ASSIGNED TO<br>22 April 2025<br>Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cere<br>REFERENCE RB-KB961K<br>SEVERITY Property Protection<br>ELEMENT Fire Door VMJ3MB (Floor: GF. Location: Howard Building)<br>DUE BY/ASSIGNED TO<br>22 April 2025<br>Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cere                        | COMPLETED ON / BY rtified. COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 326 370 V Risk Base



| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cert          | ified.            |
|--|-------------------|
| REFERENCE RB-9DLEWQ<br>SEVERITY Property Protection<br>ELEMENT Fire Door WSTDT3 (Floor: First floor. Location: Howard Building)        |                   |
| due BY / Assigned to 22 April 2025   | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cert          | ified.            |
| REFERENCE <b>RB-UMMIH6</b><br>SEVERITY Property Protection<br>ELEMENT Fire Door D7CUPT (Floor: First floor. Location: Howard Building) |                   |
| due BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cert          | ified.            |
| REFERENCE RB-131FRZ<br>SEVERITY Property Protection<br>ELEMENT Fire Door DVCJM6 (Floor: First floor. Location: Howard Building)        |                   |
| due BY / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cert          | ified.            |
| REFERENCE <b>RB-NVXDCX</b><br>SEVERITY Property Protection<br>ELEMENT Fire Door XSJL8M (Floor: First floor. Location: Howard Building) |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cert          | ified.            |
| REFERENCE RB-IKZF83<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9ZUWI7 (Floor: First floor. Location: Howard Building)        |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cert          | ified.            |
| REFERENCE RB-HBWD9X<br>SEVERITY Property Protection<br>ELEMENT Fire Door FTZ3EB (Floor: First floor. Location: Howard Building)        |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |



| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer | rtified.          |
|--|-------------------|
| REFERENCE RB-EK3JNH<br>SEVERITY Property Protection<br>ELEMENT Fire Door CZACXD (Floor: Ground. Location: Howard Building)   |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer | rtified.          |
| REFERENCE RB-YX744X<br>SEVERITY Property Protection<br>ELEMENT Fire Door EXID89 (Floor: Ground. Location: Howard Building)   |                   |
| due BY / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer | rtified.          |
| REFERENCE RB-6TSLNG<br>SEVERITY Property Protection<br>ELEMENT Fire Door 3E3PHK (Floor: Ground. Location: Howard Building)   |                   |
| due BY / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer | rtified.          |
| REFERENCE RB-ZTB65D<br>SEVERITY Property Protection<br>ELEMENT Fire Door TKJLLH (Floor: Ground. Location: Howard Building)   |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer | rtified.          |
| REFERENCE RB-375G6W<br>SEVERITY Property Protection<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)   |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer | rtified.          |
| REFERENCE RB-9NFQ1E<br>SEVERITY Property Protection<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building)   |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 328 370 V Risk Base



| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer     | tified.           |
|--|-------------------|
| REFERENCE RB-6B7W11<br>SEVERITY Property Protection<br>ELEMENT Fire Door 9EN3B8 (Floor: First floor. Location: Howard Building)  |                   |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer     | tified.           |
| REFERENCE RB-UJ384Y<br>SEVERITY Property Protection<br>ELEMENT Fire Door Q99RL7 (Floor: First floor. Location: Howard Building)  |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer     | tified.           |
| REFERENCE RB-PIV7DI<br>SEVERITY Property Protection<br>ELEMENT Fire Door BAI8Z6 (Floor: First floor. Location: Howard Building)  |                   |
| due BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer     | tified.           |
| REFERENCE RB-IY94BF<br>SEVERITY Property Protection<br>ELEMENT Fire Door 2H5NBL (Floor: First floor. Location: Howard Building)  |                   |
| due by / Assigned to<br>22 April 2025  | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer     | tified.           |
| REFERENCE RB-EKSVDT<br>SEVERITY Property Protection<br>ELEMENT Fire Door X6Y1YG (Floor: Second floor. Location: Howard Building) |                   |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer     | tified.           |
| REFERENCE RB-GMZTAH<br>SEVERITY Property Protection<br>ELEMENT Fire Door MYQB29 (Floor: Second floor. Location: Howard Building) | )                 |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY |



| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer     | tified.            |
|--|--------------------|
| REFERENCE RB-DXAQDU<br>SEVERITY Property Protection<br>ELEMENT Fire Door PZSHGC (Floor: Second floor. Location: Howard Building) | )                  |
| DUE BY / ASSIGNED TO 22 April 2025   | COMPLETED ON / BY  |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer     | tified.            |
| REFERENCE RB-ZW2FQW<br>SEVERITY Property Protection<br>ELEMENT Fire Door UR51QI (Floor: Second floor. Location: Howard Building) |                    |
| due BY / Assigned to<br>22 April 2025  | COMPLETED ON / BY  |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cer     | tified.            |
| REFERENCE RB-6NKNLL<br>SEVERITY Property Protection<br>ELEMENT Fire Door 468GQH (Floor: First floor. Location: Howard Building)  |                    |
| DUE BY / ASSIGNED TO<br>22 April 2025  | COMPLETED ON / BY  |
| Address morticing of frame jambs both sides.<br>Certification.   |                    |
| REFERENCE RB-6R9Z1W<br>ELEMENT Fire Door Q2XDJJ (Floor: GF. Location: Patra Corridor Lobby)                                      |                    |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY  |
| Adjust door alignment.<br>Door gaps exceed safe guidelines.  |                    |
| REFERENCE RB-JUHQG5<br>ELEMENT Fire Door ABA3NQ (Floor: GF. Location: Howard Building)   |                    |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY  |
| Adjust door alignment.<br>Doors do not close in-line if released from an open position. Door                                     | twisted at bottom. |
| REFERENCE RB-GNH77Y<br>ELEMENT Fire Door XSJL8M (Floor: First floor. Location: Howard Building)                                  |                    |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY  |



| Adjust the door closer. Currently slamming violently.<br>The door does not close-in-line if released from an open position |  |
|--|--|
| REFERENCE RB-JDLTUF<br>ELEMENT Fire Door TYV5EP (Floor: GF. Location: Corridor next to unit 47)                            |  |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY  |
| Confirm glazing meets BS EN fire regulations. Outer beading miss<br>Ensure the integrity of the fire door.                 | sing, glass held in place with steel pins / filler material. |
| REFERENCE RB-PHJFCM<br>ELEMENT Fire Door SSU5VQ (Floor: Ground. Location: Howard Building)                                 |  |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY  |
| Door appears to be sealed shut - confirm usage. No hinges visib Certification.   | le from outside.   |
| REFERENCE RB-2ZCSVI<br>ELEMENT Fire Door DY4BED (Floor: GF. Location: Electric cupboard)                                   |  |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY  |
| Door is domestic 38mm nfr leaf.<br>Certification.  |  |
| REFERENCE RB-SK8NYF<br>ELEMENT Fire Door QXEAJ1 (Floor: GF. Location: Unit 6)  |  |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY  |
| Door leaf split at top due to closer hitting masonry reveal.<br>Certification.   |  |
| REFERENCE RB-NCHNXZ<br>ELEMENT Fire Door SC1QF3 (Floor: GF. Location: Corridor lobby next to unit                          | 27a)   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY  |
| Door no longer in use.   |  |
| REFERENCE RB-21L2AD<br>ELEMENT Fire Door IS5WZ5 (Floor: GF. Location: Void door - Patra)                                   |  |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY  |
| Door selector not functional.  |  |
| Certification. REFERENCE RB-VH8F7I   |  |
| ELEMENT Fire Door 4FAFCU (Floor: GF. Location: Exit lobby doors)   | COMPLETED ON / BY  |
| No Due Date  |  |

| Door selector not functional.<br>Certification.   |                   |
|---|-------------------|
| REFERENCE RB-3LKMDM<br>ELEMENT Fire Door PCXWMV (Floor: GF. Location: Corridor next to unit 15)                           |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Door selector not functional.<br>Certification.   |                   |
| REFERENCE RB-T7NV4C<br>ELEMENT Fire Door D7CUPT (Floor: First floor. Location: Howard Building)                           |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Fit intumescent seals to the door frame.<br>Seals are damaged or missing in sections of the frame.                        |                   |
| REFERENCE RB-3P5C3M<br>ELEMENT Fire Door L4XTPK (Floor: GF. Location: Howard Building)                                    |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine do | or survey.        |
| REFERENCE RB-FZZSWN<br>ELEMENT Fire Door TT1BSB (Floor: GF. Location: Unit 25)  |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine do | or survey.        |
| REFERENCE RB-WCS653<br>ELEMENT Fire Door NSW7IE (Floor: GF. Location: Unit 27)  |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine do | or survey.        |
| REFERENCE RB-28ZNCT<br>ELEMENT Fire Door VUZ8YP (Floor: GF. Location: Unit 27a)   |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine do | or survey.        |
| REFERENCE RB-CIETZ1<br>ELEMENT Fire Door Q8B2LD (Floor: GF. Location: Store next to unit 38)                              |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |

| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine do | por survey.       |
|---|-------------------|
| REFERENCE RB-BE5P16<br>ELEMENT Fire Door YL926L (Floor: GF. Location: Unit 38)  |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine do | oor survey.       |
| REFERENCE RB-P127DC<br>ELEMENT Fire Door ZF8X6P (Floor: GF. Location: Unit 33)  |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine do | oor survey.       |
| REFERENCE RB-1AD7JM<br>ELEMENT Fire Door 4RX459 (Floor: GF. Location: Store / Void)                                       |                   |
| due by / Assigned to<br>No Due Date   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine do | por survey.       |
| REFERENCE RB-BJJWXY<br>ELEMENT Fire Door TB6HD7 (Floor: GF. Location: Unit 52)  |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine do | por survey.       |
| REFERENCE RB-SGCZQN<br>ELEMENT Fire Door JPZS5D (Floor: GF. Location: Unit 24)  |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine do | por survey.       |
| REFERENCE RB-AW527Z<br>ELEMENT Fire Door AZI9NN (Floor: GF. Location: Unit 23)  |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine do | por survey.       |
| REFERENCE RB-DHEHYL<br>ELEMENT Fire Door 2FS1UN (Floor: Basement. Location: Chemical store)                               |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 333 370 **Risk** Base



| Have the door fully inspected by a competent person.<br>The assessor had limited access to the door during the routine door      | pr survey.        |
|--|-------------------|
| REFERENCE RB-M58FYD<br>ELEMENT Fire Door XDG12G (Floor: First floor. Location: Howard Building)                                  |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Install a door closer compliant to BS EN 1154.<br>To ensure heat and smoke cannot pass through to escape route.                  |                   |
| REFERENCE RB-W3EU89<br>ELEMENT Fire Door HVHKZH (Floor: GF. Location: Howard Building)   |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Mag lock negates fire certification.<br>Door doesn't close against jamb, headroom of 2.0m not achieved.                          |                   |
| REFERENCE RB-83JRFP<br>ELEMENT Fire Door Q2XDJJ (Floor: GF. Location: Patra Corridor Lobby)                                      |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Make good missing lock case hole.<br>Certification.  |                   |
| REFERENCE RB-73GCCF<br>SEVERITY Property Protection<br>ELEMENT Fire Door L3UT9D (Floor: GF. Location: Female WC) LOCATION Door I | eaf.              |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Multiple lock mortices left exposed.<br>Certification.   |                   |
| REFERENCE RB-J81Q5K<br>ELEMENT Fire Door PJGGE7 (Floor: Basement. Location: Escape lobby door)                                   |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Reduce gaps between the door and the door frame.<br>To ensure heat and smoke cannot pass through to escape route.                |                   |
| REFERENCE RB-H4GIX7<br>SEVERITY Property Protection<br>ELEMENT Fire Door PCXWMV (Floor: GF. Location: Corridor next to unit 15)  |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Repair split in head section of frame where closer arm is fitted.<br>Certification.  |                   |
| REFERENCE RB-JUX3Y9<br>ELEMENT Fire Door QDQ9R3 (Floor: GF. Location: Unit 53)   |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 334 370 VRISK Base

| Replace door closer on RH door leaf.<br>Certification - closer leaking, no door control so door slams.             |                                |
|--|--------------------------------|
| REFERENCE RB-6TX3EX<br>ELEMENT Fire Door XSJL8M (Floor: First floor. Location: Howard Building)                    |                                |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY              |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.                                       |                                |
| REFERENCE RB-CBXXKM<br>ELEMENT Fire Door UXZU7D (Floor: GF. Location: Unit 31)                                     |                                |
| due BY / Assigned To<br>No Due Date  | COMPLETED ON / BY              |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - Steel door set, no certification and | oversized air transfer grille. |
| REFERENCE RB-NPA4ZY<br>ELEMENT Fire Door TB6HD7 (Floor: GF. Location: Unit 52)                                     |                                |
| due By / Assigned to<br>No Due Date  | COMPLETED ON / BY              |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - no rebate at top of door (steel doo  | r set).                        |
| REFERENCE RB-ZAZ2VP<br>ELEMENT Fire Door ETVB2I (Floor: GF. Location: Unit 34)                                     |                                |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY              |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.                                       |                                |
| REFERENCE RB-UCFMW2<br>ELEMENT Fire Door CW536F (Floor: GF. Location: Unit 35)                                     |                                |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY              |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose.                                       |                                |
| REFERENCE RB-C2Y4GF<br>ELEMENT Fire Door RFPMJH (Floor: GF. Location: Unit 41)                                     |                                |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY              |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow.                         |                                |
| REFERENCE RB-94GSA7<br>ELEMENT Fire Door JPZS5D (Floor: GF. Location: Unit 24)                                     |                                |
| due By / Assigned to<br>No Due Date  | COMPLETED ON / BY              |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 335 370 VRISK Base



| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow. |                   |
|--|-------------------|
| REFERENCE RB-WE11DN<br>ELEMENT Fire Door TT1BSB (Floor: GF. Location: Unit 25)             |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow. |                   |
| REFERENCE RB-IB159G<br>ELEMENT Fire Door AZI9NN (Floor: GF. Location: Unit 23)             |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow. |                   |
| REFERENCE RB-QNWGNB<br>ELEMENT Fire Door 19H8ZU (Floor: GF. Location: Unit 22)             |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow. |                   |
| REFERENCE RB-MMZ37Z<br>ELEMENT Fire Door TX18J6 (Floor: GF. Location: Unit 21)             |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow. |                   |
| REFERENCE RB-T1WCN7<br>ELEMENT Fire Door 5ARPDA (Floor: GF. Location: Unit 19)             |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose 38mm hollow.   |                   |
| REFERENCE RB-914Z8Y<br>ELEMENT Fire Door HHN85J (Floor: GF. Location: Unit 26)             |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow. |                   |
| REFERENCE RB-ANUYNW<br>ELEMENT Fire Door DLBK91 (Floor: GF. Location: Unit 18)             |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 336 370 VRISK Base



| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow. |                   |
|--|-------------------|
| REFERENCE RB-2XJTUE<br>ELEMENT Fire Door DEUWJF (Floor: GF. Location: Unit 17)             |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow. |                   |
| REFERENCE RB-6MCAJQ<br>ELEMENT Fire Door U5UZU4 (Floor: GF. Location: Unit 16)             |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow. |                   |
| REFERENCE RB-BY51QA<br>ELEMENT Fire Door ALV967 (Floor: GF. Location: Unit 15)             |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose 38mm hollow.   |                   |
| REFERENCE RB-M8JC7U<br>ELEMENT Fire Door KK2AQB (Floor: GF. Location: Unit 5)              |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow. |                   |
| REFERENCE RB-Z8JMN2<br>ELEMENT Fire Door 9KNZZH (Floor: GF. Location: Unit 4)              |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow. |                   |
| REFERENCE RB-3E1C36<br>ELEMENT Fire Door KIZXVC (Floor: GF. Location: Unit 3)              |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow. |                   |
| REFERENCE RB-R78YT2<br>ELEMENT Fire Door BG3AZG (Floor: GF. Location: Unit 2)              |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 337 370 VRISK Base



| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow.            |                   |
|---|-------------------|
| REFERENCE RB-YDMB7Q<br>ELEMENT Fire Door C5Z7QX (Floor: GF. Location: Unit 47)                        |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow.            |                   |
| REFERENCE RB-7X5ZIL<br>ELEMENT Fire Door FJ8R7A (Floor: GF. Location: Unit 45)                        |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm.                   |                   |
| REFERENCE RB-Y27AEB<br>ELEMENT Fire Door NNI1DK (Floor: GF. Location: Unit 50)                        |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow.            |                   |
| REFERENCE RB-PEMBED<br>ELEMENT Fire Door Z6QVYC (Floor: GF. Location: Unit 50)                        |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow.            |                   |
| REFERENCE RB-MTB4QU<br>ELEMENT Fire Door FLC2UR (Floor: GF. Location: Unit 44)                        |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm.                   |                   |
| REFERENCE RB-KL37QW<br>ELEMENT Fire Door 6M1EDY (Floor: GF. Location: Unit 48)                        |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - hollow core, see image. |                   |
| REFERENCE RB-234A8U<br>ELEMENT Fire Door MUGB2W (Floor: Basement. Location: Lift machinery)           |                   |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 338 370 V Risk Base



| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - panelled door not solid core.                              |                                    |
|--|------------------------------------|
| REFERENCE RB-B1QPJX<br>ELEMENT Fire Door FKF33E (Floor: Basement. Location: Rear workshop)   |                                    |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY                  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow.   |                                    |
| REFERENCE RB-U96ZMD<br>ELEMENT Fire Door KTSC4U (Floor: Basement. Location: Corridor near to unit  | BM5)                               |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY                  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - louvered/ panelled door, no certifi<br>REFERENCE RB-ISGDME | cation.                            |
| ELEMENT Fire Door 7VBAHW (Floor: Basement. Location: Unit BM5) DUE BY / ASSIGNED TO No Due Date  | COMPLETED ON / BY                  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose panelled/ louvered door, no certific                         | ation.                             |
| REFERENCE RB-EITCSJ<br>ELEMENT Fire Door GL2VRK (Floor: Basement. Location: Store next to female   | wc)                                |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY                  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - 38mm hollow.   |                                    |
| REFERENCE RB-U8KBKX<br>ELEMENT Fire Door NYCKVW (Floor: Basement. Location: Store next to male v   | vc)                                |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY                  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - traditional panelled door, leaf split                      | at top corner on the closing edge. |
| REFERENCE RB-XZU6NC<br>ELEMENT Fire Door 72EBBR (Floor: GF. Location: Howard Building)   |                                    |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY                  |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - timber door in an aluminium fram                           | e.                                 |
| REFERENCE RB-V9XW1W<br>SEVERITY Property Protection<br>ELEMENT Fire Door JNY8RK (Floor: GF. Location: Howard Building)                   |                                    |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY                  |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 339 370 V Risk Base

| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - timber door in an aluminium fram   | e.  |
|--|---|
| REFERENCE RB-GA7WKM<br>ELEMENT Fire Door H2YEU2 (Floor: GF. Location: Howard Building)   |   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY                                   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose; code lock fitted not suitable for fire<br>code lock fitted on an escape route.<br>Hinges fitted upside-down also.<br>REFERENCE RB-YXMCCW<br>ELEMENT Fire Door 5MWD9X (Floor: Gf. Location: Howard Building)<br>DUE BY / ASSIGNED TO |   |
| No Due Date  | COMPLETED ON / BY                                   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose - leading edges are radius edge sug<br>REFERENCE RB-VZMV3A<br>ELEMENT Fire Door SQWDQ7 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>No Due Date   | gesting this door set was originally double action. |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose, uncertified, badly damaged and fit<br>REFERENCE RB-M2RQXA<br>ELEMENT Fire Door Y66BKF (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>No Due Date   | ted in a panelled partition.                        |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose. Door badly damaged and does not<br>REFERENCE RB-I3KETE  | close in frame, located in panelled partition.      |
| ELEMENT Fire Door 9DKYW5 (Floor: GF. Location: Howard Building) DUE BY / ASSIGNED TO No Due Date   | COMPLETED ON / BY                                   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose panelled door has been resurfaced.<br>REFERENCE RB-245ZZQ<br>ELEMENT Fire Door GK57N1 (Floor: GF. Location: Howard Building)<br>DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY                                   |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose. Panelled door has been refaced.<br>REFERENCE RB-6VQXKD<br>ELEMENT Fire Door P3GWYN (Floor: GF. Location: Howard Building)   |   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY                                   |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 340 370 V Risk Base



| Replace door with FD30s rated fire door.<br>The door is not fit for purpose. Panelled door has been refaced.                    |  |
|---|--|
| REFERENCE RB-HUSV1K<br>ELEMENT Fire Door 3QAK7I (Floor: GF. Location: Howard Building)  |  |
| due BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY                              |
| Replace door with FD30s rated fire door.<br>The door is not fit for purpose. Original panelled door.                            |  |
| REFERENCE RB-VMA461<br>ELEMENT Fire Door WKRB86 (Floor: GF. Location: Howard Building)  |  |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY                              |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair.  |  |
| REFERENCE RB-2IHSVA<br>SEVERITY Property Protection<br>ELEMENT Fire Door 3JXMUG (Floor: GF. Location: Corridor next to unit 23) |  |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY                              |
| Replace fire door with FD30s fire rated door.<br>The fire door is damaged beyond repair. The whole opening is det               | eriorating . 44mm door fitted in a 38mm frame. |
| REFERENCE RB-VQIB19<br>ELEMENT Fire Door 2H5NBL (Floor: First floor. Location: Howard Building)                                 |  |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY                              |
| Replace hinges with BS EN standard fire door hinges.<br>All fire doors are required to have 3 hinges, which must be fire cert   | ified.   |
| REFERENCE RB-JMQQU3<br>SEVERITY Property Protection<br>ELEMENT Fire Door 3JXMUG (Floor: GF. Location: Corridor next to unit 23) |  |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY                              |
| Replace the door closer.<br>The door does not close-in-line if released from an open position.                                  |  |
| REFERENCE RB-34VCVT<br>ELEMENT Fire Door RVRETR (Floor: Ground. Location: Howard Building)                                      |  |
| DUE BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY                              |
| Replace the door closer.<br>The door does not close-in-line if released from an open position.                                  |  |
| REFERENCE RB-F69UJQ<br>ELEMENT Fire Door Q99RL7 (Floor: First floor. Location: Howard Building)                                 |  |
| due BY / ASSIGNED TO<br>No Due Date   | COMPLETED ON / BY                              |

RB-U8LT5M – 22/01/2025 – LENTON BUSINESS CENTRE, LENTON BOULEVARD, NOTTINGHAM NG7 2BZ 341 370 VRISK Base




| Steel partition door, no test evidence.<br>Certification.                      |                   |
|--|-------------------|
| REFERENCE RB-C67DVM<br>ELEMENT Fire Door 26HCY2 (Floor: GF. Location: Unit 30) |                   |
| DUE BY / ASSIGNED TO<br>No Due Date  | COMPLETED ON / BY |
|  |                   |
| Steel partition door, no test evidence.<br>Certification.                      |                   |
|  |                   |




# 4 PHOTOS















0

1


The second secon





















































































































**Risk**Base





**Risk**Base






























**Risk**Base













164








SUITE No. 16

































































































-


















231

